## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

AIRBUS
CUSTOMER SERVICES DIRECTORATE
1 Rond Point Maurice Bellonte
31707 BLAGNAC CEDEX
FRANCE

Tel: (33) 5 61 93 33 33 Telex: AIRBU 530526F Fax: (33) 5 61 93 42 51

ATA SYSTEM: 57

TITLE: WINGS - GENERAL - ONE TIME INSPECTION OF TAPERLOK BOLT AT

WING TO FUSELAGE JUNCTION.

MODIFICATION No.: None

This page transmits Revision No.03 of Service Bulletin No.A320-57-1140

### **ADDITIONAL WORK**

#### \*\*CONF ALL

Additional work is required by this revision for aircraft inspected by the original issue of this Service Bulletin.

No additional work is required by this revision for aircraft inspected by this Service Bulletin at revision No. 01 or revision No. 02.

The ADDITIONAL WORK consists in inspecting new fasteners located in the center and outer wing box in the Rib1 area.

Unless otherwise stated by an Airworthiness Directive, AIRBUS recommends the additional work to be accomplished within one year after the issue of this revision.

### **REASON**

Revision No. 03 issued to incorporate changes found necessary and carried out during the accomplishment of this Service Bulletin on aircraft with Manufacturer Serial Number (MSN) 2288.

NOTE: This revision satisfies the requirements of the subsequent Technical Adaptation(s) (TA) issued for the related Manufacturer Serial Number (MSN)s:

TA	MSN
80206461/012/2016	2288

### **CHANGES**

The main changes of this revision are:

- Manpower updated to be in accordance with the Gantt Chart
- 'APPENDIX 04 Inspection Report' included
- 'Procurement addresses' updated

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

- Kit 571140A01 and Kit 571140A02 updated
- Supplementary Kit 571140A01S03 and Supplementary Kit 571140A02S03 added
- 'Standard Practices' SUBTASKS updated
- Figure A-FAAAA added
- Figures A-FBAAA, A-FCAAA, A-FCBAA, A-FCEAA, A-FCEAB, A-FCFAA, A-FCGAA, A-FCGAB, A-FFAAA, A-FFAAB, A-FFBAA and A-FFBAB updated
- Figure A-FRAAA removed
- Minor changes applied.

CHMMADY		
SUMMARY		T_
MATERIAL PRICE INFORMATION	MATERIAL PRICE INFORMATION TABLE	R
	UPDATED	_
	MATERIAL PRICE INFORMATION TABLE	R
	UPDATED	_
EFFECTIVITY	OPERATOR LIST UPDATED	R
REFERENCES / REPERCUSSIONS	REFERENCES/REPERCUSSIONS TABLE	R
MANDOWED	UPDATED	
MANPOWER	MANPOWER UPDATED	R
	MANPOWER UPDATED	R
APPENDICES	APPENDICES UPDATED	R
PLANNING INFORMATION		
EFFECTIVITY	EFFECTIVITY RELATED INFORMATION UPDATED	R
Material Effectivity	MATERIAL EFFECTIVITY UPDATED	R
	MATERIAL SET UPDATED	' '
	MATERIAL SET QUANTITY UPDATED	
	MATERIAL EFFECTIVITY UPDATED	R
	MATERIAL SET UPDATED	
	MATERIAL SET QUANTITY UPDATED	
MANPOWER	MANPOWER UPDATED	R
	MANPOWER UPDATED	R
REFERENCES	REFERENCED DOCUMENTATION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	R
MATERIAL INFORMATION		
MATERIAL - PRICE AND AVAILABILITY		
Procurement Addresses	PROCUREMENT ADDRESSES UPDATED	R
	MATERIAL SET UPDATED	
Price and Availability	PRICE AND AVAILABILITY UPDATED	R
	MATERIAL AVAILABILITY UPDATED	
	MATERIAL SET UPDATED	
	MATERIAL PRICE UPDATED	
INDUSTRY SUPPORT INFORMATION	INDUSTRY SUPPORT INFORMATION UPDATED	R
LIST OF COMPONENTS	LIST OF COMPONENTS UPDATED	R

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

100 ET ( 10 A C ) TO (	DADT MATERIAL COT CONT.	1-
Kit 571140A01R04	PART MATERIAL SET UPDATED	R
	MATERIAL SET LABEL UPDATED	
	KEYWORD UPDATED	
	PART NUMBER UPDATED	
K'I 5744 40 400 D0 4	QUANTITY UPDATED	<del> </del>
Kit 571140A02R04	PART MATERIAL SET UPDATED	R
	MATERIAL SET LABEL UPDATED	
	KEYWORD UPDATED	
	PART NUMBER UPDATED QUANTITY UPDATED	
Supplementary Kit 571140A01S03	PART MATERIAL SET ADDED	N
Supplementary Kit 571140A02S03	PART MATERIAL SET ADDED	N
LIST OF MATERIALS - OPERATOR SUPPLIED		
Components	COMPONENTS UPDATED	R
Component COMPA01	PART MATERIAL SET UPDATED	R
	NOTE UPDATED	
Component COMPA03	PART MATERIAL SET UPDATED	R
·	NOTE UPDATED	
Component COMPA04	PART MATERIAL SET UPDATED	R
•	NOTE UPDATED	
TOOLING		
Tools	TOOLS UPDATED	R
ACCOMPLISHMENT INSTRUCTIONS		
TASK 571140- 832-801-001-INSPECTION	TASK SOLUTION UPDATED	R
	NOTE UPDATED	
Subtask 571140-910-001-001	SUBTASK SOLUTION UPDATED	R
Subtask 571140-910-001-001	SUBTASK SOLUTION UPDATED	R
Subtask 571140-941-001-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	REFERENCES UPDATED	
Subtask 571140-941-001-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	REFERENCES UPDATED	
Subtask 571140-832-001-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	CONFIGURATION UPDATED	
	FIGURE REFERENCE UPDATED	
	NOTE UPDATED	
	REFERENCES UPDATED	
		R
Subtask 571140-832-002-001	SUBTASK SOLUTION UPDATED	וח
Subtask 571140-832-002-001	REFERENCED DOCUMENTATION UPDATED	
Subtask 571140-832-002-001	REFERENCED DOCUMENTATION UPDATED CONFIGURATION UPDATED	n
Subtask 571140-832-002-001	REFERENCED DOCUMENTATION UPDATED CONFIGURATION UPDATED FIGURE REFERENCE UPDATED	n
Subtask 571140-832-002-001	REFERENCED DOCUMENTATION UPDATED CONFIGURATION UPDATED	n

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

0.1		1_
Subtask 571140-832-001-002	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	CONFIGURATION UPDATED	
	FIGURE REFERENCE UPDATED	
	NOTE UPDATED	
	REFERENCES UPDATED	
Subtask 571140-832-002-002	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	CONFIGURATION UPDATED	
	FIGURE REFERENCE UPDATED	
	NOTE UPDATED	
	REFERENCES UPDATED	
TASK 571140- 833-801-001-REPAIR	TASK SOLUTION UPDATED	R
	NOTE UPDATED	' '
Subtask 571140-910-002-001	SUBTASK SOLUTION UPDATED	R
Subtask 571140-910-002-001	SUBTASK SOLUTION UPDATED	R
		_
Subtask 571140-833-001-001	SUBTASK SOLUTION UPDATED	R
	KEYWORD UPDATED	
	PART NUMBER UPDATED	
	QUANTITY UPDATED	
	ITEM NUMBER UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-002-001	SUBTASK SOLUTION UPDATED	R
	KEYWORD UPDATED	
	PART NUMBER UPDATED	
	QUANTITY UPDATED	
	ITEM NUMBER UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-003-001	SUBTASK SOLUTION UPDATED	R
	NOTE UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-004-001	SUBTASK SOLUTION UPDATED	R
	NOTE UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-001-002	SUBTASK SOLUTION UPDATED	R
	KEYWORD UPDATED	
	PART NUMBER UPDATED	
	QUANTITY UPDATED	
	ITEM NUMBER UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-002-002	SUBTASK SOLUTION UPDATED	R
	KEYWORD UPDATED	1.,
	PART NUMBER UPDATED	
	QUANTITY UPDATED	
	ITEM NUMBER UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	MATERIAL LIST UPDATED	
	INIVITEI (IVE FIG. OI DALED	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

Cultinal F71110 000 000 000	CLIPTACK COLLITION LIPPATED	In
Subtask 571140-833-003-002	SUBTASK SOLUTION UPDATED	R
	NOTE UPDATED	
0.11.1.574440.000.004.000	MATERIAL LIST UPDATED	
Subtask 571140-833-004-002	SUBTASK SOLUTION UPDATED	R
	NOTE UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-410-005-001	SUBTASK SOLUTION UPDATED	R
	MATERIAL LIST UPDATED	
Subtask 571140-410-006-001	SUBTASK SOLUTION UPDATED	R
	MATERIAL LIST UPDATED	
Subtask 571140-942-001-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	REFERENCES UPDATED	
Subtask 571140-410-005-002	SUBTASK SOLUTION UPDATED	R
	MATERIAL LIST UPDATED	
Subtask 571140-410-006-002	SUBTASK SOLUTION UPDATED	R
	MATERIAL LIST UPDATED	1.,
Subtask 571140-942-001-001	SUBTASK SOLUTION UPDATED	R
Odblask 37 1 140 342 001 001	REFERENCED DOCUMENTATION UPDATED	''
	REFERENCES UPDATED	
TASK 571140- 832-802-001-INSPECTION		R
ADDITIONAL WORK	NOTE UPDATED	n
Task associated data - 001	MAN HOURS UPDATED	R
	ELAPSED TIME UPDATED	
Task associated data - 002	MAN HOURS UPDATED	R
	ELAPSED TIME UPDATED	
Subtask 571140-910-003-001	SUBTASK SOLUTION UPDATED	R
Subtask 571140-910-003-001	SUBTASK SOLUTION UPDATED	R
Subtask 571140-941-002-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	REFERENCES UPDATED	
Subtask 571140-941-002-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	REFERENCES UPDATED	
Subtask 571140-832-003-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	CONFIGURATION UPDATED	
	FIGURE REFERENCE UPDATED	
	NOTE UPDATED	
	MANPOWER RESSOURCE UPDATED	
	REFERENCES UPDATED	
Subtask 571140-832-004-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	1.,
	CONFIGURATION UPDATED	
	FIGURE REFERENCE UPDATED	
	NOTE UPDATED	
	MANPOWER RESSOURCE UPDATED	
	REFERENCES UPDATED	
	THE ENERGES OF DATED	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

Subtask 571140-832-003-002	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	CONFIGURATION UPDATED	
	FIGURE REFERENCE UPDATED	
	NOTE UPDATED	
	MANPOWER RESSOURCE UPDATED	
	REFERENCES UPDATED	
Subtask 571140-832-004-002	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	CONFIGURATION UPDATED	
	FIGURE REFERENCE UPDATED	
	NOTE UPDATED	
	MANPOWER RESSOURCE UPDATED	
	REFERENCES UPDATED	
TASK 571140- 833-802-001-REPAIR	TASK SOLUTION UPDATED	R
ADDITIONAL WORK	NOTE UPDATED	
Task associated data - 001	MAN HOURS UPDATED	R
	ELAPSED TIME UPDATED	
Task associated data - 002	MAN HOURS UPDATED	R
	ELAPSED TIME UPDATED	
Subtask 571140-910-004-001	SUBTASK SOLUTION UPDATED	R
Subtask 571140-910-004-001	SUBTASK SOLUTION UPDATED	R
Subtask 571140-833-005-001	SUBTASK SOLUTION UPDATED	R
Oublask 37 1140 000 000 001	KEYWORD UPDATED	''
	PART NUMBER UPDATED	
	QUANTITY UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	MANPOWER RESSOURCE UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-006-001	SUBTASK SOLUTION UPDATED	R
Sublask 37 1140-003-000-001	KEYWORD UPDATED	11
	PART NUMBER UPDATED	
	QUANTITY UPDATED	
	CONFIGURATION UPDATED	
	NOTE UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	FIGURE REFERENCE UPDATED	
	MANPOWER RESSOURCE UPDATED	
0	MATERIAL LIST UPDATED	<del></del>
Subtask 571140-833-007-001	SUBTASK SOLUTION UPDATED	R
	NOTE UPDATED	
	MANPOWER RESSOURCE UPDATED	<del> </del> -
Subtask 571140-833-008-001	SUBTASK SOLUTION UPDATED	R
	NOTE UPDATED	
1	MANPOWER RESSOURCE UPDATED	1

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

Subtask 571140-833-005-002	SUBTASK SOLUTION UPDATED	R
	KEYWORD UPDATED	
	PART NUMBER UPDATED	
	QUANTITY UPDATED NOTE UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-006-002	SUBTASK SOLUTION UPDATED	R
Gastask 671110 666 666 662	KEYWORD UPDATED	1.,
	PART NUMBER UPDATED	
	QUANTITY UPDATED	
	NOTE UPDATED	
	PART NUMBER DESCRIPTION UPDATED	
	MATERIAL LIST UPDATED	
Subtask 571140-833-007-002	SUBTASK SOLUTION UPDATED	R
	NOTE UPDATED	
Subtask 571140-833-008-002	MANPOWER RESSOURCE UPDATED SUBTASK SOLUTION UPDATED	R
Sublask 571140-833-008-002	NOTE UPDATED	I <sup>K</sup>
	MANPOWER RESSOURCE UPDATED	
Subtask 571140-942-002-001	SUBTASK SOLUTION UPDATED	R
Gastask 67 11 10 6 12 662 661	REFERENCED DOCUMENTATION UPDATED	1.,
	REFERENCES UPDATED	
Subtask 571140-942-002-001	SUBTASK SOLUTION UPDATED	R
	REFERENCED DOCUMENTATION UPDATED	
	REFERENCES UPDATED	
Fig. A-FBAAA		
Fig. A-FBAAA Sheet 02	SHEET UPDATED	R
Fig. A-FBAAA Sheet 03	SHEET UPDATED	R
Fig. A-FFAAA		
Fig. A-FFAAA Sheet 01	SHEET UPDATED	R
Fig. A-FFAAB		
Fig. A-FFAAB Sheet 01	SHEET UPDATED	R
Fig. A-FCAAA		
Fig. A-FCAAA Sheet 01	SHEET UPDATED	R
Fig. A-FCAAA Sheet 02	SHEET UPDATED	R
Fig. A-FCAAA Sheet 03	SHEET UPDATED	R
Fig. A-FCAAA Sheet 04	SHEET UPDATED	R
Fig. A-FCAAA Sheet 05	SHEET UPDATED	R
Fig. A-FCAAA Sheet 06	SHEET UPDATED	R
Fig. A-FCAAA Sheet 07	SHEET UPDATED	R
Fig. A-FCBAA		
Fig. A-FCBAA Sheet 02	SHEET UPDATED	R
Fig. A-FCBAA Sheet 03	SHEET UPDATED	R
Fig. A-FCBAA Sheet 04	SHEET UPDATED	R
Fig. A-FCBAA Sheet 05	SHEET UPDATED	R

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

Fig. A-FCBAA Sheet 06	SHEET UPDATED	R
Fig. A-FCBAA Sheet 07	SHEET UPDATED	R
Fig. A-FCCAA		
Fig. A-FCCAA Sheet 01	SHEET UPDATED	R
Fig. A-FCCAA Sheet 02	SHEET UPDATED	R
Fig. A-FCCAA Sheet 03	SHEET UPDATED	R
Fig. A-FCDAA		
Fig. A-FCDAA Sheet 01	SHEET UPDATED	R
Fig. A-FDDAA		
Fig. A-FDDAA Sheet 02	SHEET UPDATED	R
Fig. A-FCEAA		
Fig. A-FCEAA Sheet 02	SHEET UPDATED	R
Fig. A-FCEAA Sheet 03	SHEET UPDATED	R
Fig. A-FCEAB		
Fig. A-FCEAB Sheet 02	SHEET UPDATED	R
Fig. A-FCEAB Sheet 03	SHEET UPDATED	R
Fig. A-FFBAA		
Fig. A-FFBAA Sheet 01	SHEET UPDATED	R
Fig. A-FFBAB		
Fig. A-FFBAB Sheet 01	SHEET UPDATED	R
Fig. A-FCFAA		
Fig. A-FCFAA Sheet 01	SHEET UPDATED	R
Fig. A-FCFAA Sheet 02	SHEET UPDATED	R
Fig. A-FCFAA Sheet 03	SHEET UPDATED	R
Fig. A-FCFAA Sheet 04	SHEET UPDATED	R
Fig. A-FCFAA Sheet 05	SHEET UPDATED	R
Fig. A-FCFAA Sheet 06	SHEET UPDATED	R
Fig. A-FCFAA Sheet 07	SHEET UPDATED	R
Fig. A-FCFAB		
Fig. A-FCFAB Sheet 01	SHEET UPDATED	R
Fig. A-FCFAB Sheet 02	SHEET UPDATED	R
Fig. A-FCFAB Sheet 03	SHEET UPDATED	R
Fig. A-FCFAB Sheet 04	SHEET UPDATED	R
Fig. A-FCFAB Sheet 05	SHEET UPDATED	R
Fig. A-FCFAB Sheet 06	SHEET UPDATED	R
Fig. A-FCFAB Sheet 07	SHEET UPDATED	R
Fig. A-FCGAA		
Fig. A-FCGAA Sheet 01	SHEET UPDATED	R
Fig. A-FCGAA Sheet 02	SHEET UPDATED	R
Fig. A-FCGAA Sheet 03	SHEET UPDATED	R
Fig. A-FCGAA Sheet 04	SHEET UPDATED	R

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN REVISION TRANSMITTAL SHEET

Fig. A-FCGAA Sheet 05	SHEET UPDATED	R
Fig. A-FCGAA Sheet 06	SHEET UPDATED	R
Fig. A-FCGAA Sheet 07	SHEET UPDATED	R
Fig. A-FCGAB		
Fig. A-FCGAB Sheet 01	SHEET UPDATED	R
Fig. A-FCGAB Sheet 02	SHEET UPDATED	R
Fig. A-FCGAB Sheet 03	SHEET UPDATED	R
Fig. A-FCGAB Sheet 04	SHEET UPDATED	R
Fig. A-FCGAB Sheet 05	SHEET UPDATED	R
Fig. A-FCGAB Sheet 06	SHEET UPDATED	R
Fig. A-FCGAB Sheet 07	SHEET UPDATED	R
Fig. A-FRA	FIGURE DELETED FOR APPLICABLE MSN	D
APPENDIX 04 - Inspection Report		
APPENDIX CONTENT	APPENDIX CONTENT ADDED	N
Fig. A-FAAAA	FIGURE SOLUTION ADDED	N
Fig. A-FAAAA Sheet 01	SHEET ADDED	N

#### FILING INSTRUCTIONS

This Service Bulletin has been generated electronically and is reissued as a complete document. Replace the complete document.

Put this Revision Transmittal Sheet in front of the Service Bulletin.

### **HISTORY OF PREVIOUS REVISIONS**

This Service Bulletin has been validated on A320 aircraft MSN 1387.

Revision No. 01 issued to update the detailed inspection area of the center and outer wing box in the Rib1 and modify the Accomplishment Timescale.

Revision No. 02 issued to correct typo mistakes for kits references.

### **REVISION SEQUENCE**

ORIGINAL: Nov 21/06

**REVISION No.: 01 - Nov 25/13** 

REVISION No.: 02 - Nov 07/14

REVISION No.: 03 - Apr 19/19

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

# SERVICE BULLETIN REVISION TRANSMITTAL SHEET

This Page Intentionally Left Blank

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN SUMMARY

AIRBUS
CUSTOMER SERVICES DIRECTORATE
1 Rond Point Maurice Bellonte
31707 BLAGNAC CEDEX
FRANCE

Tel: (33) 5 61 93 33 33 Telex: AIRBU 530526F Fax: (33) 5 61 93 42 51

This summary is for information only and is not approved for modification of the aircraft.

ATA SYSTEM: 57

TITLE: WINGS - GENERAL - ONE TIME INSPECTION OF TAPERLOK BOLT AT WING TO FUSELAGE JUNCTION.

\*\*CONF ALL

### **MODIFICATIONS**

None

#### REASON/DESCRIPTION/OPERATIONAL CONSEQUENCES

During installation of the wing to the center wing box in the AIRBUS A320 family Final Assembly Line (FAL), some taperloks used in the wing to fuselage junction at RIB 1, were found to be non-compliant with the specification.

These fasteners have been used on limited number of aircraft.

Fatigue tests on samples and calculations have demonstrated that a loss in pre-tension results in reduction of the fatigue life of the assembly.

AIRBUS decided to check also the condition of the taperloks compliant to the specification used on older aircraft.

At critical locations, the new calculated fatigue life falls below the aircraft Design Service Goal (DSG) of 48,000 Flight Cycles (FC).

Consequently, two Inspection Service Bulletins were launched to perform an internal (Service Bulletin No. A320-57-1129) and an external (Service Bulletin No. A320-57-1130) ultrasonic Inspection on the stiffeners and the lower panels at rib 1, on the center wing box side and the outer wing box side.

This Inspection Service Bulletin consists in carrying out a detailed inspection of fasteners located in center and outer wing box in rib 1 area.

In accordance with the result of the inspection:

- replace the nut by self-locking nut with appropriate washer.
- replace the damaged taperlok with a new taperlok at next nominal diameter with self-locking nut.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN SUMMARY

Accomplishment of this Service Bulletin cancels the inspection requirements of inspection Service Bulletin No. A320-57-1129 & No. A320-57-1130 and restore the fatigue potential in the zone to the level initially certified.

### **GENERAL EVALUATION**

EVALUATION TABLE				
COMPLIANCE RECOMMENDED (1)		CANCELS INSPECTION SB	YES	
POTENTIAL AD	NO	A/C OPERATION AFFECTED	NO	
RELIABILITY AFFECTED	NO	PAX COMFORT AFFECTED	NO	
COST SAVING	NO	ETOPS AFFECTED	NO	
STRUCTURAL LIFE EXTN	NO	VENDOR SB INVOLVED	NO	
DE-FUELLING/VENTILATING	YES	VALIDATION ON AIRCRAFT	YES	
BOOKLET AVAILABLE	YES			

NOTE (1): Service Bulletin recommended to be accomplished to prevent significant operational

disruptions.

NOTE: This Service Bulletin has been validated at original issue on A320 aircraft with

Manufacturer Serial Number (MSN) 1387.

NOTE: Two booklets including photographs taken during the validation of this Service Bulletin

are available on AirbusWorld - Maintenance and Engineering - AirN@v engineering (in

the concerned SB file).

### **MATERIAL PRICE INFORMATION**

#### \*\*CONF 001

MATERIAL PRICE INFORMATION TABLE			
MATERIAL SET	QTY PER A/C	PRICE PER A/C (USD)	MAIN PARTS
Kit 571140A01R04	2	7,700.00	Bolt, nut, washer
Supplementary kit 571140A01S02	2	4,640.00	Bolt, nut, washer
Supplementary kit 571140A01S03	2	3,860.00	Washer
Kit tool 571140T01R01	1	1,000.00	Gage
Kit tool 571140T02R00	1	1,364.00	Test
TOTAL		18,564.00	
Component COMPA01	1	See SB	Screw, nut , washer
Component COMPA03	1	See SB	Screw, nut, washer

#### \*\*CONF 002

MATERIAL PRICE INFORMATION TABLE			
MATERIAL SET QTY PER PRICE PER A/C (USD)			MAIN PARTS
Kit 571140A02R04	2	7,700.00	Bolt, nut, washer

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN SUMMARY

MATERIAL PRICE INFORMATION TABLE						
MATERIAL SET	QTY PER A/C	PRICE PER A/C (USD)	MAIN PARTS			
Supplementary kit 571140A02S02	2	4,260.00	Bolt, nut, washer			
Supplementary kit 571140A02S03	2	3,860.00	Washer			
Kit tool 571140T01R01	1	1,000.00	Gage			
Kit tool 571140T02R00	1	1,364.00	Test			
TOTAL		18,184.00				
Component COMPA01	1	See SB	Screw, nut , washer			
Component COMPA04	1	See SB	Screw, nut , washer			

## **EFFECTIVITY**

## \*\*CONF ALL

This Service Bulletin is applicable to this (these) operator(s):

I	74T	AAF	AAR	AAV	ABL	AHY	AIJ	ALK	AMC	ANZ	ART	ARU	ASL
Ī	AUH	AWC	AXM	BAW	BEL	BKP	CES	CSN	CTV	D2F	DQA	<b>EDW</b>	EIN
Ī	ETD	<b>EWG</b>	FHY	GCR	HDA	HKE	IBE	IGO	JBU	JSA	JST	KCH	KNE
Ī	LDM	LGW	LLM	LZB	NWK	ORF	OTF	PIA	PIC	QTR	RWZ	RZO	SDR
Ī	SLK	SVR	TAI	TAM	TAP	THY	UAL	UEA	USA	VIV	VLG	VRD	

## **CONCURRENT REQUIREMENTS**

None

## REFERENCES / REPERCUSSIONS

TFU	57.11.00.006
OEB	None
AOT	None
SIL	None
ISI	None
LINE MAINTENANCE AFFECTED	No
LIFE LIMIT	None
OTHERS	OIT SE999.0078/04CL

## **NATURE OF THE WORK**

AIRCRAFT	YES
EQUIPMENT	NO
HARD	NO
SOFT	NO
OBRM	NO

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN SUMMARY

### **MANPOWER**

## \*\*CONF 001

Task 571140-832-801-001: INSPECTION				
TOTAL MANHOURS 69.00				
ELAPSED TIME (HOURS)	18.00			

Task 571140-833-801-001: REPAIR			
TOTAL MANHOURS 75.50			
ELAPSED TIME (HOURS)	25.00		

Task 571140-832-802-001: INSPECTION ADDITIONAL WORK				
TOTAL MANHOURS	59.00			
ELAPSED TIME (HOURS)	15.50			

Task 571140-833-802-001: REPAIR ADDITIONAL WORK			
TOTAL MANHOURS 65.50			
ELAPSED TIME (HOURS)	20.50		

## \*\*CONF 002

Task 571140-832-801-001: INSPECTION				
TOTAL MANHOURS	69.00			
ELAPSED TIME (HOURS)	18.00			

Task 571140-833-801-001: REPAIR			
TOTAL MANHOURS 75.50			
ELAPSED TIME (HOURS)	25.00		

Task 571140-832-802-001: INSPECTION ADDITIONAL WORK			
TOTAL MANHOURS 37.00			
ELAPSED TIME (HOURS)	10.00		

Task 571140-833-802-001: REPAIR ADDITIONAL WORK				
TOTAL MANHOURS	41.50			
ELAPSED TIME (HOURS)	14.50			

## **APPENDICES**

## \*\*CONF ALL

APPENDIX 01 - Weight Variant (WV) correspondence table

APPENDIX 02 - Elapsed Time Assumption

APPENDIX 03 - Elapsed Time Assumption (ADDITIONAL WORK)

APPENDIX 04 - Inspection Report

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN SUMMARY

## \*\*CONF ALL




Figure A-FSAAA - Sheet 01

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN SUMMARY

This Page Intentionally Left Blank

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

AIRBUS
CUSTOMER SERVICES DIRECTORATE
1 Rond Point Maurice Bellonte
31707 BLAGNAC CEDEX
FRANCE

Tel: (33) 5 61 93 33 33 Telex: AIRBU 530526F Fax: (33) 5 61 93 42 51

ATA SYSTEM: 57

TITLE: WINGS - GENERAL - ONE TIME INSPECTION OF TAPERLOK BOLT AT WING TO FUSELAGE JUNCTION.

MODIFICATION No.: None

This document contains AIRBUS PROPRIETARY INFORMATION and shall at all times remain the property of AIRBUS; no intellectual property right or licence is granted by AIRBUS in connection with any information contained in it. It is delivered on the express condition that said document and the information contained in it shall be treated as confidential, shall not be used for any purpose other than that for which it is hereby delivered. It shall not be disclosed in whole or in part to third parties and shall not be duplicated in any manner (except for the purposes of performing the tasks described hereunder and provided that any recipient of such document shall comply with the conditions herein), without AIRBUS prior written consent.

## 1. PLANNING INFORMATION

### \*\*CONF ALL

#### A. <u>EFFECTIVITY</u>

(1) Models

320-214 320-216 320-232 320-233

(2) Effectivity by MSN

2164-2169 2171 2173 2175 2177-2178 2180 2182-2183 2185 2187 2189 2191 2193 2195 2197 2199 2201 2204 2206-2207 2210 2212 2215 2217 2219 2221 2223 2225 2227 2229 2231 2233 2235 2238-2239 2242 2244 2246 2248 2250 2252 2254 2256-2257 2259 2272 2274-2275 2278 2280 2282 2284 2286 2288 2291-2292 2294 2297 2299 2301 2307 2310 2312 2314 2316 2322 2325 2327 2329 2331 2334 2336 2338 2340 2343 2345 2347 2349 2352 2354 2356 2359 2361 2364 2366 2368 2372 2374 2376 2384 2386 2388 2390-2391 2393 2395 2397 2399 2401 2403 2405 2407 2409 2411 2413 2415 2417 2419 2422-2423 2425 2428 2430 2432 2434 2437 2439 2441 2443 2445 2447 2449 2451 2453 2455 2457 2459 2461 2475 2478-2479 2482 2484 2486 2489 2491 2493 2496 2498 2502 2504 2506 2509 2511 2513 2515 2517 2520 2522 2524 2526 2529 2531 2533 2535 2537 2539-2540 2542 2562 2564 2566 2569 2571 2573 2576-2577 2580 2583-2584 2587 2589 2591 2594 2596 2598 2600 2602 2604 2606 2608-2609 2612-2613 2616 2619-2620 2623 2626-2627 2630 2633 2635 2637 2640 2642 2645 2647 2649 2651 2654 2656 2658 2661 2663 2665 2668 2670-2671 2674 2676 2678 2680 2683 2685 2688

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### (3) Effectivity by Operator

The Operator/MSN relationship is provided for information only and is correct at the time of issue in accordance with the information available to AIRBUS. Any future changes resulting from transfer of an aircraft from one operator to another will not be reflected in this list unless the Service Bulletin is revised for another reason.

OPERATOR	MSN
74T	2165
AAF	2180
AAR	2397 2459
AAV	2331 2340
ABL	2422 2430
AHY	2685
AIJ	2227 2539
ALK	2345
AMC	2189 2291 2665
ANZ	2173 2257 2297 2445 2533 2594 2663
ART	2233
ARU	2676
ASL	2587 2645
AUH	2403
AWC	2564
AXM	2183 2425 2612 2633 2656 2683
BAW	2441
BEL	2207
BKP	2254 2310 2366 2417 2509 2531 2600
CES	2219 2221 2235 2239 2244 2437 2451 2478 2493 2498
CSN	2354 2361 2484 2506 2511 2637
CTV	2598
D2F	2496
DQA	2347
EDW	2606 2627
EIN	2191 2206 2217 2250 2256 2272 2294 2364 2374 2399 2409 2411
	2432 2486 2542 2583 2635
ETD	2167
EWG	2591
FHY	2524
GCR	2338 2475
HDA	2229 2238 2428
HKE	2299 2322
IBE	2225 2242 2248 2391
IGO	2195 2204 2275 2334 2359 2388 2405 2443 2457 2482 2584 2609
	2626 2649 2670
JBU	2177 2201 2215 2231 2246 2259 2280 2284 2286 2307 2314 2336
	2352 2368 2384 2386 2415 2447 2449 2461 2489 2491 2504 2520
	2535 2577 2580 2640 2647 2671
JSA	2316 2356 2453 2604

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN

MSN
2169 2185 2197 2292 2329 2423 2526 2537 2573 2608 2642 2651
2529
2171 2182 2199 2569
2502
2562
2413 2419 2439 2571 2688
2540 2596
2455 2515
2566
2479
2212 2274
2517
2288
2193 2372 2393
2325 2390
2619 2668
2252
2166 2175 2187 2278 2327 2343 2349 2376 2623
2282 2301 2434
2513
2178
2164 2395 2401 2522 2602
2680
2654
2312 2613 2630
2210 2576 2661
2168 2223 2407 2589 2620 2658 2678
2616 2674

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

### (4) Configuration by MSN

MSN	CONFIGURATION
2164 2165 2166 2167 2168 2169 2171 2173 2175 2177 2178	001 002
2180 2182 2183 2185 2187 2189 2191 2193 2195 2197 2199	
2201 2204 2206 2207 2210 2212 2215 2217 2219 2221 2223	
2225 2227 2229 2231 2233 2235 2238 2239 2242 2244 2246	
2248 2250 2252 2254 2256 2257 2259 2272 2274 2275 2278	
2280 2282 2284 2286 2288 2291 2292 2294 2297 2299 2301	
2307 2310 2312 2314 2316 2322 2325 2327 2329 2331 2334	
2336 2338 2340 2343 2345 2347 2349 2352 2354 2356 2359	
2361 2364 2366 2368 2372 2374 2376 2384 2386 2388 2390	
2391 2393 2395 2397 2399 2401 2403 2405 2407 2409 2411	
2413 2415 2417 2419 2422 2423 2425 2428 2430 2432 2434	
2437 2439 2441 2443 2445 2447 2449 2451 2453 2455 2457	
2459 2461 2475 2478 2479 2482 2484 2486 2489 2491 2493	
2496 2498 2502 2504 2506 2509 2511 2513 2515 2517 2520	
2522 2524 2526 2529 2531 2533 2535 2537 2539 2540 2542	
2562 2564 2566 2569 2571 2573 2576 2577 2580 2583 2584	
2587 2589 2591 2594 2596 2598 2600 2602 2604 2606 2608	
2609 2612 2613 2616 2619 2620 2623 2626 2627 2630 2633	
2635 2637 2640 2642 2645 2647 2649 2651 2654 2656 2658	
2661 2663 2665 2668 2670 2671 2674 2676 2678 2680 2683	
2685 2688	

### (5) Configuration definition

#### \*\*CONF 001

Config. 001 concerns A320-200 aircraft model with a Weight Variant (WV) 000 thru 010 and 013 (Refer to APPENDIX 01 - Weight Variant (WV) correspondence table ) and is valid for aircraft on which Modification No. 26503P4809 (REPLACE TAPER-LOCK FASTENERS BY PULL TYPE FASTENERS ON SECTION 21) is embodied.

#### \*\*CONF 002

Config. 002 concerns A320-200 aircraft model with a Weight Variant (WV) 011, 012, 014, 015 and 016 (Refer to APPENDIX 01 - Weight Variant (WV) correspondence table ) and is valid for aircraft on which Modification No. 26503P4809 (REPLACE TAPER-LOCK FASTENERS BY PULL TYPE FASTENERS ON SECTION 21) is embodied.

## (6) Material Effectivity

#### \*\*CONF 001

MATERIAL	QTY PER A/C	SEE NOTES
Kit 571140A01R04	2	
Supplementary kit 571140A01S02	2	
Supplementary kit 571140A01S03	2	
Kit tool 571140T01R01	1	
Kit tool 571140T02R00	1	
Component COMPA01	1	
Component COMPA03	1	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

MATERIAL	QTY PER A/C	SEE NOTES
Consumable CMLA01	1	

#### \*\*CONF 002

MATERIAL QTY PER A/C SEE NOTES Kit 571140A02R04 2 Supplementary kit 571140A02S02 2 2 Supplementary kit 571140A02S03 Kit tool 571140T01R01 1 Kit tool 571140T02R00 1 Component COMPA01 1 Component COMPA04 1 Consumable CMLA01 1

#### \*\*CONF ALL

## B. CONCURRENT REQUIREMENTS

None

#### C. REASON

### (1) History

During installation of the wing to the center wing box in the AIRBUS A320 family Final Assembly Line (FAL), some taperloks used in the wing to fuselage junction at RIB 1, were found to be non-compliant with the specification.

These fasteners have been used on limited number of aircraft.

Fatigue tests on samples and calculations have demonstrated that a loss in pre-tension results in reduction of the fatigue life of the assembly.

AIRBUS decided to check also the condition of the taperloks compliant to the specification used on older aircraft.

At critical locations, the new calculated fatigue life falls below the aircraft Design Service Goal (DSG) of 48,000 Flight Cycles (FC).

Consequently, two Inspection Service Bulletins were launched to perform an internal (Service Bulletin No. A320-57-1129) and an external (Service Bulletin No. A320-57-1130) ultrasonic Inspection on the stiffeners and the lower panels at rib 1, on the center wing box side and the outer wing box side.

#### (2) Objective/Action

This Inspection Service Bulletin consists in carrying out a detailed inspection of fasteners located in center and outer wing box in rib 1 area.

In accordance with the result of the inspection:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- replace the nut by self-locking nut with appropriate washer.
- replace the damaged taperlok with a new taperlok at next nominal diameter with self-locking nut.

#### (3) Advantages

Accomplishment of this Service Bulletin cancels the inspection requirements of inspection Service Bulletin No. A320-57-1129 & No. A320-57-1130 and restore the fatigue potential in the zone to the level initially certified.

(4) Operational/Maintenance Consequences

None

### D. DESCRIPTION

To accomplish this Service Bulletin it is necessary to:

#### \*\*CONF 001

Task 571140-832-801-001: INSPECTION

- (1) LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction
- (2) RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction

Task 571140-833-801-001: REPAIR

- (1) Replace the Nuts on the LH Side
- (2) Replace the Nuts on the RH Side
- (3) Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side
- (4) Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side

Task 571140-832-802-001: INSPECTION ADDITIONAL WORK

- (1) LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK
- (2) RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK

Task 571140-833-802-001: REPAIR ADDITIONAL WORK

- (1) Replace the Nuts on the LH Side, ADDITIONAL WORK
- (2) Replace the Nuts on the RH Side, ADDITIONAL WORK
- (3) Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side,

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### ADDITIONAL WORK

(4) Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side, ADDITIONAL WORK

#### \*\*CONF 002

Task 571140-832-801-001: INSPECTION

- (1) LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction
- (2) RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction

Task 571140-833-801-001: REPAIR

- (1) Replace the Nuts on the LH Side
- (2) Replace the Nuts on the RH Side
- (3) Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side
- (4) Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side

Task 571140-832-802-001: INSPECTION ADDITIONAL WORK

- (1) LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK
- (2) RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK

Task 571140-833-802-001: REPAIR ADDITIONAL WORK

- (1) Replace the Nuts on the LH Side, ADDITIONAL WORK
- (2) Replace the Nuts on the RH Side, ADDITIONAL WORK
- (3) Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side, ADDITIONAL WORK
- (4) Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side, ADDITIONAL WORK

#### \*\*CONF ALL

#### E. COMPLIANCE

(1) Classification

RECOMMENDED: Service Bulletin recommended to be accomplished to prevent significant operational disruptions.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### (2) Accomplishment Timescale

Accomplishment of this Service Bulletin is recommended at the earliest opportunity where manpower and facilities are available.

#### F. APPROVAL

The technical content of this document is approved under authority of Design Organization Approval No. EASA.21J.031.

If an aircraft listed in the effectivity has a modification or repair embodied that is not of AIRBUS origin, and which affects the content of this Service Bulletin, the operator is responsible for obtaining approval by its airworthiness authority for any adaptation necessary before incorporation of the Service Bulletin.

### G. MANPOWER

The manpower estimates given in this Service Bulletin are based on the direct labor cost to do the work. These estimates assume that the work will be done by experienced personnel, and may need to be revised upwards to suit operator's circumstances. The estimates do not include the time to prepare, plan or inspect the work. Manufacture and procurement of parts and tools, drying times for paints, sealants, etc., and general administration work are also not included.

#### \*\*CONF 001

Task 571140-832-801-001: INSPECTION		
Get Access	17.00	
On Aircraft		
LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction	26.00	
RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction	26.00	
TOTAL MANHOURS	69.00	
ELAPSED TIME (HOURS)	18.00	

NOTE:

For an explanation of the man-hours and elapsed time, refer to the Gantt Chart, <u>Fig. A-FABAA</u> given in APPENDIX 02 - Elapsed Time Assumption .

Task 571140-833-801-001: REPAIR		
On Aircraft		
Replace the Nuts on the LH Side	12.00	
Replace the Nuts on the RH Side	12.00	
Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side	16.00	
Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side	16.00	
Tests	5.00	
Close-Up	14.50	
TOTAL MANHOURS	75.50	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Task 571140-833-801-001: REPAIR	
ELAPSED TIME (HOURS)	25.00

NOTE: For an explanation of the man-hours and elapsed time, refer to the Gantt

Chart, Fig. A-FACAA given in APPENDIX 02 - Elapsed Time Assumption .

NOTE: The minimum man-hours necessary to accomplish this Service Bulletin are

those for the Inspection. Depending on the inspection result, additional man-

hours can apply.

Task 571140-832-802-001: INSPECTION ADDITIONAL WORK		
Get Access	17.00	
On Aircraft		
LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK	21.00	
RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK	21.00	
TOTAL MANHOURS	59.00	
ELAPSED TIME (HOURS)	15.50	

NOTE: For an explanation of the man-hours and elapsed time, refer to the Gantt

Chart, Fig. A-FADAA given in APPENDIX 03 - Elapsed Time Assumption

(ADDITIONAL WORK) .

Task 571140-833-802-001: REPAIR ADDITIONAL WORK	
On Aircraft	
Replace the Nuts on the LH Side, ADDITIONAL WORK	10.00
Replace the Nuts on the RH Side, ADDITIONAL WORK	10.00
Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side, ADDITIONAL WORK	13.00
Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side, ADDITIONAL WORK	13.00
Tests	5.00
Close-Up	14.50
TOTAL MANHOURS	65.50
ELAPSED TIME (HOURS)	20.50

NOTE: For an explanation of the man-hours and elapsed time, refer to the Gantt

Chart, Fig. A-FAEAA given in APPENDIX 03 - Elapsed Time Assumption

(ADDITIONAL WORK) .

NOTE: The minimum man-hours necessary to accomplish this Service Bulletin are

those for the Inspection. Depending on the inspection result, additional man-

hours can apply.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

### \*\*CONF 002

Task 571140-832-801-001: INSPECTION		
Get Access	17.00	
On Aircraft		
LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction	26.00	
RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction	26.00	
TOTAL MANHOURS	69.00	
ELAPSED TIME (HOURS)	18.00	

NOTE:

For an explanation of the man-hours and elapsed time, refer to the Gantt Chart,  $\underline{\text{Fig. A-FABAA}}$  given in APPENDIX 02 - Elapsed Time Assumption .

Task 571140-833-801-001: REPAIR		
On Aircraft		
Replace the Nuts on the LH Side	12.00	
Replace the Nuts on the RH Side	12.00	
Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side	16.00	
Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side	16.00	
Tests	5.00	
Close-Up	14.50	
TOTAL MANHOURS	75.50	
ELAPSED TIME (HOURS)	25.00	

NOTE: For an explanation of the man-hours and elapsed time, refer to the Gantt

Chart, Fig. A-FACAA given in APPENDIX 02 - Elapsed Time Assumption .

NOTE: The minimum man-hours necessary to accomplish this Service Bulletin are

those for the Inspection. Depending on the inspection result, additional man-

hours can apply.

Task 571140-832-802-001: INSPECTION ADDITIONAL WORK		
Get Access 17.00		
On Aircraft		
LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK	10.00	
RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK	10.00	
TOTAL MANHOURS	37.00	
ELAPSED TIME (HOURS)	10.00	

NOTE:

For an explanation of the man-hours and elapsed time, refer to the Gantt Chart, Fig. A-FADAB given in APPENDIX 03 - Elapsed Time Assumption

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### (ADDITIONAL WORK).

Task 571140-833-802-001: REPAIR ADDITIONAL WORK		
On Aircraft		
Replace the Nuts on the LH Side, ADDITIONAL WORK	5.00	
Replace the Nuts on the RH Side, ADDITIONAL WORK	5.00	
Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side, ADDITIONAL WORK	6.00	
Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side, ADDITIONAL WORK	6.00	
Tests	5.00	
Close-Up	14.50	
TOTAL MANHOURS	41.50	
ELAPSED TIME (HOURS)	14.50	

NOTE: For an explanation of the man-hours and elapsed time, refer to the Gantt

Chart, Fig. A-FAEAB given in APPENDIX 03 - Elapsed Time Assumption

(ADDITIONAL WORK) .

NOTE: The minimum man-hours necessary to accomplish this Service Bulletin are

those for the Inspection. Depending on the inspection result, additional man-

hours can apply.

## \*\*CONF ALL

## H. WEIGHT AND BALANCE

Not Changed

## I. <u>ELECTRICAL LOAD DATA</u>

Not Changed

## J. REFERENCES

#### \*\*CONF 001

Aircraft Maintenance Manual (AMM)	12-34-24	20-21-11	20-28-00
, ,	28-00-00	28-10-00	28-11-00
	28-21-00	28-21-42	28-21-54
	28-25-00	32-12-00	53-35-11
	57-17-11	57-27-11	57-27-12
Consumable Material List (CML)			
Drawing	R5710200	1	
Elec. Std. Practices Manual (ESPM)	20-55-00		
In Service Information (ISI)	00.00.0017	79	
Non Destructive Test Manual (NTM)	51-10-01	_	_
Standards Manual (SM)			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN

Structural Repair Manual (SRM)	51-24-00	51-42-11	51-43-00
	51-75-12		

### \*\*CONF 002

Aircraft Maintenance Manual (AMM)	12-34-24 28-00-00 28-21-00 28-25-00	20-21-11 28-10-00 28-21-42 32-12-00	20-28-00 28-11-00 28-21-54 53-35-11
	57-17-11	57-27-11	57-27-12
Consumable Material List (CML)			
Drawing	R5710200	1	
Elec. Std. Practices Manual (ESPM)	20-55-00	_	
In Service Information (ISI)	00.00.00179		
Non Destructive Test Manual (NTM)	51-10-01		
Standards Manual (SM)			
Structural Repair Manual (SRM)	51-24-00	51-42-11	51-43-00
	51-75-12		

## \*\*CONF ALL

## K. PUBLICATION AFFECTED

None

## L. <u>INTERCHANGEABILITY/MIXABILITY</u>

Not Applicable

## M. SPARES

None

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### 2. MATERIAL INFORMATION

### \*\*CONF ALL

### A. MATERIAL - PRICE AND AVAILABILITY

### (1) Procurement Addresses

Customers with aircraft shown in the effectivity of this Service Bulletin should send a purchase order to AIRBUS. Quote the number of this Service Bulletin. The address is:

Kit 571140A01R04	AIRBUS Material, Logistics and Suppliers
Kit 571140A02R04	ATP II B,
Supplementary kit 571140A01S02	Hein-Sass-Weg 24
Supplementary kit 571140A02S02	21129 HAMBURG
Supplementary kit 571140A01S03	GERMANY
Supplementary kit 571140A02S03	For ordering by internet:
	http://spares.airbus.com
	For ordering by E-mail:
	airbus.kit@airbus.com
	Telephone Hotline: +49 40 743 51660

For standard hardware the purchase order shall be addressed to AIRBUS. Quote the number of this Service Bulletin, the MSN and, if applicable the Retrofit Information Letter (RIL) reference. Please send your request to:

Component COMPA01	AIRBUS Material, Logistics and Suppliers
Component COMPA03	Standard Parts
	For ordering by internet:
	http://spares.airbus.com or via SPEC2000
	For ordering by E-mail:
	ifd.spares@airbus.com
	Phone: +49 (0) 40 50 76 40 03

### (2) Price and Availability

Kit 571140A01R04	
Cost	3,850.00 USD
Availability	180 days calendar days from receipt of order

The availability given above is the standard lead time from the date of your purchase order. If items are required before this time, please include a retrofit planning schedule with your order so that we can try to comply with your requirements.

The sales terms (costs and availability) are estimated in relation to economic conditions. The latest valid price and lead time for ordering purposes shall be obtained through the AIRBUS Spares portal or through a request for quotation to airbus.kit@airbus.com.

Kit 571140A02R04	
Cost	3,850.00 USD
Availability	180 days calendar days from receipt of order

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

The availability given above is the standard lead time from the date of your purchase order. If items are required before this time, please include a retrofit planning schedule with your order so that we can try to comply with your requirements.

The sales terms (costs and availability) are estimated in relation to economic conditions. The latest valid price and lead time for ordering purposes shall be obtained through the AIRBUS Spares portal or through a request for quotation to airbus.kit@airbus.com.

Supplementary kit 571140A01S02		
Cost 2,320.00 USD		
Availability	180 days calendar days from receipt of order	

The availability given above is the standard lead time from the date of your purchase order. If items are required before this time, please include a retrofit planning schedule with your order so that we can try to comply with your requirements.

The sales terms (costs and availability) are estimated in relation to economic conditions. The latest valid price and lead time for ordering purposes shall be obtained through the AIRBUS Spares portal or through a request for quotation to airbus.kit@airbus.com.

Supplementary kit 571140A02S02		
Cost 2,130.00 USD		
Availability	180 days calendar days from receipt of order	

The availability given above is the standard lead time from the date of your purchase order. If items are required before this time, please include a retrofit planning schedule with your order so that we can try to comply with your requirements.

The sales terms (costs and availability) are estimated in relation to economic conditions. The latest valid price and lead time for ordering purposes shall be obtained through the AIRBUS Spares portal or through a request for quotation to airbus.kit@airbus.com.

Supplementary kit 571140A01S03		
Cost 1,930.00 USD		
Availability	99 days calendar days from receipt of order	

The availability given above is the standard lead time from the date of your purchase order. If items are required before this time, please include a retrofit planning schedule with your order so that we can try to comply with your requirements.

The sales terms (costs and availability) are estimated in relation to economic conditions. The latest valid price and lead time for ordering purposes shall be obtained through the AIRBUS Spares portal or through a request for quotation to airbus.kit@airbus.com.

Supplementary kit 5711	Supplementary kit 571140A02S03						
Cost	1,930.00 USD						
Availability	99 days calendar days from receipt of order						

The availability given above is the standard lead time from the date of your purchase order. If items are required before this time, please include a retrofit planning schedule with your order so that we can try to comply with your requirements.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

The sales terms (costs and availability) are estimated in relation to economic conditions. The latest valid price and lead time for ordering purposes shall be obtained through the AIRBUS Spares portal or through a request for quotation to airbus.kit@airbus.com.

### Component COMPA01

Operator supplied standard hardware parts required to accomplish this Service Bulletin are to be supplied from the operator's stock.

### Component COMPA03

Operator supplied standard hardware parts required to accomplish this Service Bulletin are to be supplied from the operator's stock.

#### Component COMPA04

Operator supplied standard hardware parts required to accomplish this Service Bulletin are to be supplied from the operator's stock.

#### **B. INDUSTRY SUPPORT INFORMATION**

AIRBUS will share the costs of accomplishment of this Service Bulletin by providing the kits at no charge for orders placed before Aug 30/19.

For the accomplishment of this Service Bulletin before Aug 30/19, AIRBUS will share the costs by crediting the operator supplied standard hardware parts. Claims for this allowance should be received no later than 90 days after completion of the last affected aircraft of your fleet.

AIRBUS will credit the man hours indicated in this Service Bulletin at the agreed in-house warranty labor rate for claims received no later than 90 days after completion of the last affected aircraft of your fleet, for the accomplishment of this Service Bulletin before Aug 30/19.

### C. <u>LIST OF COMPONENTS</u>

This table shows the supplemental kits (S kits) needed to update the kits already held in your stock to the latest status.

Kit hel	ld by operator	Supplementary Kit required	Latest status of Kit
57114		AND	571140A01R04
		571140A01S03	
57114	0A01R04	None	571140A01R04

This table shows the supplemental kits (S kits) needed to update the kits already held in your stock to the latest status.

Kit held by operator	Supplementary Kit required	Latest status of Kit
	571140A02S02 AND 571140A02S03	571140A02R04
571140A02R03	571140A02S03	571140A02R04

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

	Kit held by operator	Supplementary Kit required	Latest status of Kit
I	571140A02R04	None	571140A02R04

### Kit 571140A01R04

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
10	ASNA2532-7	34	NUT				
11	ASNA2531-7	6	NUT				
13	ASNA2532-8	16	NUT				
15	ASNA2531-6	2	NUT				
60	EN6115T2-3	14	BOLT				
61	ASNA2536-2	17	NUT				
62	EN6115T2-2	3	BOLT				
65	NAS1149D0332K	8	WASHER				
69	NAS1149F0332P	2	WASHER				
	NSA5372-616AX	2	WASHER				
	NSA5372-616BX	2	WASHER				
	NSA5372-616CX	2	WASHER				
	NSA5372-616DX	2	WASHER				
	NSA5372-616EX	2	WASHER				
	NSA5372-716AX	40	WASHER				
	NSA5372-716BX	40	WASHER				
	NSA5372-716CX	40	WASHER				
	NSA5372-716DX	40	WASHER				
	NSA5372-716EX	40	WASHER				
	NSA5372-816AX	16	WASHER				
	NSA5372-816BX	16	WASHER				
	NSA5372-816CX	16	WASHER				
	NSA5372-816DX	16	WASHER				
	NSA5372-816EX	16	WASHER				

NOTE:

If you find part numbers of hardware components in the related kit(s) which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the correct part number to part number relationship.

#### Kit 571140A02R04

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
10	ASNA2532-7	34	NUT				
11	ASNA2531-7	6	NUT				
13	ASNA2532-8	16	NUT				
15	ASNA2531-6	2	NUT				
60	EN6115T2-3	14	BOLT				
61	ASNA2536-2	17	NUT				
62	EN6115T2-2	3	BOLT				
65	NAS1149D0332K	8	WASHER				

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
69	NAS1149F0332P	2	WASHER				
	NSA5372-616AX	2	WASHER				
	NSA5372-616BX	2	WASHER				
	NSA5372-616CX	2	WASHER				
	NSA5372-616DX	2	WASHER				
	NSA5372-616EX	2	WASHER				
	NSA5372-716AX	40	WASHER				
	NSA5372-716BX	40	WASHER				
	NSA5372-716CX	40	WASHER				
	NSA5372-716DX	40	WASHER				
	NSA5372-716EX	40	WASHER				
	NSA5372-816AX	16	WASHER				
	NSA5372-816BX	16	WASHER				
	NSA5372-816CX	16	WASHER				
	NSA5372-816DX	16	WASHER				
	NSA5372-816EX	16	WASHER				

NOTE:

If you find part numbers of hardware components in the related kit(s) which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the correct part number to part number relationship.

Supplementary kit 571140A01S02

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
10	ASNA2532-7	11	NUT				
11	ASNA2531-7	2	NUT				
13	ASNA2532-8	16	NUT				
15	ASNA2531-6	2	NUT				
60	EN6115T2-3	14	BOLT				
61	ASNA2536-2	17	NUT				
62	EN6115T2-2	3	BOLT				
65	NAS1149D0332K	8	WASHER				
69	NAS1149F0332P	2	WASHER				
	NSA5372-716AX	31	WASHER				
	NSA5372-716BX	31	WASHER				
	NSA5372-716CX	31	WASHER				
	NSA5372-716DX	31	WASHER				
	NSA5372-716EX	31	WASHER				

NOTE:

If you find part numbers of hardware components in the related kit(s) which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the correct part number to part number relationship.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

### Supplementary kit 571140A01S03

	ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
1		NSA5372-616AX	2	WASHER				
I		NSA5372-616BX	2	WASHER				
1		NSA5372-616CX	2	WASHER				
I		NSA5372-616DX	2	WASHER				
		NSA5372-616EX	2	WASHER				
I		NSA5372-816AX	16	WASHER				
		NSA5372-816BX	16	WASHER				
		NSA5372-816CX	16	WASHER				
1		NSA5372-816DX	16	WASHER				
1		NSA5372-816EX	16	WASHER				

NOTE:

If you find part numbers of hardware components in the related kit(s) which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the correct part number to part number relationship.

### Supplementary kit 571140A02S02

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
10	ASNA2532-7	7	NUT				
11	ASNA2531-7	2	NUT				
13	ASNA2532-8	16	NUT				
15	ASNA2531-6	2	NUT				
60	EN6115T2-3	14	BOLT				
61	ASNA2536-2	17	NUT				
62	EN6115T2-2	3	BOLT				
65	NAS1149D0332K	8	WASHER				
69	NAS1149F0332P	2	WASHER				
	NSA5372-716AX	27	WASHER				
	NSA5372-716BX	27	WASHER				
	NSA5372-716CX	27	WASHER				
	NSA5372-716DX	27	WASHER				
	NSA5372-716EX	27	WASHER				

NOTE:

If you find part numbers of hardware components in the related kit(s) which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the correct part number to part number relationship.

### Supplementary kit 571140A02S03

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
	NSA5372-616AX	2	WASHER				
	NSA5372-616BX	2	WASHER				

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
	NSA5372-616CX	2	WASHER				
	NSA5372-616DX	2	WASHER				
	NSA5372-616EX	2	WASHER				
	NSA5372-816AX	16	WASHER				
	NSA5372-816BX	16	WASHER				
	NSA5372-816CX	16	WASHER				
	NSA5372-816DX	16	WASHER				
	NSA5372-816EX	16	WASHER				

NOTE:

If you find part numbers of hardware components in the related kit(s) which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the correct part number to part number relationship.

## D. <u>LIST OF MATERIALS - OPERATOR SUPPLIED</u>

## (1) Consumable Materials

Consumable CMLA01

ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Wash Primer - Structure	04CMA2	As required	
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required	
	Top Coat Polyurethane - External Structure	04JAA3	As required	
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required	
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required	
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required	
	Non Aqueous Cleaner	08BAA9	As required	

### (2) Components

NOTE: To accomplish this Service Bulletin it is necessary to use the expendable parts listed in the subsequent referenced tasks:

- AMM Task 28-21-42-400-001

AMM Task 28-21-54-400-001

AMM Task 53-35-11-400-001

- AMM Task 57-17-11-400-001

- AMM Task 57-27-11-400-001

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- AMM Task 57-27-12-400-001.

### Component COMPA01

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
11	ASNA2531-7	8	NUT				
31	ABS1418K8-13	4	SCREW				
32	ABS1418K8-14	28	SCREW				
33	ABS1418K8-18	32	SCREW				
34	ABS1418K8-19	36	SCREW				
35	ASNA2532-8	136	NUT				
36	ABS1418K8-21	8	SCREW				
37	ABS1418K8-26	8	SCREW				
38	ABS1418K8-17	24	SCREW				
43	ABS1418K8-25	8	SCREW				
44	ASNA2531-8	24	NUIT				
73	ABS1418K9-15	8	SCREW				
74	ABS1418K9-16	32	SCREW				
75	ABS1418K9-17	24	SCREW				
76	ASNA2532-9	64	NUT				
78	ABS1418K8-20	8	SCREW				
80	ABS1418K7-23	8	SCREW				
82	ABS1418K8-22	4	SCREW				
	NSA5372-716AX	8	WASHER				
	NSA5372-716BX	8	WASHER				
	NSA5372-716EX	8	WASHER				
	NSA5372-816AX	160	WASHER				
	NSA5372-816BX	160	WASHER				
	NSA5372-816EX	160	WASHER				
	NSA5372-916AX	64	WASHER				
	NSA5372-916BX	64	WASHER				
	NSA5372-916EX	64	WASHER				

NOTE: If you find part numbers of hardware components in the related kit(s)

which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the

correct part number to part number relationship.

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### Component COMPA03

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
11	ASNA2531-7	4	NUT				
32	ABS1418K8-14	8	SCREW				
34	ABS1418K8-19	8	SCREW				
35	ASNA2532-8	22	NUT				
37	ABS1418K8-26	2	SCREW				
43	ABS1418K8-25	2	SCREW				
44	ASNA2531-8	4	NUIT				
73	ABS1418K9-15	4	SCREW				
74	ABS1418K9-16	16	SCREW				
75	ABS1418K9-17	12	SCREW				
76	ASNA2532-9	32	NUT				
78	ABS1418K8-20	4	SCREW				
80	ABS1418K7-23	4	SCREW				
82	ABS1418K8-22	2	SCREW				
	NSA5372-716AX	4	WASHER				
	NSA5372-716BX	4	WASHER				
	NSA5372-716EX	4	WASHER				
	NSA5372-816AX	26	WASHER				
	NSA5372-816BX	26	WASHER				
	NSA5372-816EX	26	WASHER				
	NSA5372-916AX	32	WASHER				
	NSA5372-916BX	32	WASHER				
	NSA5372-916EX	32	WASHER				

NOTE: If you find part numbers of hardware components in the related kit(s)

which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the

correct part number to part number relationship.

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

#### Component COMPA04

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
11	ASNA2531-7	4	NUT				
34	ABS1418K8-19	8	SCREW				
35	ASNA2532-8	14	NUT				
37	ABS1418K8-26	2	SCREW				

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	ITEM	OLD PART N°	INT	SEE NOTES
43	ABS1418K8-25	2	SCREW				
44	ASNA2531-8	4	NUIT				
73	ABS1418K9-15	4	SCREW				
74	ABS1418K9-16	16	SCREW				
75	ABS1418K9-17	12	SCREW				
76	ASNA2532-9	32	NUT				
78	ABS1418K8-20	4	SCREW				
80	ABS1418K7-23	4	SCREW				
82	ABS1418K8-22	2	SCREW				
	NSA5372-716AX	4	WASHER				
	NSA5372-716BX	4	WASHER				
	NSA5372-716EX	4	WASHER				
	NSA5372-816AX	18	WASHER				
	NSA5372-816BX	18	WASHER				
	NSA5372-816EX	18	WASHER				
	NSA5372-916AX	32	WASHER				
	NSA5372-916BX	32	WASHER				
	NSA5372-916EX	32	WASHER				

NOTE: If you find part numbers of hardware components in the related kit(s)

which you cannot identify in the LIST OF COMPONENTS of this Service Bulletin, refer to Standards Manual (SM). The SM will give you the

correct part number to part number relationship.

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

(3) Equipment

None

### E. PARTS TO BE RE-IDENTIFIED BY OPERATOR

None

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### F. TOOLING

- (1) Tooling Price and Availability
  - (a) Procurement Addresses

Customers with aircraft shown in the effectivity of this Service Bulletin should send a purchase order to AIRBUS. Quote the number of this Service Bulletin. The address is :

Kit tool 571140T01R01	AIRBUS Material, Logistics and Suppliers
Kit tool 571140T02R00	IFD - In Flight Desk
	Weg beim Jaeger 150
	D-22335 HAMBURG
	GERMANY
	For ordering by internet:
	http://spares.airbus.com
	For ordering by fax: +49 40 50 76 4012
	For ordering by E-mail:
	ifd.spares@airbus.com

(b) Price and Availability

Kit tool 571140T01R01	
Cost	1,000.00 USD
Availability	42 calendar days from receipt of order

AIRBUS will provide at no charge the loan of this specific tool for a period equivalent to the Service Bulletin elapsed time (8 hours a day) per aircraft application plus ten days for transportation. After relevant period, standard loan charges apply.

Kit tool 571140T02R00	
Cost	1,364.00 USD
Availability	60 calendar days from receipt of order

AIRBUS will provide at no charge the loan of this specific tool for a period equivalent to the Service Bulletin elapsed time (8 hours a day) per aircraft application plus ten days for transportation. After relevant period, standard loan charges apply.

### (2) Tools

- (1) To accomplish this Service Bulletin it is necessary to use the following tools and equipment.
  - (a) For the taperlok installation test it is necessary to use the tool No. 98D57103001000 defined in Kit 571140T01R01 and the tool No. 98D57103002000 defined in Kit 571140T02R00.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

(b) In case of finding, for the installation of the new taperlok it is necessary to use the drilling tool SOA-TL-R57102001B.

Procurement to be negotiated directly with:

S.O.A

International Managing Support 66 rue des Graves, BP30013 33326 EYSINES Cedex

Tel: +33.5.56.57.94.50 Fax: +33.5.56.28.95.17 Email: direction@soaweb.fr

**FRANCE** 

- (c) Equipment and materials for the rotating probe inspection of the holes, refer to NTM 51-10-01 Part 6.
- (d) To accomplish this Service Bulletin it is necessary to use the tool 98D57004014000 listed in:
  - AMM Task 28-21-42-000-001
  - AMM Task 28-21-54-000-001
- (e) To accomplish this Service Bulletin it is necessary to use the tools listed in the subsequent referenced tasks:
  - AMM Task 57-27-11-000-001
  - AMM Task 57-27-11-400-001
  - AMM Task 57-27-12-000-001
  - AMM Task 57-27-12-400-001.

None

(3) Special Tools

Kit tool 571140T01R01

ITEM	PART N°	KEYWORD	QTY	SEE NOTES
	98D57103001000	Gage	8	

Kit tool 571140T02R00

ITEM	PART N°	KEYWORD	QTY	SEE NOTES
	98D57103002000	Test	1	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

#### 3. ACCOMPLISHMENT INSTRUCTIONS

Task 571140-832-801-001 - INSPECTION

WARNING: MAKE SURE THAT YOU OBEY ALL THE WARNINGS AND ALL THE CAUTIONS

INCLUDED IN THE REFERENCED PROCEDURES.

<u>CAUTION</u>: ALWAYS OBEY THE PRECAUTIONS THAT FOLLOW TO KEEP

ELECTRICAL WIRING IN A SATISFACTORY CONDITION (ELECTRICALLY AND MECHANICALLY SERVICEABLE). WHEN YOU DO MAINTENANCE WORK, REPAIRS OR MODIFICATIONS, ALWAYS KEEP ELECTRICAL WIRING, COMPONENTS AND THE WORK AREA AS CLEAN AS POSSIBLE. TO DO

THIS:

 PUT PROTECTION, SUCH AS PLASTIC SHEETING, CLOTHS, ETC; AS NECESSARY ON WIRING AND COMPONENTS.

 REGULARLY REMOVE ALL SHAVINGS, UNWANTED MATERIAL AND OTHER CONTAMINATION.

THESE PRECAUTIONS WILL DECREASE THE RISK OF CONTAMINATION AND DAMAGE TO THE ELECTRICAL WIRING INSTALLATION.

IF THERE IS CONTAMINATION REFER TO ESPM 20-55-00.

NOTE: The accomplishment instructions of this Service Bulletin include procedures given

in other documents or in other sections of the Service Bulletin. When the words 'refer to' are used and the operator has a procedure accepted by the local authority he belongs to, the accepted alternative procedure can be used. When the words 'in

accordance with' are used then the given procedure must be followed.

NOTE: The access and close-up instructions, not comprising return to service tests, in this

Service Bulletin do not constitute or affect the technical intent of the Service Bulletin. Operators can therefore, as deemed necessary, omit or add access and/or close-up steps to add flexibility to their maintenance operations as long as the

technical intent of the Service Bulletin is met within the set parameters.

NOTE: Manual titles given in the accomplishment instructions are referred to by acronyms.

Refer to paragraph 1.J., References, for the definition of acronyms.

NOTE: Discarded parts must be managed at the operator's discretion.

NOTE: This Service Bulletin contains the instructions for the on-aircraft maintenance

necessary to ensure the continued airworthiness of the aircraft.

For any deviations to the instructions, including RC paragraph contained herein,

contact AIRBUS for further instructions and approval.

NOTE: The purpose of flowcharts is to supplement the information given in the Procedure

and Compliance paragraphs and not to serve as the primary source for tasks or

compliance times given in this Service Bulletin.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### **Task Associated Data**

### \*\*CONF 001

	Zone				
From 141 to 540	From 141 to 540				
From 142 to 640	From 142 to 640				
Access					
Panel	Panel 147AZ 148AZ 540AB 540BZ 640AB 640BZ				
	Manpower				
TOTAL MANHOURS		69.00			
ELAPSED TIME (HO	URS)	18.00			

#### \*\*CONF 002

	Zone					
From 142 to 640	From 142 to 640					
	Access					
Panel 148AZ 640AB 640BZ						
Manpower						
TOTAL MANHOURS		69.00				
ELAPSED TIME (HO	URS)	18.00				

### \*\*CONF ALL

#### A. GENERAL

#### \*\*CONF 001

#### (1) Subtask 571140-910-001-001 - Standard Practices

	Manpower Resource	es
Skills		NON SPECIFIC

Ref	erences
Consumable Material List (CML)	
Structural Repair Manual (SRM)	51-42-11

- (a) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (b) Remove and install fasteners in accordance with SRM 51-42-11.

#### (2) Subtask 571140-839-001-001 - Administrative

Manpower Resource	ces
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 002

### (1) Subtask 571140-910-001-001 - Standard Practices

Manpower Resources	
Skills	NON SPECIFIC

References	
Consumable Material List (CML)	
Structural Repair Manual (SRM)	51-42-11

- (a) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (b) Remove and install fasteners in accordance with SRM 51-42-11.

#### (2) Subtask 571140-839-001-001 - Administrative

Manpower Resources	
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

#### \*\*CONF ALL

#### **B. PREPARATION**

#### \*\*CONF 001

#### (1) Subtask 571140-941-001-001 - Job Set-up

Manpower Resources	
Skills	NON SPECIFIC

References	
Aircraft Maintenance Manual (AMM)	Task 12-34-24-869-002
	Task 28-00-00-910-001
	Task 28-10-00-910-004
	Task 28-25-00-650-001
	Task 32-12-00-010-001

NOTE:

The items given in this note shall be considered as the basic Aircraft configuration before you start a maintenance task:

- Aircraft on the ground resting on landing gear (the ground safety locks and the wheel chocks are in position on the landing gear),
- Engine shut down, thrust reversers closed and locked,
- Aircraft in clean configuration,
- Parking brake applied,

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- Aircraft electrical network de-energized,
- Hydraulic systems depressurized,
- Access to the cockpit and cabin is available,
- All circuit breakers are in closed position,
- All controls in NORM, AUTO or OFF position.
- (a) Make sure that the aircraft is electrically grounded, refer to AMM Task 12-34-24-869-002.
- (b) Put an access platform in position at zones Z540 and Z640.
- (c) Defuel the center tank, refer to AMM Task 28-25-00-650-001.
- (d) Defuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (e) Degas and ventilate the center tank and the wing tanks, refer to AMM Task 28-00-00-910-001 and AMM Task 28-10-00-910-004.
- (f) Open the main landing gear doors, refer to AMM Task 32-12-00-010-001.

#### (2) Subtask 571140-010-001-001 - Remove/Open for Access on the LH Side

Manpower Resources	
Skills	NON SPECIFIC

References	
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001 Task 28-21-54-000-001 Task 53-35-11-000-001 Task 57-17-11-000-001 Task 57-27-11-000-001 Task 57-27-12-000-001
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01

- (a) Remove the access cover 147AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 540AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 540BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-001.
- (f) If necessary, remove the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### (3) Subtask 571140-010-002-001 - Remove/Open for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

References	
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001
	Task 28-21-54-000-801
	Task 53-35-11-000-001
	Task 57-17-11-000-001
	Task 57-27-11-000-001
	Task 57-27-12-000-001
Fig. A-FDCAA	Sheet 01
Removal/Installation of the Fuel Pump	
Strainer Covers	

- (a) Remove the access cover 148AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 640AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 640BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-801.
- (f) If necessary, remove the panels 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

#### (4) Subtask 571140-010-005-001 - Remove the Fuel Strainer, LH Side

Manpower Resources	
Skills	NON SPECIFIC

References	
Structural Repair Manual (SRM)	51-42-11
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

Remove for access the fuel strainer for LH side:
 Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02
 In accordance with SRM 51-42-11.

1 Strainer Assembly Item (55) Retain

1 Strainer Assembly Item (57) Retain

attached with:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

8	Bolt	Item (66)	Retain
2	Bolt	Item (67)	Retain
2	Bolt	Item (68)	Retain
2	Washer	Item (69)	Discard

### (5) Subtask 571140-010-006-001 - Remove the Fuel Strainer, RH Side

Manpower Re	esources
Skills	NON SPECIFIC

References	
Structural Repair Manual (SRM)	51-42-11
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

- Remove for access the fuel strainer for RH side: Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02 In accordance with SRM 51-42-11.

1	Strainer Assembly	Item (56)	Retain
1	Strainer Assembly	Item (58)	Retain
	attached with:		
8	Bolt	Item (66)	Retain
2	Bolt	Item (67)	Retain
2	Bolt	Item (68)	Retain
2	Washer	Item (69)	Discard

#### \*\*CONF 002

### (1) Subtask 571140-941-001-001 - Job Set-up

Manpower Resources	
Skills	NON SPECIFIC

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References		
Aircraft Maintenance Manual (AMM)	Task 12-34-24-869-002	
	Task 28-00-00-910-001	
	Task 28-10-00-910-004	
	Task 28-25-00-650-001	
	Task 32-12-00-010-001	

NOTE:

The items given in this note shall be considered as the basic Aircraft configuration before you start a maintenance task:

- Aircraft on the ground resting on landing gear (the ground safety locks and the wheel chocks are in position on the landing gear),
- Engine shut down, thrust reversers closed and locked,
- Aircraft in clean configuration,
- Parking brake applied,
- Aircraft electrical network de-energized,
- Hydraulic systems depressurized,
- Access to the cockpit and cabin is available,
- All circuit breakers are in closed position.
- All controls in NORM, AUTO or OFF position.
- (a) Make sure that the aircraft is electrically grounded, refer to AMM Task 12-34-24-869-002.
- (b) Put an access platform in position at zones Z540 and Z640.
- (c) Defuel the center tank, refer to AMM Task 28-25-00-650-001.
- (d) Defuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (e) Degas and ventilate the center tank and the wing tanks, refer to AMM Task 28-00-00-910-001 and AMM Task 28-10-00-910-004.
- (f) Open the main landing gear doors, refer to AMM Task 32-12-00-010-001.
- (2) Subtask 571140-010-001-001 Remove/Open for Access on the LH Side

Manpower Resources	
Skills	NON SPECIFIC

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001 Task 28-21-54-000-001 Task 53-35-11-000-001 Task 57-17-11-000-001 Task 57-27-11-000-001 Task 57-27-12-000-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

- (a) Remove the access cover 147AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 540AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 540BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-001.
- (f) If necessary, remove the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

#### (3) Subtask 571140-010-002-001 - Remove/Open for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001	
	Task 28-21-54-000-801	
	Task 53-35-11-000-001	
	Task 57-17-11-000-001	
	Task 57-27-11-000-001	
	Task 57-27-12-000-001	
Fig. A-FDCAA	Sheet 01	
Removal/Installation of the Fuel Pump		
Strainer Covers		

- (a) Remove the access cover 148AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 640AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 640BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-801.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

(f) If necessary, remove the panels 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

#### (4) Subtask 571140-010-005-001 - Remove the Fuel Strainer, LH Side

Manpower Resources	
Skills	NON SPECIFIC

References		
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

Remove for access the fuel strainer for LH side:
 Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02
 In accordance with SRM 51-42-11.

1	Strainer Assembly Item (55)			
1	Strainer Assembly Item (57) Re			
	attached with:			
8	Bolt	Item (66)	Retain	
2	Bolt	Item (67)	Retain	
2	Bolt	Item (68)	Retain	
2	Washer	Item (69)	Discard	

#### (5) Subtask 571140-010-006-001 - Remove the Fuel Strainer, RH Side

Manpower Resource	es
Skills	NON SPECIFIC

References	
Structural Repair Manual (SRM)	51-42-11
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

Remove for access the fuel strainer for RH side:
 Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02
 In accordance with SRM 51-42-11.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

1	Strainer Assembly	Item (56)	Retain	
1	Strainer Assembly Item (58)			
	attached with:			
8	Bolt	Item (66)	Retain	
2	Bolt	Item (67)	Retain	
2	Bolt	Item (68)	Retain	
2	Washer	Item (69)	Discard	

#### \*\*CONF ALL

### C. PROCEDURE

#### \*\*CONF 001

# (1) Subtask 571140-832-001-001 - LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction

	Work Zones and Access Panels			
	Zone	Access/Work location		
From	141	Access	Panel 147AZ	
		Work location	Rib 1	
То	540	Access Panel 540AB, Panel 540BZ		
		Work location	Rib 1	

Manpower Resources		
Manhours	26.00	
Minimum number of person	2	
Subtask elapsed time	13.00	
Skills	AIRFRAME	

### Material necessary to do the job

Cons	umable CMLA01			
ITEM	DESCRIPTION	REFERENCE TO	QTY PER A/C	SEE
		CML MAT. No.		NOTES
	Non Aqueous Cleaner	08BAA9	As required	

Kit tool 571140T01R01				
ITEM	PART N°	KEYWORD	QTY	SEE NOTES
	98D57103001000	Gage	1	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References		
In Service Information (ISI)	00.00.00179	
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FBAAA	Sheet 01	
Inspection of the Fasteners	Sheet 02	
	Sheet 03	
Fig. A-FBCAA	Sheet 01	
Thread Damage		
Fig. A-FCAAA	Sheet 01	
LH Side, Replacement of the Lower	Sheet 02	
Panel Fasteners	Sheet 03	
	Sheet 04	
	Sheet 05	
	Sheet 06	
	Sheet 07	
Fig. A-FFAAA	Sheet 01	
Flow Chart		

(a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFAAA Sheet 01

Refer to Fig. A-FBAAA Sheet 01 to Fig. A-FBAAA Sheet 03

Refer to Fig. A-FBCAA Sheet 01

Refer to Fig. A-FCAAA Sheet 01 to Fig. A-FCAAA Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

2 Remove the nuts:

Refer to Fig. A-FCAAA Sheet 01 to Fig. A-FCAAA Sheet 04

34	Nut	NSA5457-7E	Item (10)	Discard
	or			
34	Nut	NAS1727-7E	Item (10)	Discard
	or			
34	Nut	NSA5151-7	Item (10)	Discard
	and			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

6	Nut	NAS1726-7E	Item (11)	Discard
	or			
6	Nut	NSA5050-7	Item (11)	Discard
	and			
16	Nut	NSA5457-8E	Item (13)	Discard
	or			
16	Nut	NAS1727-8E	Item (13)	Discard
	or			
16	Nut	NSA5151-8	Item (13)	Discard
	and			
2	Nut	NAS1726-6E	Item (15)	Discard
	or			
2	Nut	NSA5050-6	Item (15)	Discard

NOTE: Identify the location of each removed nut.

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

98D57103001000 Gage set 1

- 1 If taperlok gage fit and move:
  - <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
    - <1> If thread marks are found caused by an incorrect installation:
      - <a> Apply SUBTASK 571140-833-003 001 Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.</a>
    - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-003 001 Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.</a>
    - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-001 001 Replace the Nuts on the LH Side before next flight.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- 2 If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-003 001 Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
- 3 If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-001 001 Replace the Nuts on the LH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

NOTE: Uploading the Inspection Report sheet is not Required for Compliance.

# (2) Subtask 571140-832-002-001 - RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction

	Work Zones and Access Panels				
	Zone		Access/Work location		
From	142	Access	Panel 148AZ		
		Work location	Rib 1		
То	640	Access Panel 640AB, Panel 640BZ			
		Work location	Rib 1		

Manpower Resources		
Manhours	26.00	
Minimum number of person	2	
Subtask elapsed time	13.00	
Skills	AIRFRAME	

#### Material necessary to do the job

Cons	umable CMLA01			
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Non Aqueous Cleaner	08BAA9	As required	

Kit to	ol 571140T01R01			
ITEM	PART N°	KEYWORD	QTY	SEE NOTES
	98D57103001000	Gage	1	

References		
In Service Information (ISI)	00.00.00179	
Structural Repair Manual (SRM)	51-42-11	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Ref	erences
Fig. A-FBAAA	Sheet 01
Inspection of the Fasteners	Sheet 02
	Sheet 03
Fig. A-FBCAA	Sheet 01
Thread Damage	
Fig. A-FCBAA	Sheet 01
RH Side, Replacement of the Lower	Sheet 02
Panel Fasteners	Sheet 03
	Sheet 04
	Sheet 05
	Sheet 06
	Sheet 07
Fig. A-FFAAA	Sheet 01
Flow Chart	

(a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFAAA Sheet 01

Refer to Fig. A-FBAAA Sheet 01 to Fig. A-FBAAA Sheet 03

Refer to Fig. A-FBCAA Sheet 01

Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FCBAA Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

2 Remove the nuts :

Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FCBAA Sheet 04

34	Nut	NSA5457-7E	Item (10)	Discard
	or			
34	Nut	NAS1727-7E	Item (10)	Discard
	or			
34	Nut	NSA5151-7	Item (10)	Discard
	and			
6	Nut	NAS1726-7E	Item (11)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

	C	or			
6	Nut		NSA5050-7	Item (11)	Discard
	a	and			
16	Nut		NSA5457-8E	Item (13)	Discard
	c	or			
16	Nut		NAS1727-8E	Item (13)	Discard
	c	or			
16	Nut		NSA5151-8	Item (13)	Discard
	a	and			
2	Nut		NAS1726-6E	Item (15)	Discard
	c	or			
2	Nut		NSA5050-6	Item (15)	Discard
	1	NOTE: I	dentify the location of e	ach removed i	nut.

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

98D57103001000 Gage set 1

- 1 If taperlok gage fit and move:
  - <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
    - <1> If thread marks are found caused by an incorrect installation:
      - <a> Apply SUBTASK 57-1140-833-004 001 Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.</a>
    - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
      - <a> Apply SUBTASK 57-1140-833-004 001 Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.</a>
    - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
      - <a> Apply SUBTASK 57-1140-833-002 001 Replace the Replace the Nuts on the RH Side before next flight.</a>

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 57-1140-833-004 001 Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
- 3 If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - a Apply SUBTASK 57-1140-833-002 001 Replace the Replace the Nuts on the RH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

NOTE: Uploading the Inspection Report sheet is not Required for Compliance.

#### \*\*CONF 002

(1) Subtask 571140-832-001-002 - LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction

	Work Zones and Access Panels			
	Zone	Access/Work location		
From	142	Access	Panel 148AZ	
		Work location	Rib 1	
То	640	Access	Panel 640AB, Panel 640BZ	
		Work location	Rib 1	

Manpower Resources		
Manhours	26.00	
Minimum number of person	2	
Subtask elapsed time	13.00	
Skills	AIRFRAME	

### Material necessary to do the job

Cons	umable CMLA01			
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Non Aqueous Cleaner	08BAA9	As required	

Kit tool 571140T01R01				
ITEM	PART N°	KEYWORD	QTY	SEE NOTES
	98D57103001000	Gage	1	

References	
In Service Information (ISI)	00.00.00179

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References		
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FFAAB	Sheet 01	
Flow Chart		
Fig. A-FBAAA	Sheet 01	
Inspection of the Fasteners	Sheet 02	
	Sheet 03	
Fig. A-FBCAA	Sheet 01	
Thread Damage		
Fig. A-FCAAA	Sheet 01	
LH Side, Replacement of the Lower	Sheet 02	
Panel Fasteners	Sheet 03	
	Sheet 04	
	Sheet 05	
	Sheet 06	
	Sheet 07	

### (a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFAAB Sheet 01

Refer to Fig. A-FBAAA Sheet 01 to Fig. A-FBAAA Sheet 03

Refer to Fig. A-FBCAA Sheet 01

Refer to Fig. A-FCAAA Sheet 01to Fig. A-FCAAA Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

#### 2 Remove the nuts:

Refer to Fig. A-FCAAA Sheet 01 to Fig. A-FCAAA Sheet 04

34	Nut	NSA5457-7E	Item (10)	Discard
	or			
34	Nut	NAS1727-7E	Item (10)	Discard
	or			
34	Nut	NSA5151-7	Item (10)	Discard
	and			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

6	Nut	NAS1726-7E	Item (11)	Discard
	or			
6	Nut	NSA5050-7	Item (11)	Discard
	and			
16	Nut	NSA5457-8E	Item (13)	Discard
	or			
16	Nut	NAS1727-8E	Item (13)	Discard
	or			
16	Nut	NSA5151-8	Item (13)	Discard
	and			
2	Nut	NAS1726-6E	Item (15)	Discard
	or			
2	Nut	NSA5050-6	Item (15)	Discard

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

Identify the location of each removed nut.

98D57103001000 Gage set 1

1 If taperlok gage fit and move:

NOTE:

- <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
  - <1> If thread marks are found caused by an incorrect installation:
    - <a> Apply SUBTASK 571140-833-003 002 Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.</a>
  - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
    - <a> Apply SUBTASK 571140-833-003 002 Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.</a>
  - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
    - <a> Apply SUBTASK 571140-833-001 002 Replace the Nuts on the LH Side before next flight.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- <u>2</u> If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - a Apply SUBTASK 571140-833-003 002 Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
- <u>3</u> If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-001 002 Replace the Nuts on the LH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

NOTE: Uploading the Inspection Report sheet is not Required for Compliance.

# (2) Subtask 571140-832-002-002 - RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction

Manpower Resources		
Manhours	26.00	
Minimum number of person	2	
Subtask elapsed time	13.00	
Skills	AIRFRAME	

#### Material necessary to do the job

Cons	umable CMLA01			
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Non Aqueous Cleaner	08BAA9	As required	

Kit to	ol 571140T01R01			
ITEM	PART N°	KEYWORD	QTY	SEE NOTES
	98D57103001000	Gage	1	

References	
In Service Information (ISI)	00.00.00179
Structural Repair Manual (SRM)	51-42-11
Fig. A-FBAAA Inspection of the Fasteners	Sheet 01 Sheet 02 Sheet 03
Fig. A-FBCAA Thread Damage	Sheet 01

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References		
Fig. A-FCBAA	Sheet 01	
RH Side, Replacement of the Lower	Sheet 02	
Panel Fasteners	Sheet 03	
	Sheet 04	
	Sheet 05	
	Sheet 06	
	Sheet 07	
Fig. A-FCAAA	Sheet 01	
LH Side, Replacement of the Lower	Sheet 02	
Panel Fasteners	Sheet 03	
	Sheet 04	
	Sheet 05	
	Sheet 06	
	Sheet 07	
Fig. A-FFAAB	Sheet 01	
Flow Chart		

(a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFAAB Sheet 01

Refer to Fig. A-FBAAA Sheet 01 to Fig. A-FBAAA Sheet 03

Refer to Fig. A-FBCAA Sheet 01

Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FCBAA Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

2 Remove the nuts:

Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FCBAA Sheet 04

34	Nut	NSA5457-7E	Item (10)	Discard
	or			
34	Nut	NAS1727-7E	Item (10)	Discard
	or			
34	Nut	NSA5151-7	Item (10)	Discard
	and			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

6	Nut	NAS1726-7E	Item (11)	Discard
	or			
6	Nut	NSA5050-7	Item (11)	Discard
	and			
16	Nut	NSA5457-8E	Item (13)	Discard
	or			
16	Nut	NAS1727-8E	Item (13)	Discard
	or			
16	Nut	NSA5151-8	Item (13)	Discard
	and			
2	Nut	NAS1726-6E	Item (15)	Discard
	or			
2	Nut	NSA5050-6	Item (15)	Discard

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

Identify the location of each removed nut.

98D57103001000 Gage set 1

1 If taperlok gage fit and move:

NOTE:

- <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
  - <1> If thread marks are found caused by an incorrect installation:
    - <a> Apply SUBTASK 57-1140-833-004 002 Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.</a>
  - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
    - <a> Apply SUBTASK 57-1140-833-004 002 Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.</a>
  - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
    - <a> Apply SUBTASK 57-1140-833-002 002 Replace the Replace the Nuts on the RH Side before next flight.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - a Apply SUBTASK 57-1140-833-004 002 Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
- 3 If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 57-1140-833-002 002 Replace the Replace the Nuts on the RH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

<u>NOTE</u>: Uploading the Inspection Report sheet is not Required for Compliance.

\*\*CONF ALL

D. TEST

\*\*CONF 001

None

\*\*CONF 002

None

\*\*CONF ALL

E. CLOSE-UP

\*\*CONF 001

None

\*\*CONF 002

None

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

#### Task 571140-833-801-001 - REPAIR

#### \*\*CONF ALL

WARNING: MAKE SURE THAT YOU OBEY ALL THE WARNINGS AND ALL THE CAUTIONS

INCLUDED IN THE REFERENCED PROCEDURES.

<u>CAUTION</u>: ALWAYS OBEY THE PRECAUTIONS THAT FOLLOW TO KEEP ELECTRICAL WIRING IN A SATISFACTORY CONDITION (ELECTRICALLY

AND MECHANICALLY SERVICEABLE). WHEN YOU DO MAINTENANCE WORK, REPAIRS OR MODIFICATIONS, ALWAYS KEEP ELECTRICAL WIRING, COMPONENTS AND THE WORK AREA AS CLEAN AS POSSIBLE. TO DO

THIS:

 PUT PROTECTION, SUCH AS PLASTIC SHEETING, CLOTHS, ETC; AS NECESSARY ON WIRING AND COMPONENTS.

 REGULARLY REMOVE ALL SHAVINGS, UNWANTED MATERIAL AND OTHER CONTAMINATION.

THESE PRECAUTIONS WILL DECREASE THE RISK OF CONTAMINATION AND DAMAGE TO THE ELECTRICAL WIRING INSTALLATION.

#### IN CASE OF CONTAMINATION REFER TO ESPM 20-55-00.

NOTE: The accomplishment instructions of this Service Bulletin include procedures given

in other documents or in other sections of the Service Bulletin. When the words 'refer to' are used and the operator has a procedure accepted by the local authority he belongs to, the accepted alternative procedure can be used. When the words 'in

accordance with' are used then the given procedure must be followed.

NOTE: The access and close-up instructions, not comprising return to service tests, in this

Service Bulletin do not constitute or affect the technical intent of the Service Bulletin. Operators can therefore, as deemed necessary, omit or add access and/or close-up steps to add flexibility to their maintenance operations as long as the

technical intent of the Service Bulletin is met within the set parameters.

NOTE: Manual titles given in the accomplishment instructions are referred to by acronyms.

Refer to paragraph 1.J., References, for the definition of acronyms.

NOTE: This Service Bulletin contains the instructions for the on-aircraft maintenance

necessary to ensure the continued airworthiness of the aircraft.

For any deviations to the instructions contained herein, contact AIRBUS for further

instructions and approval.

#### **Task Associated Data**

#### \*\*CONF 001

Zone
From 141 to 540
From 142 to 640

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Access		
Panel 147AZ 148AZ 540AB 540BZ 640AB 640BZ		
Manpower		
TOTAL MANHOURS		75.50
ELAPSED TIME (HOURS)		25.00

#### \*\*CONF 002

Zone			
From 141 to 540	From 141 to 540		
From 142 to 640	From 142 to 640		
Access			
Panel 147AZ 148AZ 540AB 540BZ 640AB 640BZ			
Manpower			
TOTAL MANHOURS 75.50			
ELAPSED TIME (HOURS)		25.00	

#### \*\*CONF ALL

#### A. GENERAL

#### \*\*CONF 001

#### (1) Subtask 571140-910-002-001 - Standard Practices

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Consumable Material List (CML)		
Structural Repair Manual (SRM)	51-24-00 51-42-11 51-43-00 51-75-12	

- (a) Apply the sealant in accordance with SRM 51-24-00.
- (b) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (c) Remove and install fasteners in accordance with SRM 51-42-11.
- (d) Get alternative and substitute fastener data in accordance with SRM 51-43-00.
- (e) Renew the protective finish in accordance with SRM 51-75-12.
  - (f) To torque tighten the standard threaded fasteners, refer to AMM Task 20-21-11-911-001.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### (2) Subtask 571140-839-002-001 - Administrative

Manpower Resources	
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

#### \*\*CONF 002

### (1) Subtask 571140-910-002-001 - Standard Practices

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Consumable Material List (CML)		
Structural Repair Manual (SRM)	51-24-00	
	51-42-11	
	51-43-00	
	51-75-12	

- (a) Apply the sealant in accordance with SRM 51-24-00.
- (b) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (c) Remove and install fasteners in accordance with SRM 51-42-11.
- (d) Get alternative and substitute fastener data in accordance with SRM 51-43-00.
- (e) Renew the protective finish in accordance with SRM 51-75-12.
- (f) To torque tighten the standard threaded fasteners, refer to AMM Task 20-21-11-911-001.

### (2) Subtask 571140-839-002-001 - Administrative

Manpower Resources	S
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

#### \*\*CONF ALL

### **B. PREPARATION**

#### \*\*CONF 001

None

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

#### \*\*CONF 002

None

### \*\*CONF ALL

### C. PROCEDURE

### \*\*CONF 001

### (1) Subtask 571140-833-001-001 - Replace the Nuts on the LH Side

Work Zones and Access Panels			
	Zone	Access/Work location	
From	141	Access	Panel 147AZ
		Work location	Rib 1
То	540	Access Panel 540AB, Panel 540BZ	
		Work location	Rib 1

Manpower Resources		
Manhours	12.00	
Minimum number of person	2	
Subtask elapsed time	6.00	
Skills	AIRFRAME	

### Material necessary to do the job

Kit 57	Kit 571140A01R04				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES	
10	ASNA2532-7	34	NUT		
11	ASNA2531-7	6	NUT		
13	ASNA2532-8	16	NUT		
15	ASNA2531-6	2	NUT		
	NSA5372-616AX	2	WASHER		
	NSA5372-616BX	2	WASHER		
	NSA5372-616CX	2	WASHER		
	NSA5372-616DX	2	WASHER		
	NSA5372-616EX	2	WASHER		
	NSA5372-716AX	40	WASHER		
	NSA5372-716BX	40	WASHER		
	NSA5372-716CX	40	WASHER		
	NSA5372-716DX	40	WASHER		
	NSA5372-716EX	40	WASHER		
	NSA5372-816AX	16	WASHER		
	NSA5372-816BX	16	WASHER		
	NSA5372-816CX	16	WASHER		
	NSA5372-816DX	16	WASHER		
	NSA5372-816EX	16	WASHER		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Cons	umable CMLA01			
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required	
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required	

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Structural Repair Manual (SRM)	51-42-11	
	51-43-00	
Fig. A-FCAAA	Sheet 01	
LH Side, Replacement of the Lower	Sheet 02	
Panel Fasteners	Sheet 03	
	Sheet 04	
	Sheet 05	
	Sheet 06	
	Sheet 07	
Fig. A-FCCAA	Sheet 01	
Definition of the Washer Thickness for	Sheet 02	
the Original Taperlok	Sheet 03	

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCAAA Sheet 01, Fig. A-FCAAA Sheet 02, Fig. A-FCAAA Sheet 05, Fig. A-FCAAA Sheet 06, Fig. A-FCAAA Sheet 07

	34	Nut	ASNA2532-7	Item 10
	6	Nut	ASNA2531-7	Item 11
I		with		
I	40	Washer	NSA5372-716AX	
ı		and/or		
ı	40	Washer	NSA5372-716BX	
I		and/or		
I	40	Washer	NSA5372-716CX	
I		and/or		
I	40	Washer	NSA5372-716DX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

ı		and/or		
1	40	Washer	NSA5372-716EX	
ı		and		
	2	Nut	ASNA2531-6	Item 15
		with		
ı	2	Washer	NSA5372-616AX	
		and/or		
I	2	Washer	NSA5372-616BX	
		and/or		
ı	2	Washer	NSA5372-616CX	
		and/or		
ı	2	Washer	NSA5372-616DX	
		and/or		
I	2	Washer	NSA5372-616EX	
I		and		
I	16	Nut	ASNA2532-8	Item 13
I		with		
I	16	Washer	NSA5372-816AX	
I		and/or		
I	16	Washer	NSA5372-816BX	
I		and/or		
I	16	Washer	NSA5372-816CX	
I		and/or		
I	16	Washer	NSA5372-816DX	
I		and/or		
I	16	Washer	NSA5372-816EX	
		NOTE:	Install the washer in accordant thickness given in the Fig. A-I	ance with the definition of the washer FCCAA Sheet 01.
		NOTE:	If necessary, the installation condition.	of the three washers is approved in this

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

NOTE: Torque the nuts between 3.80daN and 4.60daN (342lbf.in. and

411lbf.in.).

<u>NOTE</u>: Inside the wing center box, apply on the nuts :

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

### (2) Subtask 571140-833-002-001 - Replace the Nuts on the RH Side

Work Zones and Access Panels						
	Zone	ne Access/Work location				
From	142	Access Panel 148AZ				
		Work location Rib 1				
То	640	Access Panel 640AB, Panel 640BZ				
		Work location Rib 1				

Manpower Resources				
Manhours	12.00			
Minimum number of person	2			
Subtask elapsed time	6.00			
Skills	AIRFRAME			

### Material necessary to do the job

Kit 5	Kit 571140A01R04				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES	
10	ASNA2532-7	34	NUT		
11	ASNA2531-7	6	NUT		
13	ASNA2532-8	16	NUT		
15	ASNA2531-6	2	NUT		
	NSA5372-616AX	2	WASHER		
	NSA5372-616BX	2	WASHER		
	NSA5372-616CX	2	WASHER		
	NSA5372-616DX	2	WASHER		
	NSA5372-616EX	2	WASHER		
	NSA5372-716AX	40	WASHER		
	NSA5372-716BX	40	WASHER		
	NSA5372-716CX	40	WASHER		
	NSA5372-716DX	40	WASHER		
	NSA5372-716EX	40	WASHER		
	NSA5372-816AX	16	WASHER		
	NSA5372-816BX	16	WASHER		
	NSA5372-816CX	16	WASHER		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM NEW PART N° QTY (UM) KEYWORD SEE NOTES

NSA5372-816DX 16 WASHER

NSA5372-816EX 16 WASHER

Consi	Consumable CMLA01						
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES			
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required				
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required				

References				
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001			
Structural Repair Manual (SRM)	51-42-11			
	51-43-00			
Fig. A-FCCAA	Sheet 01			
Definition of the Washer Thickness for	Sheet 02			
the Original Taperlok	Sheet 03			
Fig. A-FCBAA	Sheet 01			
RH Side, Replacement of the Lower	Sheet 02			
Panel Fasteners	Sheet 03			
	Sheet 04			
	Sheet 05			
	Sheet 06			
	Sheet 07			

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCBAA Sheet 01, Fig. A-FCBAA Sheet 02, Fig. A-FCBAA Sheet 05, Fig. A-FCBAA Sheet 06, Fig. A-FCBAA Sheet 07

	34	Nut	ASNA2532-7	Item 10
	6	Nut	ASNA2531-7	Item 11
		with		
	40	Washer	NSA5372-716AX	
		and/or		
	40	Washer	NSA5372-716BX	
I		and/or		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

I	40	Washer	NSA5372-716CX	
I		and/or		
I	40	Washer	NSA5372-716DX	
I		and/or		
I	40	Washer	NSA5372-716EX	
I		and		
	2	Nut	ASNA2531-6	Item 15
		with		
I	2	Washer	NSA5372-616AX	
		and/or		
I	2	Washer	NSA5372-616BX	
		and/or		
I	2	Washer	NSA5372-616CX	
		and/or		
I	2	Washer	NSA5372-616DX	
		and/or		
I	2	Washer	NSA5372-616EX	
I		and		
I	16	Nut	ASNA2532-8	Item 13
I		with		
I	16	Washer	NSA5372-816AX	
I		and/or		
I	16	Washer	NSA5372-816BX	
I		and/or		
I	16	Washer	NSA5372-816CX	
I		and/or		
I	16	Washer	NSA5372-816DX	
I		and/or		
I	16	Washer	NSA5372-816EX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

NOTE: Install the washer in accordance with the definition of the washer

thickness given in the Fig. A-FCCAA Sheet 01.

NOTE: If necessary, the installation of the three washers is approved in this

condition.

NOTE: Torque the nuts between 3.80daN and 4.60daN (342lbf.in. and

411lbf.in.).

NOTE: Inside the wing center box, apply on the nuts:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1

As required

For Polysulfide

Sealant

# (3) Subtask 571140-833-003-001 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side

	Work Zones and Access Panels				
	Zone Access/Work location				
From	141	Access Panel 147AZ			
		Work location Rib 1			
То	540	Access	Panel 540AB, Panel 540BZ		
		Work location Rib 1			

Manpower Resources				
Manhours	16.00			
Minimum number of person	2			
Subtask elapsed time	10.00			
Skills	AIRFRAME NON DESTRUCTIVE TESTING			

### Material necessary to do the job

Kit 57	Kit 571140A01R04					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
60	EN6115T2-3	14	BOLT			
61	ASNA2536-2	17	NUT			
62	EN6115T2-2	3	BOLT			
65	NAS1149D0332K	8	WASHER			

Component COMPA01				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
11	ASNA2531-7	2	NUT	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
31	ABS1418K8-13	1	SCREW	
32	ABS1418K8-14	7	SCREW	
33	ABS1418K8-18	8	SCREW	
34	ABS1418K8-19	9	SCREW	
35	ASNA2532-8	34	NUT	
36	ABS1418K8-21	2	SCREW	
37	ABS1418K8-26	2	SCREW	
38	ABS1418K8-17	6	SCREW	
43	ABS1418K8-25	2	SCREW	
44	ASNA2531-8	6	NUIT	
73	ABS1418K9-15	2	SCREW	
74	ABS1418K9-16	8	SCREW	
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	40	WASHER	
	NSA5372-816BX	40	WASHER	
	NSA5372-816EX	40	WASHER	
	NSA5372-916AX	16	WASHER	
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

Consi	Consumable CMLA01					
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES		
	Wash Primer - Structure	04CMA2	As required			
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required			
	Top Coat Polyurethane - External Structure	04JAA3	As required			
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required	
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required	

Kit tool 571140T02R00					
ITEM	PART N°	KEYWORD	QTY	SEE NOTES	
	98D57103002000	Test	1		

Ref	erences
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001
Drawing	R57102001
Non Destructive Test Manual (NTM)	51-10-01 PART 6
Structural Repair Manual (SRM)	51-24-00
	51-42-11
	51-43-00
Fig. A-FCAAA	Sheet 01
LH Side, Replacement of the Lower	Sheet 02
Panel Fasteners	Sheet 03
	Sheet 04
	Sheet 05
	Sheet 06
	Sheet 07
Fig. A-FCDAA	Sheet 01
Definition of the Washer Thickness for	
the New Taperlok	
Fig. A-FDAAA	Sheet 01
Removal/Installation of the Cooling Duct	
Fig. A-FDBAA	Sheet 01
Removal/Installation of the Belly Fairing	Sheet 02
Structure	Sheet 03

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCAAA Sheet 01 to Fig. A-FCAAA Sheet 07

- (a) Depending on the result of the inspection, remove for access:
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1 Duct Item (53) Retain

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

1		Duct		Item (52)	Retain
			attached with		
1		Clamp		Item (63)	Retain
8		Scr	ew	Item (64)	Retain
8		Wa	sher	Item (65)	Discard
		<u>2</u>	Remove the structure of the belly fairing	<b>)</b> .	
			Refer to Fig. A-FDBAA Sheet 01 to Fig.	A-FDBAA Sh	neet 03
1		Cha	annel-Formed	Item (51)	Retain
			attached with		
3		Riv	et	Item (62)	Discard
7		Riv	et	Item (60)	Discard
10		Bus	sh	Item (61)	Discard
			and/or		
1		We	b 4 assy	Item (50)	Retain
			attached with		
7		Riv	et	Item (60)	Discard
7		Bus	sh	Item (61)	Discard
	(b)	In a	accordance with the result of the inspection	n, remove the	taperlok(s):
		Ref	er to Fig. A-FCAAA Sheet 01 to Fig. A-F0	CAAA Sheet 0	<u>)4</u>
6		Scr	ew	Item (16)	Discard
10		Scr	ew	Item (5)	Discard
9		Scr	ew	Item (7)	Discard
7		Scr	ew	Item (3)	Discard
2		Scr	ew	Item (14)	Discard
1		Scr	ew	Item (1)	Discard
2		Scr	ew	Item (12)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

2	Screw	Item (70)	Discard
8	Screw	Item (71)	Discard
6	Screw	Item (72)	Discard
2	Screw	Item (77)	Discard
2	Screw	Item (79)	Discard
1	Screw	Item (81)	Discard

NOTE: The nuts are removed during the inspection.

- (c) Do a rototest inspection of the holes for cracks, refer to NTM 51-10-01 PART 6.
  - 1 If cracks are found, contact AIRBUS before any further work.
  - 2 If no crack is found, do the following steps.
- (d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

NOTE: To prevent any accidental damage, we recommend to train to oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCAAA Sheet 01, Fig. A-FCAAA Sheet 02, Fig. A-FCAAA Sheet 05, Fig. A-FCAAA Sheet 06, Fig. A-FCAAA Sheet 07

6	Screw	ABS1418K8-17	Item 38
8	Screw	ABS1418K8-18	Item 33
9	Screw	ABS1418K8-19	Item 34
1	Screw	ABS1418K8-13	Item 31
7	Screw	ABS1418K8-14	Item 32
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		
34	Nut	ASNA2532-8	Item 35

5 DATE: Nov. 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

	and if necessary		
34	Washer	NSA5372-816AX	
	and/or		
34	Washer	NSA5372-816EX	
	and/or		
34	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K8-25	Item 43
2	Screw	ABS1418K8-26	Item 37
2	Screw	ABS1418K8-21	Item 36
	with		
6	Nut	ASNA2531-8	Item 44
	and if necessary		
6	Washer	NSA5372-816AX	
	and/or		
6	Washer	NSA5372-816EX	
	and/or		
6	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K9-15	Item 73
8	Screw	ABS1418K9-16	Item 74
6	Screw	ABS1418K9-17	Item 75
	with		
16	Nut	ASNA2532-9	Item 76
	and if necessary		
16	Washer	NSA5372-916AX	
	and/or		
16	Washer	NSA5372-916EX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

and/or

16 Washer NSA5372-916BX

and

2 Screw ABS1418K7-23 Item 80

with

2 Nut ASNA2531-7 Item 11

and if necessary

2 Washer NSA5372-716AX

and/or

2 Washer NSA5372-716EX

and/or

2 Washer NSA5372-716BX

NOTE: Install the screw in accordance with the installation principle given in

the repair instruction R57102001.

NOTE: If necessary, install the washer in accordance with the definition of

the washer thickness given in the Fig. A-FCDAA Sheet 01.

NOTE: Wet assembly, apply:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

<u>NOTE</u>: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

- Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

NOTE: Inside the wing center box, apply on the nuts:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Polysulfide Sealant- 06ABB1 As required Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

(f) If removed, install:

1 The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

1	Channel-Formed		Item (51)	Retained at removal
	with			
7	Bolt	EN6115T2-3	Item 60	
3	Bolt	EN6115T2-2	Item 62	
10	Nut	ASNA2536-2	Item 61	
	and/or			
1	Web 4 assy		Item (50)	Retained at removal
	attached with			
7	Bolt	EN6115T2-3	Item 60	
7	Nut	ASNA2536-2	Item 61	

NOTE: Apply to the interface of the structure and all the parts :

Polysulfide Sealant- 06AAA1

As required

General Purpose

with

Brushable

2 The cooling duct.

Refer to Fig. A-FDAAA Sheet 01

Duct Item (53) Retained at removal
 Duct Item (52) Retained at removal

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

1 Clamp Item (63) Retained at removal

8 Screw Item (64) Retained at removal

Washer NAS1149D0332K Item 65

8

# (4) Subtask 571140-833-004-001 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side

	Work Zones and Access Panels				
	Zone	Access/Work location			
From	142	Access	Panel 148AZ		
		Work location	Rib 1		
То	640	Access	Panel 640AB, Panel 640BZ		
		Work location	Rib 1		

Manpower Reso	Manpower Resources				
Manhours	16.00				
Minimum number of person	2				
Subtask elapsed time	10.00				
Skills	AIRFRAME NON DESTRUCTIVE TESTING				

### Material necessary to do the job

Kit 571140A01R04 ITEM NEW PART N° QTY (UM) **KEYWORD** SEE NOTES 60 EN6115T2-3 14 **BOLT** 17 61 ASNA2536-2 NUT 62 3 **BOLT** EN6115T2-2 8 **WASHER** NAS1149D0332K

Comp	Component COMPA01				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES	
11	ASNA2531-7	2	NUT		
31	ABS1418K8-13	1	SCREW		
32	ABS1418K8-14	7	SCREW		
33	ABS1418K8-18	8	SCREW		
34	ABS1418K8-19	9	SCREW		
35	ASNA2532-8	34	NUT		
36	ABS1418K8-21	2	SCREW		
37	ABS1418K8-26	2	SCREW		
38	ABS1418K8-17	6	SCREW		
43	ABS1418K8-25	2	SCREW		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
44	ASNA2531-8	6	NUIT	
73	ABS1418K9-15	2	SCREW	
74	ABS1418K9-16	8	SCREW	
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	40	WASHER	
	NSA5372-816BX	40	WASHER	
	NSA5372-816EX	40	WASHER	
	NSA5372-916AX	16	WASHER	_
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

Consu	Consumable CMLA01			
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Wash Primer - Structure	04CMA2	As required	
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required	
	Top Coat Polyurethane - External Structure	04JAA3	As required	
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required	
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required	
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required	

Kit to	Kit tool 571140T02R00				
ITEM	PART N°	KEYWORD	QTY	SEE NOTES	
	98D57103002000	Test	1		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References			
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001		
Drawing	R57102001		
Non Destructive Test Manual (NTM)	51-10-01 PART 6		
Structural Repair Manual (SRM)	51-24-00		
	51-42-11		
	51-43-00		
Fig. A-FCBAA	Sheet 01		
RH Side, Replacement of the Lower	Sheet 02		
Panel Fasteners	Sheet 03		
	Sheet 04		
	Sheet 05		
	Sheet 06		
	Sheet 07		
Fig. A-FCDAA	Sheet 01		
Definition of the Washer Thickness for			
the New Taperlok			
Fig. A-FDAAA	Sheet 01		
Removal/Installation of the Cooling Duct			
Fig. A-FDBAA	Sheet 01		
Removal/Installation of the Belly Fairing	Sheet 02		
Structure	Sheet 03		

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FCBAA Sheet 07

- (a) Depending on the result of the inspection, remove for access :
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1	Duct	Item (54)	Retain
1	Duct	Item (52)	Retain
	attached with		
1	Clamp	Item (63)	Retain
8	Screw	Item (64)	Retain
8	Washer	Item (65)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

2 Remove the structure of the belly fairing.

1	Channel-Formed	Item (171)	Retain
	attached with		
3	Rivet	Item (62)	Discard
7	Rivet	Item (60)	Discard
10	Bush	Item (61)	Discard
	and/or		
1	Web 4 assy	Item (170)	Retain
	attached with		
7	Rivet	Item (60)	Discard
7	Bush	Item (61)	Discard
(b)	In accordance with the result of the inspection	n, remove the	taperlok(s):
	Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FC	BAA Sheet 0	<u>4</u>
6	Screw	Item (16)	Discard
10	Screw	Item (5)	Discard
9	Screw	Item (7)	Discard
7	Screw	Item (3)	Discard
2	Screw	Item (14)	Discard
1	Screw	Item (1)	Discard
2	Screw	Item (12)	Discard
2	Screw	Item (70)	Discard
8	Screw	Item (71)	Discard
6	Screw	Item (72)	Discard
2	Screw	Item (77)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

2	Screw	Item (79)	Discard
1	Screw	Item (81)	Discard

NOTE: The nuts are removed during the inspection.

- (c) Do a rototest inspection of the holes for cracks refer to NTM 51-10-01 PART 6.
  - 1 If cracks are found, contact AIRBUS before any further work.
  - 2 If no crack is found, do the following steps.
- (d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

<u>NOTE</u>: To prevent any accidental damage, we recommend to train to oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCBAA Sheet 01, Fig. A-FCBAA Sheet 02, Fig. A-FCBAA Sheet 05, Fig. A-FCBAA Sheet 06, Fig. A-FCBAA Sheet 07

6	Screw	ABS1418K8-17	Item 38
8	Screw	ABS1418K8-18	Item 33
9	Screw	ABS1418K8-19	Item 34
1	Screw	ABS1418K8-13	Item 31
7	Screw	ABS1418K8-14	Item 32
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		
34	Nut	ASNA2532-8	Item 35
	and if necessary		
34	Washer	NSA5372-816AX	
	and/or		
34	Washer	NSA5372-816EX	
	and/or		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

34	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K8-25	Item 43
2	Screw	ABS1418K8-26	Item 37
2	Screw	ABS1418K8-21	Item 36
	with		
6	Nut	ASNA2531-8	Item 44
	and if necessary		
6	Washer	NSA5372-816AX	
	and/or		
6	Washer	NSA5372-816EX	
	and/or		
6	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K9-15	Item 73
8	Screw	ABS1418K9-16	Item 74
6	Screw	ABS1418K9-17	Item 75
	with		
16	Nut	ASNA2532-9	Item 76
	and if necessary		
16	Washer	NSA5372-916AX	
	and/or		
16	Washer	NSA5372-916EX	
	and/or		
16	Washer	NSA5372-916BX	
	and		
2	Screw	ABS1418K7-23	Item 80
	with		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

2 Nut ASNA2531-7 Item 11

and if necessary

2 Washer NSA5372-716AX

and/or

2 Washer NSA5372-716EX

and/or

2 Washer NSA5372-716BX

NOTE: Install the screw in accordance with the installation principle given in

the repair instruction R57102001.

NOTE: If necessary, install the washer in accordance with the definition of

the washer thickness given in the Fig. A-FCDAA Sheet 01.

NOTE: Wet assembly, apply:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

NOTE: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

- Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

<u>NOTE</u>: Inside the wing center box, apply on the nuts :

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 70

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

### SERVICE BULLETIN

(f)	If removed,	install	:
-----	-------------	---------	---

1 The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

1	Channel-Formed		Item (171)	Retained at removal
	with			
7	Bolt	EN6115T2-3	Item 60	
3	Bolt	EN6115T2-2	Item 62	
10	Nut	ASNA2536-2	Item 61	
	and/or			
1	Web 4 assy		Item (170)	Retained at removal
	attached with	1		
7	Bolt	EN6115T2-3	Item 60	
7	Nut	ASNA2536-2	Item 61	
	NOTE:	Apply to the interface of	the structure	and all the parts:
	Polysulfide Sealant General Purpose Brushable	- 06AAA1 As	required	
	General Purpose		required	
	General Purpose Brushable  2 The cooling of		required	
1	General Purpose Brushable  2 The cooling of	duct.	required  Item (54)	Retained at removal
1	General Purpose Brushable  2 The cooling of Refer to Fig.	duct.		
	General Purpose Brushable  2 The cooling of Refer to Fig.  Duct	duct.	Item (54)	removal Retained at
	General Purpose Brushable  2 The cooling of Refer to Fig.  Duct  Duct	duct.	Item (54)	removal Retained at
1	General Purpose Brushable  2 The cooling of Refer to Fig.  Duct  Duct  with	duct.	Item (54) Item (52)	removal  Retained at removal  Retained at

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 002

### (1) Subtask 571140-833-001-002 - Replace the Nuts on the LH Side

	Work Zones and Access Panels					
	Zone Access/Work location					
From	141	Access	Panel 147AZ			
		Work location Rib 1				
То	540	Access Panel 540AB, Panel 540BZ				
		Work location	Rib 1			

Manpower Resources					
Manhours	12.00				
Minimum number of person	2				
Subtask elapsed time	6.00				
Skills	AIRFRAME				

### Material necessary to do the job

Kit 57	Kit 571140A02R04					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
10	ASNA2532-7	34	NUT			
11	ASNA2531-7	6	NUT			
13	ASNA2532-8	16	NUT			
15	ASNA2531-6	2	NUT			
	NSA5372-616AX	2	WASHER			
	NSA5372-616BX	2	WASHER			
	NSA5372-616CX	2	WASHER			
	NSA5372-616DX	2	WASHER			
	NSA5372-616EX	2	WASHER			
	NSA5372-716AX	40	WASHER			
	NSA5372-716BX	40	WASHER			
	NSA5372-716CX	40	WASHER			
	NSA5372-716DX	40	WASHER			
	NSA5372-716EX	40	WASHER			
	NSA5372-816AX	16	WASHER			
	NSA5372-816BX	16	WASHER			
	NSA5372-816CX	16	WASHER			
	NSA5372-816DX	16	WASHER			
	NSA5372-816EX	16	WASHER			

Consumable CMLA01					
ITEM DESCRIPTION REFERENCE TO QTY PER A/C SEE CML MAT. No. NOTES					
Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required	

References				
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001			
Structural Repair Manual (SRM)	51-42-11			
	51-43-00			
Fig. A-FCAAA	Sheet 01			
LH Side, Replacement of the Lower	Sheet 02			
Panel Fasteners	Sheet 03			
	Sheet 04			
	Sheet 05			
	Sheet 06			
	Sheet 07			
Fig. A-FCCAA	Sheet 01			
Definition of the Washer Thickness for	Sheet 02			
the Original Taperlok	Sheet 03			

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCAAA Sheet 01, Fig. A-FCAAA Sheet 02, Fig. A-FCAAA Sheet 05, Fig. A-FCAAA Sheet 06, Fig. A-FCAAA Sheet 07

	34	Nut	ASNA2532-7	Item 10
	6	Nut	ASNA2531-7	Item 11
I		with		
I	40	Washer	NSA5372-716AX	
I		and/or		
ı	40	Washer	NSA5372-716BX	
ı		and/or		
ı	40	Washer	NSA5372-716CX	
ı		and/or		
I	40	Washer	NSA5372-716DX	
ı		and/or		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

I	40	Washer		NSA5372-716EX	
ı		and			
	2	Nut		ASNA2531-6	Item 15
		with			
ı	2	Washer		NSA5372-616AX	
		and/or			
I	2	Washer		NSA5372-616BX	
		and/or			
I	2	Washer		NSA5372-616CX	
		and/or			
I	2	Washer		NSA5372-616DX	
		and/or			
ı	2	Washer		NSA5372-616EX	
I		and			
I	16	Nut		ASNA2532-8	Item 13
I		with			
I	16	Washer		NSA5372-816AX	
I		and/or			
I	16	Washer		NSA5372-816BX	
I		and/or			
I	16	Washer		NSA5372-816CX	
ı		and/or			
ı	16	Washer		NSA5372-816DX	
ı		and/or			
I	16	Washer		NSA5372-816EX	
		<u>NOTE</u> :		ie washer in accorda s given in the <u>Fig. A-I</u>	ance with the definition of the washer FCCAA Sheet 01.
		<u>NOTE</u> :	If necess condition		f the three washers is approved in this
		NOTE:	Torque	the nuts between 3	.80daN and 4.60daN (342lbf.in. and

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

411lbf.in.).

NOTE: Inside the wing center box, apply on the nuts:

Polysulfide Sealant- 06ABB1

arit

As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1

As required

For Polysulfide

Sealant

### (2) Subtask 571140-833-002-002 - Replace the Nuts on the RH Side

Work Zones and Access Panels						
	Zone Access/Work location					
From	142	Access Panel 148AZ				
		Work location Rib 1				
То	640	Access Panel 640AB, Panel 640BZ				
		Work location	Rib 1			

Manpower Resources				
Manhours	12.00			
Minimum number of person	2			
Subtask elapsed time	6.00			
Skills	AIRFRAME			

### Material necessary to do the job

Kit 57	Kit 571140A02R04					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
10	ASNA2532-7	34	NUT			
11	ASNA2531-7	6	NUT			
13	ASNA2532-8	16	NUT			
15	ASNA2531-6	2	NUT			
	NSA5372-616AX	2	WASHER			
	NSA5372-616BX	2	WASHER			
	NSA5372-616CX	2	WASHER			
	NSA5372-616DX	2	WASHER			
	NSA5372-616EX	2	WASHER			
	NSA5372-716AX	40	WASHER			
	NSA5372-716BX	40	WASHER			
	NSA5372-716CX	40	WASHER			
	NSA5372-716DX	40	WASHER			
	NSA5372-716EX	40	WASHER			
	NSA5372-816AX	16	WASHER			
	NSA5372-816BX	16	WASHER			
	NSA5372-816CX	16	WASHER			
	NSA5372-816DX	16	WASHER			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
	NSA5372-816EX	16	WASHER	

Consi	Consumable CMLA01						
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES			
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required				
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required				

Ref	References				
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001				
Structural Repair Manual (SRM)	51-42-11				
	51-43-00				
Fig. A-FCCAA	Sheet 01				
Definition of the Washer Thickness for	Sheet 02				
the Original Taperlok	Sheet 03				
Fig. A-FCBAA	Sheet 01				
RH Side, Replacement of the Lower	Sheet 02				
Panel Fasteners	Sheet 03				
	Sheet 04				
	Sheet 05				
	Sheet 06				
	Sheet 07				

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCBAA Sheet 01, Fig. A-FCBAA Sheet 02, Fig. A-FCBAA Sheet 05, Fig. A-FCBAA Sheet 06, Fig. A-FCBAA Sheet 07

	34	Nut	ASNA2532-7	Item 10
	6	Nut	ASNA2531-7	Item 11
I		with		
	40	Washer	NSA5372-716AX	
		and/or		
I	40	Washer	NSA5372-716BX	
Ī		and/or		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

I	40	Washer	NSA5372-716CX	
I		and/or		
I	40	Washer	NSA5372-716DX	
I		and/or		
I	40	Washer	NSA5372-716EX	
I		and		
	2	Nut	ASNA2531-6	Item 15
		with		
I	2	Washer	NSA5372-616AX	
		and/or		
I	2	Washer	NSA5372-616BX	
		and/or		
I	2	Washer	NSA5372-616CX	
		and/or		
I	2	Washer	NSA5372-616DX	
		and/or		
I	2	Washer	NSA5372-616EX	
I		and		
I	16	Nut	ASNA2532-8	Item 13
I		with		
I	16	Washer	NSA5372-816AX	
I		and/or		
I	16	Washer	NSA5372-816BX	
I		and/or		
I	16	Washer	NSA5372-816CX	
I		and/or		
I	16	Washer	NSA5372-816DX	
I		and/or		
I	16	Washer	NSA5372-816EX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

NOTE: Install the washer in accordance with the definition of the washer

thickness given in the Fig. A-FCCAA Sheet 01.

NOTE: If necessary, the installation of the three washers is approved in this

condition.

NOTE: Torque the nuts between 3.80daN and 4.60daN (342lbf.in. and

411lbf.in.).

NOTE: Inside the wing center box, apply on the nuts:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1

As required

For Polysulfide

Sealant

# (3) Subtask 571140-833-003-002 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side

	Work Zones and Access Panels				
	Zone Access/Work location				
From	141	Access	Panel 147AZ		
		Work location	Work location Rib 1		
То	540	Access	Panel 540AB, Panel 540BZ		
		Work location	Rib 1		

Manpower Resources	
Manhours	16.00
Minimum number of person	2
Subtask elapsed time	10.00
Skills	AIRFRAME NON DESTRUCTIVE TESTING

### Material necessary to do the job

Kit 571140A02R04 ITEM NEW PART N° QTY (UM) **KEYWORD** SEE NOTES BOLT 60 EN6115T2-3 14 ASNA2536-2 17 NUT 61 62 EN6115T2-2 3 **BOLT** 65 NAS1149D0332K 8 WASHER

Comp	onent COMPA01			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
11	ASNA2531-7	2	NUT	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
31	ABS1418K8-13	1	SCREW	
32	ABS1418K8-14	7	SCREW	
33	ABS1418K8-18	8	SCREW	
34	ABS1418K8-19	9	SCREW	
35	ASNA2532-8	34	NUT	
36	ABS1418K8-21	2	SCREW	
37	ABS1418K8-26	2	SCREW	
38	ABS1418K8-17	6	SCREW	
43	ABS1418K8-25	2	SCREW	
44	ASNA2531-8	6	NUIT	
73	ABS1418K9-15	2	SCREW	
74	ABS1418K9-16	8	SCREW	
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	40	WASHER	
	NSA5372-816BX	40	WASHER	
	NSA5372-816EX	40	WASHER	
	NSA5372-916AX	16	WASHER	
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

Consi	Consumable CMLA01					
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES		
	Wash Primer - Structure	04CMA2	As required			
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required			
	Top Coat Polyurethane - External Structure	04JAA3	As required			
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required	
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required	

Kit to	Kit tool 571140T02R00						
ITEM	PART N°	KEYWORD	QTY	SEE NOTES			
	98D57103002000	Test	1				

References				
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001			
Drawing	R57102001			
Non Destructive Test Manual (NTM)	51-10-01 PART 6			
Structural Repair Manual (SRM)	51-24-00			
	51-42-11			
	51-43-00			
Fig. A-FCAAA	Sheet 01			
LH Side, Replacement of the Lower	Sheet 02			
Panel Fasteners	Sheet 03			
	Sheet 04			
	Sheet 05			
	Sheet 06			
	Sheet 07			
Fig. A-FCDAA	Sheet 01			
Definition of the Washer Thickness for				
the New Taperlok				
Fig. A-FDAAA	Sheet 01			
Removal/Installation of the Cooling Duct				
Fig. A-FDBAA	Sheet 01			
Removal/Installation of the Belly Fairing	Sheet 02			
Structure	Sheet 03			

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCAAA Sheet 01 to Fig. A-FCAAA Sheet 07

- (a) Depending on the result of the inspection, remove for access :
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1 Duct Item (53) Retain

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

1		Duo	et	Item (52)	Retain
			attached with		
1		Cla	mp	Item (63)	Retain
8		Scr	ew	Item (64)	Retain
8		Wa	sher	Item (65)	Discard
		<u>2</u>	Remove the structure of the belly fairing	J.	
			Refer to Fig. A-FDBAA Sheet 01 to Fig.	A-FDBAA Sh	ieet 03
1		Cha	annel-Formed	Item (51)	Retain
			attached with		
3		Riv	et	Item (62)	Discard
7		Riv	et	Item (60)	Discard
10		Bus	sh	Item (61)	Discard
			and/or		
1		We	b 4 assy	Item (50)	Retain
			attached with		
7		Riv	et	Item (60)	Discard
7		Bus	sh	Item (61)	Discard
	(b)	In a	accordance with the result of the inspectio	n, remove the	taperlok(s):
		Ref	er to Fig. A-FCAAA Sheet 01 to Fig. A-FC	CAAA Sheet 0	<u>14</u>
6		Scr	ew	Item (16)	Discard
10		Scr	ew	Item (5)	Discard
9		Scr	ew	Item (7)	Discard
7		Scr	ew	Item (3)	Discard
2		Scr	ew	Item (14)	Discard
1		Scr	ew	Item (1)	Discard
2		Scr	ew	Item (12)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

2	Screw	Item (70)	Discard
8	Screw	Item (71)	Discard
6	Screw	Item (72)	Discard
2	Screw	Item (77)	Discard
2	Screw	Item (79)	Discard
1	Screw	Item (81)	Discard

<u>NOTE</u>: The nuts are removed during the inspection.

- (c) Do a rototest inspection of the holes for cracks, refer to NTM 51-10-01 PART 6.
  - 1 If cracks are found, contact AIRBUS before any further work.
  - 2 If no crack is found, do the following steps.
- (d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

NOTE: To prevent any accidental damage, we recommend to train to oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCAAA Sheet 01, Fig. A-FCAAA Sheet 02, Fig. A-FCAAA Sheet 05, Fig. A-FCAAA Sheet 06, Fig. A-FCAAA Sheet 07

6	Screw	ABS1418K8-17	Item 38
8	Screw	ABS1418K8-18	Item 33
9	Screw	ABS1418K8-19	Item 34
1	Screw	ABS1418K8-13	Item 31
7	Screw	ABS1418K8-14	Item 32
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		
34	Nut	ASNA2532-8	Item 35

5 DATE: Nov. 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

	and if necessary		
34	Washer	NSA5372-816AX	
	and/or		
34	Washer	NSA5372-816EX	
	and/or		
34	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K8-25	Item 43
2	Screw	ABS1418K8-26	Item 37
2	Screw	ABS1418K8-21	Item 36
	with		
6	Nut	ASNA2531-8	Item 44
	and if necessary		
6	Washer	NSA5372-816AX	
	and/or		
6	Washer	NSA5372-816EX	
	and/or		
6	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K9-15	Item 73
8	Screw	ABS1418K9-16	Item 74
6	Screw	ABS1418K9-17	Item 75
	with		
16	Nut	ASNA2532-9	Item 76
	and if necessary		
16	Washer	NSA5372-916AX	
	and/or		
16	Washer	NSA5372-916EX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

and/or

16 Washer NSA5372-916BX

and

2 Screw ABS1418K7-23 Item 80

with

2 Nut ASNA2531-7 Item 11

and if necessary

2 Washer NSA5372-716AX

and/or

2 Washer NSA5372-716EX

and/or

2 Washer NSA5372-716BX

NOTE: Install the screw in accordance with the installation principle given in

the repair instruction R57102001.

NOTE: If necessary, install the washer in accordance with the definition of

the washer thickness given in the Fig. A-FCDAA Sheet 01.

NOTE: Wet assembly, apply:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

<u>NOTE</u>: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

- Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

NOTE: Inside the wing center box, apply on the nuts:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Polysulfide Sealant- 06ABB1 As required Fuel Tank Fillet Adhesion Promoter- 06PAG1 As required For Polysulfide Sealant

If removed, install:

Channel-Formed

1

1

Duct

with

The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

Item (51)

Item (52)

Retained at removal

Retained at

•			(01)	removal
	with			
7	Bolt	EN6115T2-3	Item 60	
3	Bolt	EN6115T2-2	Item 62	
10	Nut	ASNA2536-2	Item 61	
	and/or			
1	Web 4 assy		Item (50)	Retained at removal
	attached with			
7	Bolt	EN6115T2-3	Item 60	
7	Nut	ASNA2536-2	Item 61	
	NOTE:	Apply to the interface	of the structure	and all the parts:
	Polysulfide Sealant- General Purpose Brushable	06AAA1 A	As required	
	2 The cooling du	uct.		
	Refer to Fig. F	A-FDAAA Sheet 01		
1	Duct		Item (53)	Retained at removal

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

1 Clamp Item (63) Retained at removal

8 Screw Item (64) Retained at removal

8 Washer NAS1149D0332K Item 65

# (4) Subtask 571140-833-004-002 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side

	Work Zones and Access Panels				
	Zone Access/Work location				
From	142	Access	Access Panel 148AZ		
		Work location Rib 1			
То	640	Access Panel 640AB, Panel 640BZ			
		Work location	Rib 1		

Manpower Resources					
Manhours	16.00				
Minimum number of person	2				
Subtask elapsed time	10.00				
Skills	AIRFRAME NON DESTRUCTIVE TESTING				

### Material necessary to do the job

Kit 571140A02R04 QTY (UM) ITEM NEW PART N° **KEYWORD** SEE NOTES 60 EN6115T2-3 14 **BOLT** 17 61 ASNA2536-2 NUT 62 3 **BOLT** EN6115T2-2 8 **WASHER** NAS1149D0332K

Comp	Component COMPA01					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
11	ASNA2531-7	2	NUT			
31	ABS1418K8-13	1	SCREW			
32	ABS1418K8-14	7	SCREW			
33	ABS1418K8-18	8	SCREW			
34	ABS1418K8-19	9	SCREW			
35	ASNA2532-8	34	NUT			
36	ABS1418K8-21	2	SCREW			
37	ABS1418K8-26	2	SCREW			
38	ABS1418K8-17	6	SCREW	·		
43	ABS1418K8-25	2	SCREW			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
44	ASNA2531-8	6	NUIT	
73	ABS1418K9-15	2	SCREW	
74	ABS1418K9-16	8	SCREW	
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	40	WASHER	
	NSA5372-816BX	40	WASHER	
	NSA5372-816EX	40	WASHER	
	NSA5372-916AX	16	WASHER	
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

Consi	Consumable CMLA01						
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES			
	Wash Primer - Structure	04CMA2	As required				
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required				
	Top Coat Polyurethane - External Structure	04JAA3	As required				
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required				
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required				
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required				

Kit to	Kit tool 571140T02R00						
ITEM	PART N°	KEYWORD	QTY	SEE NOTES			
	98D57103002000	Test	1				

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References			
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001		
Drawing	R57102001		
Non Destructive Test Manual (NTM)	51-10-01 PART 6		
Structural Repair Manual (SRM)	51-24-00		
	51-42-11		
	51-43-00		
Fig. A-FCBAA	Sheet 01		
RH Side, Replacement of the Lower	Sheet 02		
Panel Fasteners	Sheet 03		
	Sheet 04		
	Sheet 05		
	Sheet 06		
	Sheet 07		
Fig. A-FCDAA	Sheet 01		
Definition of the Washer Thickness for			
the New Taperlok			
Fig. A-FDAAA	Sheet 01		
Removal/Installation of the Cooling Duct			
Fig. A-FDBAA	Sheet 01		
Removal/Installation of the Belly Fairing	Sheet 02		
Structure	Sheet 03		

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FCBAA Sheet 07

- (a) Depending on the result of the inspection, remove for access :
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1	Duct	Item (54)	Retain
1	Duct	Item (52)	Retain
	attached with		
1	Clamp	Item (63)	Retain
8	Screw	Item (64)	Retain
8	Washer	Item (65)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

2 Remove the structure of the belly fairing.

1		Channel-Formed	Item (171)	Retain
		attached with		
3		Rivet	Item (62)	Discard
7		Rivet	Item (60)	Discard
10		Bush	Item (61)	Discard
		and/or		
1		Web 4 assy	Item (170)	Retain
		attached with		
7		Rivet	Item (60)	Discard
7		Bush	Item (61)	Discard
(	(b)	In accordance with the result of the inspection	n, remove the	taperlok(s)
		Refer to Fig. A-FCBAA Sheet 01 to Fig. A-FC	BAA Sheet 0	<u>4</u>
6		Screw	Item (16)	Discard
10		Screw	Item (5)	Discard
9		Screw	Item (7)	Discard
7		Screw	Item (3)	Discard
2		Screw	Item (14)	Discard
1		Screw	Item (1)	Discard
2		Screw	Item (12)	Discard
2		Screw	Item (70)	Discard
8		Screw	Item (71)	Discard
6		Screw	Item (72)	Discard
2		Screw	Item (77)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

2	Screw	Item (79)	Discard
1	Screw	Item (81)	Discard

<u>NOTE</u>: The nuts are removed during the inspection.

- (c) Do a rototest inspection of the holes for cracks refer to NTM 51-10-01 PART 6.
  - 1 If cracks are found, contact AIRBUS before any further work.
  - 2 If no crack is found, do the following steps.
- (d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

<u>NOTE</u>: To prevent any accidental damage, we recommend to train to oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCBAA Sheet 01, Fig. A-FCBAA Sheet 02, Fig. A-FCBAA Sheet 05, Fig. A-FCBAA Sheet 06, Fig. A-FCBAA Sheet 07

6	Screw	ABS1418K8-17	Item 38
8	Screw	ABS1418K8-18	Item 33
9	Screw	ABS1418K8-19	Item 34
1	Screw	ABS1418K8-13	Item 31
7	Screw	ABS1418K8-14	Item 32
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		
34	Nut	ASNA2532-8	Item 35
	and if necessary		
34	Washer	NSA5372-816AX	
	and/or		
34	Washer	NSA5372-816EX	
	and/or		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

34	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K8-25	Item 43
2	Screw	ABS1418K8-26	Item 37
2	Screw	ABS1418K8-21	Item 36
	with		
6	Nut	ASNA2531-8	Item 44
	and if necessary		
6	Washer	NSA5372-816AX	
	and/or		
6	Washer	NSA5372-816EX	
	and/or		
6	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K9-15	Item 73
8	Screw	ABS1418K9-16	Item 74
6	Screw	ABS1418K9-17	Item 75
	with		
16	Nut	ASNA2532-9	Item 76
	and if necessary		
16	Washer	NSA5372-916AX	
	and/or		
16	Washer	NSA5372-916EX	
	and/or		
16	Washer	NSA5372-916BX	
	and		
2	Screw	ABS1418K7-23	Item 80
	with		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

2 Nut ASNA2531-7 Item 11

and if necessary

2 Washer NSA5372-716AX

and/or

2 Washer NSA5372-716EX

and/or

2 Washer NSA5372-716BX

NOTE: Install the screw in accordance with the installation principle given in

the repair instruction R57102001.

NOTE: If necessary, install the washer in accordance with the definition of

the washer thickness given in the Fig. A-FCDAA Sheet 01.

NOTE: Wet assembly, apply:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

<u>NOTE</u>: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

- Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

<u>NOTE</u>: Inside the wing center box, apply on the nuts :

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 92

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

## SERVICE BULLETIN

(f) If removed.	install	:
-----------------	---------	---

1 The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

1	Channel-Formed		Item (171)	Retained at removal
	with			
7	Bolt	EN6115T2-3	Item 60	
3	Bolt	EN6115T2-2	Item 62	
10	Nut	ASNA2536-2	Item 61	
	and/or			
1	Web 4 assy		Item (170)	Retained at removal
	attached with	1		
7	Bolt	EN6115T2-3	Item 60	
7	Nut	ASNA2536-2	Item 61	
	NOTE:	Apply to the interface of	the structure	and all the parts:
	Polysulfide Sealant General Purpose Brushable	- 06AAA1 As	required	
	General Purpose		required	
	General Purpose Brushable  2 The cooling of		required	
1	General Purpose Brushable  2 The cooling of	duct.	required  Item (54)	Retained at removal
1	General Purpose Brushable  2 The cooling of Refer to Fig.	duct.		
	General Purpose Brushable  2 The cooling of Refer to Fig.  Duct	duct.	Item (54)	removal Retained at
	General Purpose Brushable  2 The cooling of Refer to Fig.  Duct  Duct	duct.	Item (54)	removal Retained at
1	General Purpose Brushable  2 The cooling of Refer to Fig.  Duct  Duct  with	duct.	Item (54) Item (52)	removal  Retained at removal  Retained at

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

### \*\*CONF ALL

#### D. TEST

#### \*\*CONF 001

### (1) Subtask 571140-710-001-001 - Test

Manpower Resou	rces
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 20-28-00-720-005	
	Task 20-28-00-869-002	
	Task 28-11-00-280-002	
	Task 28-21-00-710-006	
	Task 57-17-11-400-001	
	Task 57-27-11-400-001	

NOTE:

This test procedure is to be accomplished after the installation of the parts removed for the access SUBTASK 571137-410-001 001 Install/Close Items Removed/Opened for Access on the LH Side, SUBTASK 571137-410-002 001 Install/Close Items Removed/Opened for Access on the RH Side, SUBTASK 571137-410-005 001 Install the Fuel Strainer, LH Side and SUBTASK 571137-410-006 001 Install the Fuel Strainer, RH Side.

## (a) Job Set-up:

- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.

### (b) Test:

- <u>1</u> Do the test procedure as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- Do the test procedure as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.
- Do a fuel tanks leak checks (only leak test of the center tank or/and leak test of the wing tanks - without fuel - by the local blowing procedure), refer to AMM Task 28-11-00-280-002.

NOTE: Do this test on the taperlok bolts inspected by this Service Bulletin.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

4 For all the access panels and covers removed during the preparation procedure, do a check of the electrical bonding (external metal surfaces/parts (hinges or fixed)) refer to AMM Task 20-28-00-720-005.

NOTE: For the

For the maximum permitted resistance values : refer to the

table AMM Task 20-28-00-869-002.

#### \*\*CONF 002

### (1) Subtask 571140-710-001-001 - Test

Manpower	Resources
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 20-28-00-720-005	
	Task 20-28-00-869-002	
	Task 28-11-00-280-002	
	Task 28-21-00-710-006	
	Task 57-17-11-400-001	
	Task 57-27-11-400-001	

NOTE:

This test procedure is to be accomplished after the installation of the parts removed for the access SUBTASK 571137-410-001 001 Install/Close Items Removed/Opened for Access on the LH Side, SUBTASK 571137-410-002 001 Install/Close Items Removed/Opened for Access on the RH Side, SUBTASK 571137-410-005 001 Install the Fuel Strainer, LH Side and SUBTASK 571137-410-006 001 Install the Fuel Strainer, RH Side.

### (a) Job Set-up:

- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.

## (b) Test:

- <u>1</u> Do the test procedure as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- Do the test procedure as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.
- On a fuel tanks leak checks (only leak test of the center tank or/and leak test of the wing tanks without fuel by the local blowing procedure), refer to AMM Task 28-11-00-280-002.

NOTE: Do this test on the taperlok bolts inspected by this Service

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 95

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

#### SERVICE BULLETIN

Bulletin.

4 For all the access panels and covers removed during the preparation procedure, do a check of the electrical bonding (external metal surfaces/parts (hinges or fixed)) refer to AMM Task 20-28-00-720-005.

NOTE:

For the maximum permitted resistance values : refer to the table AMM Task 20-28-00-869-002.

### \*\*CONF ALL

#### E. CLOSE-UP

### \*\*CONF 001

(1) Subtask 571140-410-001-001 - Install/Close Items Removed/Opened for Access on the LH Side

Manp	power Resources
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-001 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 540BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 540AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 147AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

# (2) Subtask 571140-410-002-001 - Install/Close Items Removed/Opened for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

References			
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001		
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01		

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-001 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 640BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 640AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 148AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels, 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.

## (3) Subtask 571140-410-005-001 - Install the Fuel Strainer, LH Side

Manpower Resource	ces
Skills	NON SPECIFIC

Material necessary to do the job

Kit 571140A01R04				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
69	NAS1149F0332P	2	WASHER	

References	
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001
Structural Repair Manual (SRM)	51-42-11

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References	
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: The parts removed for the access must be installed before the

SUBTASK 571137-700-001 001 Testing.

NOTE: This step is only valid for aircraft on which Service Bulletin No.

A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for LH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly	Item (55)	Retained at removal
1	Strainer Assembly	Item (57)	Retained at removal
	with		
8	Bolt	Item (66)	Retained at removal
2	Bolt	Item (67)	Retained at removal
2	Bolt	Item (68)	Retained at removal

2 Washer NAS1149F0332P Item 69

## (4) Subtask 571140-410-006-001 - Install the Fuel Strainer, RH Side

Manpower Resources	
Skills	NON SPECIFIC

## Material necessary to do the job

Kit 57	′1140A01R04			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
69	NAS1149F0332P	2	WASHER	

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Structural Repair Manual (SRM)	51-42-11	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References	
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: The parts removed for the access must be installed before the

SUBTASK 571137-700-001 001 Testing.

NOTE: This step is only valid for aircraft on which Service Bulletin No.

A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for RH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly		Item (56)	Retained at removal
1	Strainer Assembly		Item (58)	Retained at removal
	with			
8	Bolt		Item (66)	Retained at removal
2	Bolt		Item (67)	Retained at removal
2	Bolt		Item (68)	Retained at removal
2	Washer	NAS1149F0332P	Item 69	

## (5) Subtask 571140-942-001-001 - Close-up

	lanpower Resources
Skills	NON SPECIFIC

References	
Aircraft Maintenance Manual (AMM)	Task 28-25-00-650-001
	Task 32-12-00-410-001

- (a) Refuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (b) Refuel the center tank, refer to AMM Task 28-25-00-650-001.
  - (c) Close the main landing gear doors, refer to AMM Task 32-12-00-410-001.
  - (d) Remove the access platform(s).

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

(e) Put the aircraft back to its initial configuration.

## \*\*CONF 002

(1) Subtask 571140-410-001-001 - Install/Close Items Removed/Opened for Access on the LH Side

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-001 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 540BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 540AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 147AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.
- (2) Subtask 571140-410-002-001 Install/Close Items Removed/Opened for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

Ref	erences
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-001 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 640BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 640AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 148AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels, 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.

## (3) Subtask 571140-410-005-002 - Install the Fuel Strainer, LH Side

Manp	power Resources
Skills	NON SPECIFIC

## Material necessary to do the job

Kit 57	′1140A02R04			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
69	NAS1149F0332P	2	WASHER	

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-001 001 Testing.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for LH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly		Item (55)	Retained at removal
1	Strainer Assembly		Item (57)	Retained at removal
	with			
8	Bolt		Item (66)	Retained at removal
2	Bolt		Item (67)	Retained at removal
2	Bolt		Item (68)	Retained at removal
2	Washer	NAS1149F0332P	Item 69	

## (4) Subtask 571140-410-006-002 - Install the Fuel Strainer, RH Side

	Manpower Resou	rces
Skills		NON SPECIFIC

## Material necessary to do the job

Kit 57	71140A02R04			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
69	NAS1149F0332P	2	WASHER	

References	
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001
Structural Repair Manual (SRM)	51-42-11
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: The parts removed for the access must be installed before the

SUBTASK 571137-700-001 001 Testing.

NOTE: This step is only valid for aircraft on which Service Bulletin No.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN

A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for RH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly		Item (56)	Retained at removal
1	Strainer Assembly		Item (58)	Retained at removal
	with			
8	Bolt		Item (66)	Retained at removal
2	Bolt		Item (67)	Retained at removal
2	Bolt		Item (68)	Retained at removal
2	Washer	NAS1149F0332P	Item 69	

## (5) Subtask 571140-942-001-001 - Close-up

Manpower Resources	
Skills	NON SPECIFIC

References	
Aircraft Maintenance Manual (AMM)	Task 28-25-00-650-001
	Task 32-12-00-410-001

- (a) Refuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (b) Refuel the center tank, refer to AMM Task 28-25-00-650-001.
  - (c) Close the main landing gear doors, refer to AMM Task 32-12-00-410-001.
  - (d) Remove the access platform(s).
  - (e) Put the aircraft back to its initial configuration.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

This Page Intentionally Left Blank

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

#### Task 571140-832-802-001 - INSPECTION ADDITIONAL WORK

## \*\*CONF ALL

WARNING: MAKE SURE THAT YOU OBEY ALL THE WARNINGS AND ALL THE CAUTIONS

INCLUDED IN THE REFERENCED PROCEDURES.

CAUTION: ALWAYS OBEY THE PRECAUTIONS THAT FOLLOW TO KEEP

ELECTRICAL WIRING IN A SATISFACTORY CONDITION (ELECTRICALLY AND MECHANICALLY SERVICEABLE). WHEN YOU DO MAINTENANCE WORK, REPAIRS OR MODIFICATIONS, ALWAYS KEEP ELECTRICAL WIRING, COMPONENTS AND THE WORK AREA AS CLEAN AS POSSIBLE. TO DO

THIS:

 PUT PROTECTION, SUCH AS PLASTIC SHEETING, CLOTHS, ETC; AS NECESSARY ON WIRING AND COMPONENTS.

 REGULARLY REMOVE ALL SHAVINGS, UNWANTED MATERIAL AND OTHER CONTAMINATION.

THESE PRECAUTIONS WILL DECREASE THE RISK OF CONTAMINATION AND DAMAGE TO THE ELECTRICAL WIRING INSTALLATION.

IN CASE OF CONTAMINATION REFER TO ESPM 20-55-00.

NOTE: The accomplishment instructions of this Service Bulletin include procedures given

in other documents or in other sections of the Service Bulletin. When the words 'refer to' are used and the operator has a procedure accepted by the local authority he belongs to, the accepted alternative procedure can be used. When the words 'in

accordance with' are used then the given procedure must be followed.

NOTE: The access and close-up instructions, not comprising return to service tests, in this

Service Bulletin do not constitute or affect the technical intent of the Service Bulletin. Operators can therefore, as deemed necessary, omit or add access and/or close-up steps to add flexibility to their maintenance operations as long as the

technical intent of the Service Bulletin is met within the set parameters.

NOTE: Manual titles given in the accomplishment instructions are referred to by acronyms.

Refer to paragraph 1.J., References, for the definition of acronyms.

NOTE: Discarded parts must be managed at the operator's discretion.

NOTE: This Service Bulletin contains the instructions for the on-aircraft maintenance

necessary to ensure the continued airworthiness of the aircraft.

For any deviations to the instructions contained herein, contact AIRBUS for further

instructions and approval.

NOTE: The purpose of flowcharts is to supplement the information given in the Procedure

and Compliance paragraphs and not to serve as the primary source for tasks or

compliance times given in this Service Bulletin.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### **Task Associated Data**

## \*\*CONF 001

Zone		
From 141 to 540		
From 142 to 640		
Access		
Panel	Panel 147AZ 148AZ 540AB 540BZ 640AB 640BZ	
Manpower		
TOTAL MANHOURS 59.00		
ELAPSED TIME (HOURS) 15.50		15.50

### \*\*CONF 002

Zone		
From 141 to 540		
From 142 to 640		
Access		
Panel 147AZ 148AZ 540AB 540BZ 640AB 640BZ		640AB 640BZ
Manpower		
TOTAL MANHOURS 37.00		
ELAPSED TIME (HOURS) 10.00		10.00

## \*\*CONF ALL

## A. **GENERAL**

### \*\*CONF 001

## (1) Subtask 571140-910-003-001 - Standard Practices

Manpower Resources	
Skills	NON SPECIFIC

References		
Consumable Material List (CML)		
Structural Repair Manual (SRM)	51-42-11	

- (a) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (b) Remove and install fasteners in accordance with SRM 51-42-11.

## (2) Subtask 571140-839-003-001 - Administrative

Manpower Resources	
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

### \*\*CONF 002

## (1) Subtask 571140-910-003-001 - Standard Practices

Manpower Re	sources
Skills	NON SPECIFIC

References	
Consumable Material List (CML)	
Structural Repair Manual (SRM)	51-42-11

- (a) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (b) Remove and install fasteners in accordance with SRM 51-42-11.

### (2) Subtask 571140-839-003-001 - Administrative

Manpower Resources	
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

## \*\*CONF ALL

### **B. PREPARATION**

### \*\*CONF 001

## (1) Subtask 571140-941-002-001 - Job Set-up

	Manpower Resources	
Skills		NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 12-34-24-869-002	
	Task 28-00-00-910-001	
	Task 28-10-00-910-004	
	Task 28-25-00-650-001	
	Task 32-12-00-010-001	

NOTE:

The items given in this note shall be considered as the basic Aircraft configuration before you start a maintenance task:

- Aircraft on the ground resting on landing gear (the ground safety locks and the wheel chocks are in position on the landing gear),
- Engine shut down, thrust reversers closed and locked,
- Aircraft in clean configuration,
- Parking brake applied,

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- Aircraft electrical network de-energized,
- Hydraulic systems depressurized,
- Access to the cockpit and cabin is available,
- All circuit breakers are in closed position,
- All controls in NORM, AUTO or OFF position.
- (a) Make sure that the aircraft is electrically grounded, refer to AMM Task 12-34-24-869-002.
- (b) Put an access platform in position at zones Z540 and Z640.
- (c) Defuel the center tank, refer to AMM Task 28-25-00-650-001.
- (d) Defuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (e) Degas and ventilate the center tank and the wing tanks, refer to AMM Task 28-00-00-910-001 and AMM Task 28-10-00-910-004.
- (f) Open the main landing gear doors, refer to AMM Task 32-12-00-010-001.

### (2) Subtask 571140-010-003-001 - Remove/Open for Access on the LH Side

Manpower Resources	
Skills	NON SPECIFIC

References	
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001 Task 28-21-54-000-001 Task 53-35-11-000-001 Task 57-17-11-000-001 Task 57-27-11-000-001 Task 57-27-12-000-001
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01

- (a) Remove the access cover 147AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 540AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 540BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-001.
- (f) If necessary, remove the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

## (3) Subtask 571140-010-004-001 - Remove/Open for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

References	
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001
	Task 28-21-54-000-801
	Task 53-35-11-000-001
	Task 57-17-11-000-001
	Task 57-27-11-000-001
	Task 57-27-12-000-001
Fig. A-FDCAA	Sheet 01
Removal/Installation of the Fuel Pump	
Strainer Covers	

- (a) Remove the access cover 148AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 640AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 640BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-801.
- (f) If necessary, remove the panels 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

## (4) Subtask 571140-010-007-001 - Remove the Fuel Strainer, LH Side

Manpower Resources	
Skills	NON SPECIFIC

References	
Structural Repair Manual (SRM)	51-42-11
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

Remove for access the fuel strainer for LH side:
 Refer to <u>Fig. A-FDDAA Sheet 01</u> and <u>Fig. A-FDDAA Sheet 02</u>
 In accordance with SRM 51-42-11.

1 Strainer Assembly Item (55) Retain

1 Strainer Assembly Item (57) Retain

attached with:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

8	Bolt	Item (66)	Retain
2	Bolt	Item (67)	Retain
2	Bolt	Item (68)	Retain
2	Washer	Item (69)	Discard

## (5) Subtask 571140-010-008-001 - Remove the Fuel Strainer, RH Side

Manpower Resources	
Skills	NON SPECIFIC

References	
Structural Repair Manual (SRM)	51-42-11
Fig. A-FDDAA	Sheet 01
Removal/Installation of the Fuel Strainer	Sheet 02

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

- Remove for access the fuel strainer for RH side: Refer to <u>Fig. A-FDDAA Sheet 01</u> and <u>Fig. A-FDDAA Sheet 02</u> In accordance with SRM 51-42-11.

1	Strainer Assembly	Item (56)	Retain
1	Strainer Assembly	Item (58)	Retain
	attached with:		
8	Bolt	Item (66)	Retain
2	Bolt	Item (67)	Retain
2	Bolt	Item (68)	Retain
2	Washer	Item (69)	Discard

### \*\*CONF 002

## (1) Subtask 571140-941-002-001 - Job Set-up

Manpower Resources	
Skills	NON SPECIFIC

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References		
Aircraft Maintenance Manual (AMM)	Task 12-34-24-869-002	
	Task 28-00-00-910-001	
	Task 28-10-00-910-004	
	Task 28-25-00-650-001	
	Task 32-12-00-010-001	

NOTE:

The items given in this note shall be considered as the basic Aircraft configuration before you start a maintenance task:

- Aircraft on the ground resting on landing gear (the ground safety locks and the wheel chocks are in position on the landing gear),
- Engine shut down, thrust reversers closed and locked,
- Aircraft in clean configuration,
- Parking brake applied,
- Aircraft electrical network de-energized,
- Hydraulic systems depressurized,
- Access to the cockpit and cabin is available,
- All circuit breakers are in closed position,
- All controls in NORM, AUTO or OFF position.
- (a) Make sure that the aircraft is electrically grounded, refer to AMM Task 12-34-24-869-002.
- (b) Put an access platform in position at zones Z540 and Z640.
- (c) Defuel the center tank, refer to AMM Task 28-25-00-650-001.
- (d) Defuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (e) Degas and ventilate the center tank and the wing tanks, refer to AMM Task 28-00-00-910-001 and AMM Task 28-10-00-910-004.
- (f) Open the main landing gear doors, refer to AMM Task 32-12-00-010-001.
- (2) Subtask 571140-010-003-001 Remove/Open for Access on the LH Side

Manpower Resources	
Skills	NON SPECIFIC

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001 Task 28-21-54-000-001 Task 53-35-11-000-001 Task 57-17-11-000-001 Task 57-27-11-000-001 Task 57-27-12-000-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

- (a) Remove the access cover 147AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 540AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 540BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-001.
- (f) If necessary, remove the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

### (3) Subtask 571140-010-004-001 - Remove/Open for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-000-001 Task 28-21-54-000-801	
	Task 53-35-11-000-001	
	Task 57-17-11-000-001	
	Task 57-27-11-000-001	
	Task 57-27-12-000-001	
Fig. A-FDCAA	Sheet 01	
Removal/Installation of the Fuel Pump		
Strainer Covers		

- (a) Remove the access cover 148AZ, refer to AMM Task 57-17-11-000-001.
- (b) Remove the wing access panel 640AB, refer to AMM Task 57-27-11-000-001.
- (c) Open the fuel surge access door 640BZ, refer to AMM Task 57-27-12-000-001.
- (d) Remove the fuel pump suction valve, refer to AMM Task 28-21-42-000-001.
- (e) Remove the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-000-801.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

(f) If necessary, remove the panels 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-000-001.

### (4) Subtask 571140-010-007-001 - Remove the Fuel Strainer, LH Side

Manpower Resources	
Skills	NON SPECIFIC

References		
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

Remove for access the fuel strainer for LH side:
 Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02
 In accordance with SRM 51-42-11.

1	Strainer Assembly	Item (55)	Retain
1	Strainer Assembly	Item (57)	Retain
	attached with:		
8	Bolt	Item (66)	Retain
2	Bolt	Item (67)	Retain
2	Bolt	Item (68)	Retain
2	Washer	Item (69)	Discard

## (5) Subtask 571140-010-008-001 - Remove the Fuel Strainer, RH Side

Manpower Resource	es
Skills	NON SPECIFIC

References		
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

Remove for access the fuel strainer for RH side:
 Refer to <u>Fig. A-FDDAA Sheet 01</u> and <u>Fig. A-FDDAA Sheet 02</u>
 In accordance with SRM 51-42-11.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN

1	Strainer Assembly	Item (56)	Retain
1	Strainer Assembly	Item (58)	Retain
	attached with:		
8	Bolt	Item (66)	Retain
2	Bolt	Item (67)	Retain
2	Bolt	Item (68)	Retain
2	Washer	Item (69)	Discard

## \*\*CONF ALL

## C. PROCEDURE

## \*\*CONF 001

(1) Subtask 571140-832-003-001 - LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK

Work Zones and Access Panels				
	Zone	Access/Work location		
From	141	Access	Panel 147AZ	
		Work location	Rib 1	
То	540	Access	Panel 540AB, Panel 540BZ	
		Work location	Rib 1	

Manpower Resources		
Manhours	21.00	
Minimum number of person	2	
Subtask elapsed time	10.50	
Skills	AIRFRAME	

Matavial passages to do the inte	
Material necessary to do the job	

Cons	sumable CMLA01			
ITEM	DESCRIPTION	REFERENCE TO	QTY PER A/C	SEE
		CML MAT. No.		NOTES
	Non Aqueous Cleaner	08BAA9	As required	

Kit tool 571140T01R01				
ITEM PART N°		KEYWORD	QTY	SEE NOTES
	98D57103001000	Gage	1	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References			
In Service Information (ISI)	00.00.00179		
Structural Repair Manual (SRM)	51-42-11		
Fig. A-FBCAA	Sheet 01		
Thread Damage			
Fig. A-FCEAA	Sheet 01		
Inspection of the Fasteners for the	Sheet 02		
ADDITIONAL WORK	Sheet 03		
Fig. A-FCFAA	Sheet 01		
LH Side, Replacement of the Lower	Sheet 02		
Panel Fasteners for the ADDITIONAL	Sheet 03		
WORK	Sheet 04		
	Sheet 05		
	Sheet 06		
	Sheet 07		
Fig. A-FFBAA	Sheet 01		
Flow Chart for the ADDITIONAL WORK			

(a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFBAA Sheet 01

Refer to Fig. A-FBCAA Sheet 01.

Refer to Fig. A-FCEAA Sheet 01 to Fig. A-FCEAA Sheet 03

Refer to Fig. A-FCFAA Sheet 01 to Fig. A-FCFAA Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

2 Remove the nuts:

Refer to Fig. A-FCFAA Sheet 01 to Fig. A-FCFAA Sheet 04

11	Nut	NSA5457-7E	Item (10)	Discard
	or			
11	Nut	NAS1727-7E	Item (10)	Discard
	or			
11	Nut	NSA5151-7	Item (10)	Discard
	and			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

2	Nut	NAS1726-7E	Item (11)	Discard
	or			
2	Nut	NSA5050-7	Item (11)	Discard
	and			
16	Nut	NSA5457-8E	Item (13)	Discard
	or			
16	Nut	NAS1727-8E	Item (13)	Discard
	or			
16	Nut	NSA5151-8	Item (13)	Discard
	and			
2	Nut	NAS1726-6E	Item (15)	Discard
	or			
2	Nut	NSA5050-6	Item (15)	Discard

NOTE: Identify the location of each removed nut.

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

98D57103001000 Gage set 1

- 1 If taperlok gage fit and move:
  - <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
    - <1> If thread marks are found caused by an incorrect installation:
      - <a> Apply SUBTASK 571140-833-007 001 Replace Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
    - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-007 001 Replace Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
    - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-005 001 Replacethe the Nuts on the LH Side before next flight.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- 2 If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - a Apply SUBTASK 571140-833-007 001 Replace Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
- <u>3</u> If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-005 001 Replace the Nuts on the LH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

NOTE: Uploading the Inspection Report sheet is not Required for Compliance.

(2) Subtask 571140-832-004-001 - RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK

	Work Zones and Access Panels			
	Zone Access/Work location			
From	142	Access	Panel 148AZ	
		Work location	Rib 1	
То	640	Access	Panel 640AB, Panel 640BZ	
		Work location	Rib 1	

Manpower Resources				
Manhours	21.00			
Minimum number of person	2			
Subtask elapsed time	10.50			
Skills	AIRFRAME			

## Material necessary to do the job

Cons	Consumable CMLA01					
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES		
	Non Aqueous Cleaner	08BAA9	As required			

Kit to	Kit tool 571140T01R01					
ITEM	PART N°	KEYWORD	QTY	SEE NOTES		
	98D57103001000	Gage	1			

Ref	erences
In Service Information (ISI)	00.00.00179
Structural Repair Manual (SRM)	51-42-11

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References				
Fig. A-FBCAA	Sheet 01			
Thread Damage				
Fig. A-FCEAA	Sheet 01			
Inspection of the Fasteners for the	Sheet 02			
ADDITIONAL WORK	Sheet 03			
Fig. A-FCGAA	Sheet 01			
RH Side, Replacement of the Lower	Sheet 02			
Panel Fasteners for the ADDITIONAL	Sheet 03			
WORK	Sheet 04			
	Sheet 05			
	Sheet 06			
	Sheet 07			
Fig. A-FFBAA	Sheet 01			
Flow Chart for the ADDITIONAL WORK				

(a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFBAA Sheet 01

Refer to Fig. A-FBCAA Sheet 01.

Refer to Fig. A-FCEAA Sheet 01 to Fig. A-FCEAA Sheet 03

Refer to Fig. A-FCGAA Sheet 01 to Fig. A-FCGAA Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

2 Remove the nuts:

Refer to Fig. A-FCGAA Sheet 01 to Fig. A-FCGAA Sheet 04

11	Nut	NSA5457-7E	Item (10)	Discard
	or			
11	Nut	NAS1727-7E	Item (10)	Discard
	or			
11	Nut	NSA5151-7	Item (10)	Discard
	and			
2	Nut	NAS1726-7E	Item (11)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

		or			
2	Nut		NSA5050-7	Item (11)	Discard
		and			
16	Nut		NSA5457-8E	Item (13)	Discard
		or			
16	Nut		NAS1727-8E	Item (13)	Discard
		or			
16	Nut		NSA5151-8	Item (13)	Discard
		and			
2	Nut		NAS1726-6E	Item (15)	Discard
		or		,	
2	Nut		NSA5050-6	Item (15)	Discard
				` '	
		NOTE:	Identify the location of ea	ach removed	nut.

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

98D57103001000 Gage set 1

- 1 If taperlok gage fit and move:
  - <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
    - <1> If thread marks are found caused by an incorrect installation:
      - <a> Apply SUBTASK 571140-833-008 001 Replace Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
    - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-008 001 Replace Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
    - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-006 001 Replace the Nuts on the RH Side before next flight.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- 2 If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-008 001 Replace Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
- 3 If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-006 001 Replace the Nuts on the RH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

NOTE: Uploading the Inspection Report sheet is not Required for Compliance.

#### \*\*CONF 002

(1) Subtask 571140-832-003-002 - LH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK

Work Zones and Access Panels					
	Zone Access/Work location				
From	141	Access Panel 147AZ			
		Work location	Rib 1		
То	540	Access Panel 540AB, Panel 540BZ			
		Work location	Rib 1		

Manpower Resources				
Manhours	10.00			
Minimum number of person	2			
Subtask elapsed time	5.00			
Skills	AIRFRAME			

## Material necessary to do the job

Cons	Consumable CMLA01				
ITEM	TEM DESCRIPTION REFERENCE TO QTY PER A/C SEE CML MAT. No. NOTES				
	Non Aqueous Cleaner	08BAA9	As required		

Kit to	Kit tool 571140T01R01				
ITEM	PART N°	KEYWORD	QTY	SEE NOTES	
	98D57103001000	Gage	1		

Ref	erences
In Service Information (ISI)	00.00.00179

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References			
Structural Repair Manual (SRM)	51-42-11		
Fig. A-FBCAA	Sheet 01		
Thread Damage			
Fig. A-FCEAB	Sheet 01		
Inspection of the Fasteners for the	Sheet 02		
ADDITIONAL WORK	Sheet 03		
Fig. A-FCFAB	Sheet 01		
LH Side, Replacement of the Lower	Sheet 02		
Panel Fasteners for the ADDITIONAL	Sheet 03		
WORK	Sheet 04		
	Sheet 05		
	Sheet 06		
	Sheet 07		
Fig. A-FFBAB	Sheet 01		
Flow Chart for the ADDITIONAL WORK			

(a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFBAB Sheet 01

Refer to Fig. A-FBCAA Sheet 01.

Refer to Fig. A-FCEAB Sheet 01 to Fig. A-FCEAB Sheet 03

Refer to Fig. A-FCFAB Sheet 01 to Fig. A-FCFAB Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

2 Remove the nuts:

Refer to Fig. A-FCFAB Sheet 01 to Fig. A-FCFAB Sheet 04

7	Nut	NSA5457-7E	Item (10)	Discard
	or			
7	Nut	NAS1727-7E	Item (10)	Discard
	or			
7	Nut	NSA5151-7	Item (10)	Discard
	and			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

2	Nut	NAS1726-7E	Item (11)	Discard
	or			
2	Nut	NSA5050-7	Item (11)	Discard
	and			
16	Nut	NSA5457-8E	Item (13)	Discard
	or			
16	Nut	NAS1727-8E	Item (13)	Discard
	or			
16	Nut	NSA5151-8	Item (13)	Discard
	and			
2	Nut	NAS1726-6E	Item (15)	Discard
	or			
2	Nut	NSA5050-6	Item (15)	Discard

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

Identify the location of each removed nut.

98D57103001000 Gage set 1

1 If taperlok gage fit and move:

NOTE:

- <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
  - <1> If thread marks are found caused by an incorrect installation:
    - <a> Apply SUBTASK 571140-833-007 002 Replace Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
  - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
    - <a> Apply SUBTASK 571140-833-007 002 Replace Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
  - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
    - <a> Apply SUBTASK 571140-833-005 002 Replace the Nuts on the LH Side before next flight.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- 2 If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - a Apply SUBTASK 571140-833-007 002 Replace Taperlok with the Next Nominal Diameter Taperlok on the LH Side before next flight.
- 3 If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-005 002 Replace the Nuts on the LH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

NOTE: Uploading the Inspection Report sheet is not Required for Compliance.

(2) Subtask 571140-832-004-002 - RH Side, do a Detailed Inspection in Center and Outer Wing Box at Level of Rib1 junction, ADDITIONAL WORK

	Work Zones and Access Panels			
	Zone Access/Work location			
From	142	Access	Panel 148AZ	
		Work location	Rib 1	
То	640	Access Panel 640AB, Panel 640BZ		
		Work location	Rib 1	

Manpower Resources			
Manhours	10.00		
Minimum number of person	2		
Subtask elapsed time	5.00		
Skills	AIRFRAME		

## Material necessary to do the job

Cons	Consumable CMLA01				
ITEM	EM DESCRIPTION REFERENCE TO QTY PER A/C SEE CML MAT. No. NOTES				
	Non Aqueous Cleaner	08BAA9	As required		

Kit to	Kit tool 571140T01R01				
ITEM	PART N°	KEYWORD	QTY	SEE NOTES	
	98D57103001000	Gage	1		

References		
In Service Information (ISI)	00.00.00179	
Structural Repair Manual (SRM)	51-42-11	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References		
Fig. A-FBCAA	Sheet 01	
Thread Damage		
Fig. A-FCGAB	Sheet 01	
RH Side, Replacement of the Lower	Sheet 02	
Panel Fasteners for the ADDITIONAL	Sheet 03	
WORK	Sheet 04	
	Sheet 05	
	Sheet 06	
	Sheet 07	
Fig. A-FCEAB	Sheet 01	
Inspection of the Fasteners for the	Sheet 02	
ADDITIONAL WORK	Sheet 03	
Fig. A-FFBAB	Sheet 01	
Flow Chart for the ADDITIONAL WORK		

(a) At threshold given in the PLANNING INFORMATION Paragraph E.(2):

Do a detailed inspection of lower panels in center and outer wing box at level of rib1 junction:

In accordance with SRM 51-42-11.

Refer to Fig. A-FFBAB Sheet 01

Refer to Fig. A-FBCAA Sheet 01.

Refer to Fig. A-FCEAB Sheet 01 to Fig. A-FCEAB Sheet 03

Refer to Fig. A-FCGAB Sheet 01 to Fig. A-FCGAB Sheet 04

1 Remove the sealant on the nuts with:

Non Aqueous 08BAA9 As required Cleaner

2 Remove the nuts:

Refer to Fig. A-FCGAB Sheet 01 to Fig. A-FCGAB Sheet 04

7	Nut	NSA5457-7E	Item (10)	Discard
	or			
7	Nut	NAS1727-7E	Item (10)	Discard
	or			
7	Nut	NSA5151-7	Item (10)	Discard
	and			
2	Nut	NAS1726-7E	Item (11)	Discard

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

		or			
2	Nut		NSA5050-7	Item (11)	Discard
		and			
16	Nut		NSA5457-8E	Item (13)	Discard
		or			
16	Nut		NAS1727-8E	Item (13)	Discard
		or			
16	Nut		NSA5151-8	Item (13)	Discard
		and			
2	Nut		NAS1726-6E	Item (15)	Discard
		or			
2	Nut		NSA5050-6	Item (15)	Discard
		NOTE:	Identify the location of ea	ach removed r	nut.

(b) Check if the taperlok gage fit and move as described in the gage set procedure:

98D57103001000 Gage set 1

- 1 If taperlok gage fit and move:
  - <u>a</u> Do a visual inspection of the thread to determine the cause of thread marks found:
    - <1> If thread marks are found caused by an incorrect installation:
      - <a> Apply SUBTASK 571140-833-008 002 Replace Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
    - <2> If no thread marks are found caused by an incorrect installation but thread was damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-008 002 Replace Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
    - <3> If no thread marks are found caused by an incorrect installation and thread was not damaged during the nut removal:
      - <a> Apply SUBTASK 571140-833-006 002 Replace the Nuts on the RH Side before next flight.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

- 2 If the taperlok gage do not fit and move but thread was damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-008 002 Replace Taperlok with the Next Nominal Diameter Taperlok on the RH Side before next flight.
- 3 If the taperlok gage do not fit and move and thread was not damaged during the nut removal:
  - <u>a</u> Apply SUBTASK 571140-833-006 002 Replace the Nuts on the RH Side before next flight.
- (c) Upload the completed Inspection Report sheet given in APPENDIX 04 Inspection Report in accordance with ISI 00.00.00179.

<u>NOTE</u>: Uploading the Inspection Report sheet is not Required for Compliance.

\*\*CONF ALL

D. TEST

\*\*CONF 001

None

\*\*CONF 002

None

\*\*CONF ALL

E. CLOSE-UP

\*\*CONF 001

None

\*\*CONF 002

None

**REVISION No.: 03 - Apr 19/19** 

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

Page: 126

#### SERVICE BUILLETIN

#### Task 571140-833-802-001 - REPAIR ADDITIONAL WORK

## \*\*CONF ALL

WARNING: MAKE SURE THAT YOU OBEY ALL THE WARNINGS AND ALL THE CAUTIONS

INCLUDED IN THE REFERENCED PROCEDURES.

<u>CAUTION</u>: ALWAYS OBEY THE PRECAUTIONS THAT FOLLOW TO KEEP ELECTRICAL WIRING IN A SATISFACTORY CONDITION (ELECTRICALLY

AND MECHANICALLY SERVICEABLE). WHEN YOU DO MAINTENANCE WORK, REPAIRS OR MODIFICATIONS, ALWAYS KEEP ELECTRICAL WIRING, COMPONENTS AND THE WORK AREA AS CLEAN AS POSSIBLE. TO DO

THIS:

 PUT PROTECTION, SUCH AS PLASTIC SHEETING, CLOTHS, ETC; AS NECESSARY ON WIRING AND COMPONENTS.

 REGULARLY REMOVE ALL SHAVINGS, UNWANTED MATERIAL AND OTHER CONTAMINATION.

THESE PRECAUTIONS WILL DECREASE THE RISK OF CONTAMINATION AND DAMAGE TO THE ELECTRICAL WIRING INSTALLATION.

#### IN CASE OF CONTAMINATION REFER TO ESPM 20-55-00.

NOTE: The accomplishment instructions of this Service Bulletin include procedures given

in other documents or in other sections of the Service Bulletin. When the words 'refer to' are used and the operator has a procedure accepted by the local authority he belongs to, the accepted alternative procedure can be used. When the words 'in

accordance with' are used then the given procedure must be followed.

NOTE: The access and close-up instructions, not comprising return to service tests, in this

Service Bulletin do not constitute or affect the technical intent of the Service Bulletin. Operators can therefore, as deemed necessary, omit or add access and/or close-up steps to add flexibility to their maintenance operations as long as the

technical intent of the Service Bulletin is met within the set parameters.

NOTE: Manual titles given in the accomplishment instructions are referred to by acronyms.

Refer to paragraph 1.J., References, for the definition of acronyms.

NOTE: This Service Bulletin contains the instructions for the on-aircraft maintenance

necessary to ensure the continued airworthiness of the aircraft.

For any deviations to the instructions contained herein, contact AIRBUS for further

instructions and approval.

### **Task Associated Data**

#### \*\*CONF 001

Zone
From 141 to 540
From 142 to 640

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

Access		
Panel	147AZ 148AZ 540AB 540BZ	640AB 640BZ
Manpower		
TOTAL MANHOURS		65.50
ELAPSED TIME (HOURS)		20.50

## \*\*CONF 002

Zone			
From 141 to 540	From 141 to 540		
From 142 to 640			
Access			
Panel 147AZ 148AZ 540AB 540BZ 640AB 640BZ			
Manpower			
TOTAL MANHOURS 41.50			
ELAPSED TIME (HOURS) 14.50		14.50	

## \*\*CONF ALL

## A. GENERAL

#### \*\*CONF 001

### (1) Subtask 571140-910-004-001 - Standard Practices

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Consumable Material List (CML)		
Structural Repair Manual (SRM)	51-24-00	
	51-42-11	
	51-43-00	
	51-75-12	

- (a) Apply the sealant in accordance with SRM 51-24-00.
- (b) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (c) Remove and install fasteners in accordance with SRM 51-42-11.
- (d) Get alternative and substitute fastener data in accordance with SRM 51-43-00.
- (e) Renew the protective finish in accordance with SRM 51-75-12.
  - (f) To torque tighten the standard threaded fasteners, refer to AMM Task 20-21-11-911-001.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### (2) Subtask 571140-839-004-001 - Administrative

Manpower Resources	
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

#### \*\*CONF 002

#### (1) Subtask 571140-910-004-001 - Standard Practices

Manpower Resources	
Skills	NON SPECIFIC

References			
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001		
Consumable Material List (CML)			
Structural Repair Manual (SRM)	51-24-00		
	51-42-11		
	51-43-00		
	51-75-12		

- (a) Apply the sealant in accordance with SRM 51-24-00.
- (b) For the specification of Material Numbers (Mat. No.) given in this Service Bulletin, refer to the Consumable Material List (CML).
- (c) Remove and install fasteners in accordance with SRM 51-42-11.
- (d) Get alternative and substitute fastener data in accordance with SRM 51-43-00.
- (e) Renew the protective finish in accordance with SRM 51-75-12.
- (f) To torque tighten the standard threaded fasteners, refer to AMM Task 20-21-11-911-001.

#### (2) Subtask 571140-839-004-001 - Administrative

Manpower Resource	ces
Skills	NON SPECIFIC

Write in the applicable aircraft records that you have done all the work given in the Service Bulletin.

#### \*\*CONF ALL

#### **B. PREPARATION**

#### \*\*CONF 001

None

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 002

None

#### \*\*CONF ALL

### C. PROCEDURE

### \*\*CONF 001

# (1) Subtask 571140-833-005-001 - Replace the Nuts on the LH Side, ADDITIONAL WORK

	Work Zones and Access Panels				
	Zone Access/Work location				
From	141	Access	Access Panel 147AZ		
		Work location Rib 1			
То	540	Access Panel 540AB, Panel 540BZ			
		Work location	Rib 1		

Manpower Resources			
Manhours	10.00		
Minimum number of person	2		
Subtask elapsed time	5.00		
Skills	AIRFRAME		

#### Material necessary to do the job

Suppl	Supplementary kit 571140A01S02				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES	
10	ASNA2532-7	11	NUT		
11	ASNA2531-7	2	NUT		
13	ASNA2532-8	16	NUT		
15	ASNA2531-6	2	NUT		
	NSA5372-716AX	31	WASHER		
	NSA5372-716BX	31	WASHER		
	NSA5372-716CX	31	WASHER		
	NSA5372-716DX	31	WASHER		
	NSA5372-716EX	31	WASHER		

Supplementary kit 571140A01S03					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES	
	NSA5372-616AX	2	WASHER		
	NSA5372-616BX	2	WASHER		
	NSA5372-616CX	2	WASHER		
	NSA5372-616DX	2	WASHER		
	NSA5372-616EX	2	WASHER		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
	NSA5372-816AX	16	WASHER	
	NSA5372-816BX	16	WASHER	
	NSA5372-816CX	16	WASHER	
	NSA5372-816DX	16	WASHER	
	NSA5372-816EX	16	WASHER	

Cons	Consumable CMLA01				
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES	
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required		
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required		

References			
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001		
Structural Repair Manual (SRM)	51-42-11		
	51-43-00		
Fig. A-FCCAA	Sheet 01		
Definition of the Washer Thickness for	Sheet 02		
the Original Taperlok	Sheet 03		
Fig. A-FCFAA	Sheet 01		
LH Side, Replacement of the Lower	Sheet 02		
Panel Fasteners for the ADDITIONAL	Sheet 03		
WORK	Sheet 04		
	Sheet 05		
	Sheet 06		
	Sheet 07		

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCFAA Sheet 01, Fig. A-FCFAA Sheet 02, Fig. A-FCFAA Sheet 05, Fig. A-FCFAA Sheet 06, Fig. A-FCFAA Sheet 07

The supplementary kit 538096A01S02 includes:

11	Nut	ASNA2532-7	Item 10
2	Nut	ASNA2531-7	Item 11
16	Nut	ASNA2532-8	Item 13
2	Nut	ASNA2531-6	Item 15

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 131

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

### SERVICE BULLETIN

		with	
	31	Washer	NSA5372-716AX
		and/or	
	31	Washer	NSA5372-716BX
		and/or	
	31	Washer	NSA5372-716CX
		and/or	
	31	Washer	NSA5372-716DX
		and/or	
I	31	Washer	NSA5372-716EX
I		- The supplementary	kit 538096A01S03 includes:
	2	Washer	NSA5372-616AX
I		and/or	
	2	Washer	NSA5372-616BX
I		and/or	
I	2	Washer	NSA5372-616CX
I		and/or	
I	2	Washer	NSA5372-616DX
I		and/or	
I	2	Washer	NSA5372-616EX
I		and	
I	16	Washer	NSA5372-816AX
I		and/or	
I	16	Washer	NSA5372-816BX
I		and/or	
I	16	Washer	NSA5372-816CX
I		and/or	
I	16	Washer	NSA5372-816DX
1		and/or	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

16 Washer NSA5372-816EX

NOTE: Install the washer in accordance with the definition of the washer

thickness given in the Fig. A-FCCAA Sheet 01.

NOTE: If necessary, the installation of the three washers is approved in this

condition.

NOTE: Torque the nuts between 3.80daN and 4.60daN (342lbf.in. and

411lbf.in.).

NOTE: Inside the wing center box, apply on the nuts:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1

As required

For Polysulfide

Sealant

# (2) Subtask 571140-833-006-001 - Replace the Nuts on the RH Side, ADDITIONAL WORK

	Work Zones and Access Panels					
	Zone		Access/Work location			
From	142	Access Panel 148AZ				
		Work location Rib 1				
То	640	Access Panel 640AB, Panel 640BZ				
		Work location	Rib 1			

Manpower Resources				
Manhours	10.00			
Minimum number of person	2			
Subtask elapsed time	5.00			
Skills	AIRFRAME			

#### Material necessary to do the job

Suppl	Supplementary kit 571140A01S02					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
10	ASNA2532-7	11	NUT			
11	ASNA2531-7	2	NUT			
13	ASNA2532-8	16	NUT			
15	ASNA2531-6	2	NUT			
	NSA5372-716AX	31	WASHER			
	NSA5372-716BX	31	WASHER			
	NSA5372-716CX	31	WASHER			
	NSA5372-716DX	31	WASHER			
	NSA5372-716EX	31	WASHER			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Supplementary kit 571140A0	)1S03		
ITEM NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
NSA5372-616AX	2	WASHER	
NSA5372-616BX	2	WASHER	
NSA5372-616CX	2	WASHER	
NSA5372-616DX	2	WASHER	
NSA5372-616EX	2	WASHER	
NSA5372-816AX	16	WASHER	
NSA5372-816BX	16	WASHER	
NSA5372-816CX	16	WASHER	
NSA5372-816DX	16	WASHER	
NSA5372-816EX	16	WASHER	

Cons	Consumable CMLA01				
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES	
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required		
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required		

Ref	ferences
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001
Structural Repair Manual (SRM)	51-42-11 51-43-00
Fig. A-FCCAA Definition of the Washer Thickness for the Original Taperlok	Sheet 01 Sheet 02 Sheet 03
Fig. A-FCGAA RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK	Sheet 01 Sheet 02 Sheet 03 Sheet 04 Sheet 05 Sheet 06 Sheet 07

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCGAA Sheet 01, Fig. A-FCGAA Sheet 02, Fig. A-FCGAA Sheet 05, Fig. A-FCGAA Sheet 06, Fig. A-FCGAA Sheet 07

The supplementary kit 538096A01S02 includes:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

	11	Nut	ASNA2532-7	Item 10
	2	Nut	ASNA2531-7	Item 11
	16	Nut	ASNA2532-8	Item 13
	2	Nut	ASNA2531-6	Item 15
		with		
	31	Washer	NSA5372-716AX	
		and/or		
	31	Washer	NSA5372-716BX	
		and/or		
	31	Washer	NSA5372-716CX	
		and/or		
	31	Washer	NSA5372-716DX	
		and/or		
	31	Washer	NSA5372-716EX	
I		- The supplementary	kit 538096A01S03 ind	cludes:
I	2	Washer	NSA5372-616AX	
I		and/or		
I	2	Washer	NSA5372-616BX	
I		and/or		
I	2	Washer	NSA5372-616CX	
I		and/or		
I	2	Washer	NSA5372-616DX	
I		and/or		
I	2	Washer	NSA5372-616EX	
I		and		
I	16	Washer	NSA5372-816AX	
I		and/or		
I	16	Washer	NSA5372-816BX	
I		and/or		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

I	16	Washer	NSA5372-816CX
I		and/or	
ı	16	Washer	NSA5372-816DX
1		and/or	
1	16	Washer	NSA5372-816EX
1		NOTE:	Install the washer in accordance with the definition of the washer thickness given in the $\underline{\text{Fig. A-FCCAA Sheet 01}}$ .

NOTE: Install the washer in accordance with the definition of the washer

thickness given in the Fig. A-FCCAA Sheet 01.

NOTE: If necessary, the installation of the three washers is approved in this

condition.

NOTE: Torque the nuts between 3.80daN and 4.60daN (342lbf.in. and

411lbf.in.).

NOTE: Inside the wing center box, apply on the nuts:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

# (3) Subtask 571140-833-007-001 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side, ADDITIONAL WORK

	Work Zones and Access Panels				
	Zone		Access/Work location		
From	141	Access Panel 147AZ			
		Work location Rib 1			
То	540	Access Panel 540AB, Panel 540BZ			
		Work location	Rib 1		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Manpower ResourcesManhours13.00Minimum number of person2Subtask elapsed time6.50SkillsAIRFRAME<br/>NON DESTRUCTIVE<br/>TESTING

#### Material necessary to do the job

Suppl	Supplementary kit 571140A01S02					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
60	EN6115T2-3	14	BOLT			
61	ASNA2536-2	17	NUT			
62	EN6115T2-2	3	BOLT			
65	NAS1149D0332K	8	WASHER			

Comp	onent COMPA03			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
11	ASNA2531-7	2	NUT	
32	ABS1418K8-14	4	SCREW	
34	ABS1418K8-19	4	SCREW	
35	ASNA2532-8	11	NUT	
37	ABS1418K8-26	1	SCREW	
43	ABS1418K8-25	1	SCREW	
44	ASNA2531-8	2	NUIT	
73	ABS1418K9-15	2	SCREW	
74	ABS1418K9-16	8	SCREW	
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	13	WASHER	
	NSA5372-816BX	13	WASHER	
	NSA5372-816EX	13	WASHER	
	NSA5372-916AX	16	WASHER	
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

<u>NOTE</u>: The quantities given in the component table are for all the taperloks replacement.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

Consi	Consumable CMLA01					
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES		
	Wash Primer - Structure	04CMA2	As required			
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required			
	Top Coat Polyurethane - External Structure	04JAA3	As required			
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required			
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required			
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required			

Kit to	Kit tool 571140T02R00						
ITEM	PART N°	KEYWORD	QTY	SEE NOTES			
	98D57103002000	Test	1				

Ref	References				
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001				
Drawing	R57102001				
Non Destructive Test Manual (NTM)	51-10-01 PART 6				
Structural Repair Manual (SRM)	51-24-00				
	51-42-11				
	51-43-00				
Fig. A-FCDAA	Sheet 01				
Definition of the Washer Thickness for					
the New Taperlok					
Fig. A-FDAAA	Sheet 01				
Removal/Installation of the Cooling Duct					
Fig. A-FDBAA	Sheet 01				
Removal/Installation of the Belly Fairing	Sheet 02				
Structure	Sheet 03				
Fig. A-FCFAA	Sheet 01				
LH Side, Replacement of the Lower	Sheet 02				
Panel Fasteners for the ADDITIONAL	Sheet 03				
WORK	Sheet 04				
	Sheet 05				
	Sheet 06				
	Sheet 07				

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCFAA Sheet 01 to Fig. A-FCFAA Sheet 07

- (a) Depending on the result of the inspection, remove for access :
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1		Duct		Item (53)	Retain
1		Duo	et	Item (52)	Retain
			attached with		
1		Cla	mp	Item (63)	Retain
8		Scr	ew	Item (64)	Retain
8		Wa	sher	Item (65)	Discard
		<u>2</u>	Remove the structure of the belly fairing		
			Refer to Fig. A-FDBAA Sheet 01 to Fig.	A-FDBAA Sh	<u>eet 03</u>
1		Cha	annel-Formed	Item (51)	Retain
			attached with		
3		Riv	et	Item (62)	Discard
7		Riv	et	Item (60)	Discard
10		Bus	sh	Item (61)	Discard
			and/or		
1		We	b 4 assy	Item (50)	Retain
			attached with		
7		Riv	et	Item (60)	Discard
7		Bus	sh	Item (61)	Discard
	(b)	In a	accordance with the result of the inspection	n, remove the	taperlok(s):

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

Refer to Fig. A-FCFAA Sheet 01 to Fig. A-FCFAA Sheet 04

#### SERVICE BULLETIN

4	Screw	Item (7)	Discard
4	Screw	Item (3)	Discard
1	Screw	Item (14)	Discard
1	Screw	Item (12)	Discard
2	Screw	Item (70)	Discard
8	Screw	Item (71)	Discard
6	Screw	Item (72)	Discard
2	Screw	Item (77)	Discard
2	Screw	Item (79)	Discard
1	Screw	Item (81)	Discard

NOTE: The nuts are removed during the inspection.

- (c) Do a rototest inspection of the holes for cracks, refer to NTM 51-10-01 PART 6.
  - 1 If cracks are found, contact AIRBUS before any further work.
  - 2 If no crack is found, do the following steps.
- (d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

NOTE: To prevent any accidental damage, we recommend to train to oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCFAA Sheet 01, Fig. A-FCFAA Sheet 02, Fig. A-FCFAA Sheet 05, Fig. A-FCFAA Sheet 06, Fig. A-FCFAA Sheet 07

4	Screw	ABS1418K8-19	Item 34
4	Screw	ABS1418K8-14	Item 32
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

11	Nut	ASNA2532-8	Item 35
	and if necessary		
11	Washer	NSA5372-816AX	
	and/or		
11	Washer	NSA5372-816EX	
	and/or		
11	Washer	NSA5372-816BX	
	and		
1	Screw	ABS1418K8-25	Item 43
1	Screw	ABS1418K8-26	Item 37
	with		
2	Nut	ASNA2531-8	Item 44
	and if necessary		
2	Washer	NSA5372-816AX	
	and/or		
2	Washer	NSA5372-816EX	
	and/or		
2	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K9-15	Item 73
8	Screw	ABS1418K9-16	Item 74
6	Screw	ABS1418K9-17	Item 75
	with		
16	Nut	ASNA2532-9	Item 76
	and if necessary		
16	Washer	NSA5372-916AX	
	and/or		
16	Washer	NSA5372-916EX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

and/or

16 Washer NSA5372-916BX

and

2 Screw ABS1418K7-23 Item 80

with

2 Nut ASNA2531-7 Item 11

and if necessary

2 Washer NSA5372-716AX

and/or

2 Washer NSA5372-716EX

and/or

2 Washer NSA5372-716BX

NOTE: Install the screw in accordance with the installation principle given in

the repair instruction R57102001.

NOTE: If necessary, install the washer in accordance with the definition of

the washer thickness given in the Fig. A-FCDAA Sheet 01.

NOTE: Wet assembly, apply:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

<u>NOTE</u>: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

- Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

NOTE: Inside the wing center box, apply on the nuts:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Polysulfide Sealant- 06ABB1 As required Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required For Polysulfide Sealant

If removed, install:

1 The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

1	Channel-Formed		Item (51)	Retained at removal
	with			
7	Bolt	EN6115T2-3	Item 60	
3	Bolt	EN6115T2-2	Item 62	
10	Nut	ASNA2536-2	Item 61	
	and/or			
1	Web 4 assy		Item (50)	Retained at removal
	attached with			
7	Bolt	EN6115T2-3	Item 60	
7	Nut	ASNA2536-2	Item 61	
	NOTE:	Apply to the interface	of the structure	and all the parts:
	Polysulfide Sealant- General Purpose Brushable	06AAA1	As required	

2 The cooling duct.

Refer to Fig. A-FDAAA Sheet 01

Duct Item (53) Retained at removal
 Duct Item (52) Retained at removal
 with

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

1 Clamp Item (63) Retained at removal

8 Screw Item (64) Retained at removal

8

Washer

# (4) Subtask 571140-833-008-001 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side, ADDITIONAL WORK

Item 65

NAS1149D0332K

	Work Zones and Access Panels					
	Zone Access/Work location					
From	142	Access Panel 148AZ				
		Work location Rib 1				
То	640	Access	Panel 640AB, Panel 640BZ			
		Work location	Rib 1			

Manpower Resources					
Manhours	13.00				
Minimum number of person	2				
Subtask elapsed time	6.50				
Skills	AIRFRAME NON DESTRUCTIVE TESTING				

### Material necessary to do the job

Suppl	Supplementary kit 571140A01S02					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
60	EN6115T2-3	14	BOLT			
61	ASNA2536-2	17	NUT			
62	EN6115T2-2	3	BOLT			
65	NAS1149D0332K	8	WASHER			

Comp	Component COMPA03					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
11	ASNA2531-7	2	NUT			
32	ABS1418K8-14	4	SCREW			
34	ABS1418K8-19	4	SCREW			
35	ASNA2532-8	11	NUT			
37	ABS1418K8-26	1	SCREW			
43	ABS1418K8-25	1	SCREW			
44	ASNA2531-8	2	NUIT			
73	ABS1418K9-15	2	SCREW			
74	ABS1418K9-16	8	SCREW			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	13	WASHER	
	NSA5372-816BX	13	WASHER	
	NSA5372-816EX	13	WASHER	
	NSA5372-916AX	16	WASHER	
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

Cons	Consumable CMLA01					
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES		
	Wash Primer - Structure	04CMA2	As required			
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required			
	Top Coat Polyurethane - External Structure	04JAA3	As required			
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required			
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required			
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required			

Kit to	Kit tool 571140T02R00				
ITEM	PART N°	KEYWORD	QTY	SEE NOTES	
	98D57103002000	Test	1		

References			
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001		
Drawing	R57102001		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References				
Non Destructive Test Manual (NTM)	51-10-01 PART 6			
Structural Repair Manual (SRM)	51-24-00			
	51-42-11			
	51-43-00			
Fig. A-FCDAA	Sheet 01			
Definition of the Washer Thickness for				
the New Taperlok				
Fig. A-FDAAA	Sheet 01			
Removal/Installation of the Cooling Duct				
Fig. A-FDBAA	Sheet 01			
Removal/Installation of the Belly Fairing	Sheet 02			
Structure	Sheet 03			
Fig. A-FCGAA	Sheet 01			
RH Side, Replacement of the Lower	Sheet 02			
Panel Fasteners for the ADDITIONAL	Sheet 03			
WORK	Sheet 04			
	Sheet 05			
	Sheet 06			
	<u>Sheet 07</u>			

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCGAA Sheet 01 to Fig. A-FCGAA Sheet 07

- (a) Depending on the result of the inspection, remove for access :
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1	Duct	Item (54)	Retain
1	Duct		Retain
	attached with		
1	Clamp	Item (63)	Retain
8	Screw	Item (64)	Retain
8	Washer	Item (65)	Discard

2 Remove the structure of the belly fairing.

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

1		Channel-Formed	Item (171)	Retain
		attached with		
3		Rivet	Item (62)	Discard
7		Rivet	Item (60)	Discard
10		Bush	Item (61)	Discard
		and/or		
1		Web 4 assy	Item (170)	Retain
		attached with		
7		Rivet	Item (60)	Discard
7		Bush	Item (61)	Discard
	(b)	In accordance with the result of the inspection	n, remove the	taperlok(s):
		Refer to Fig. A-FCGAA Sheet 01 to Fig. A-FC	GAA Sheet (	<u>)4</u>
4		Screw	Item (7)	Discard
4		Screw	Item (3)	Discard
1		Screw	Item (14)	Discard
1		Screw	Item (12)	Discard
2		Screw	Item (70)	Discard
8		Screw	Item (71)	Discard
6		Screw	Item (72)	Discard
2		Screw	Item (77)	Discard
2		Screw	Item (79)	Discard
1		Screw	Item (81)	Discard
		NOTE: The nuts are removed during	the inspection	1.
	(c)	Do a rototest inspection of the holes for cracks refer to NTM 51-10-01 PART 6.		

- - 1 If cracks are found, contact AIRBUS before any further work.
  - If no crack is found, do the following steps.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

(d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

NOTE: To prevent any accidental damage, we recommend to train to

oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCGAA Sheet 01, Fig. A-FCGAA Sheet 02, Fig. A-FCGAA Sheet 05, Fig. A-FCGAA Sheet 06, Fig. A-FCGAA Sheet 07

4	Screw	ABS1418K8-19	Item 34
4	Screw	ABS1418K8-14	Item 32
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		
11	Nut	ASNA2532-8	Item 35
	and if necessary		
11	Washer	NSA5372-816AX	
	and/or		
11	Washer	NSA5372-816EX	
	and/or		
11	Washer	NSA5372-816BX	
	and		
1	Screw	ABS1418K8-25	Item 43
1	Screw	ABS1418K8-26	Item 37
	with		
2	Nut	ASNA2531-8	Item 44
	and if necessary		
2	Washer	NSA5372-816AX	
	and/or		
2	Washer	NSA5372-816EX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

	and/or				
2	Washer		NSA5372-816BX		
	and				
2	Screw		ABS1418K9-15	Item 73	
8	Screw		ABS1418K9-16	Item 74	
6	Screw		ABS1418K9-17	Item 75	
	with				
16	Nut		ASNA2532-9	Item 76	
	and if necess	sary			
16	Washer		NSA5372-916AX		
	and/or				
16	Washer		NSA5372-916EX		
	and/or				
16	Washer		NSA5372-916BX		
	and				
2	Screw		ABS1418K7-23	Item 80	
	with				
2	Nut		ASNA2531-7	Item 11	
	and if necess	sary			
2	Washer		NSA5372-716AX		
	and/or				
2	Washer		NSA5372-716EX		
	and/or				
2	Washer		NSA5372-716BX		
	NOTE:		Install the screw in accordance with the installation principle given in the repair instruction R57102001.		
	<u>NOTE</u> :			ner in accordance with the definition of the Fig. A-FCDAA Sheet 01.	
	NOTE:	Wet asse	Wet assembly, apply:		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

NOTE: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

- Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

NOTE: Inside the wing center box, apply on the nuts :

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

(f) If removed, install:

The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

1 Channel-Formed Item (171) Retained at removal with

7 Bolt EN6115T2-3 Item 60

3 Bolt EN6115T2-2 Item 62

10 Nut ASNA2536-2 Item 61

and/or

1 Web 4 assy Item (170) Retained at

removal

attached with

7 Bolt EN6115T2-3 Item 60

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 150

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

#### SERVICE BULLETIN

7 Nut ASNA2536-2 Item 61

NOTE: Apply to the interface of the structure and all the parts :

Polysulfide Sealant- 06AAA1

As required

General Purpose

Brushable

2 The cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1	Duct		Item (54)	Retained at removal
1	Duct		Item (52)	Retained at removal
	with			
1	Clamp		Item (63)	Retained at removal
8	Screw		Item (64)	Retained at removal
8	Washer	NAS1149D0332K	Item 65	

### \*\*CONF 002

# (1) Subtask 571140-833-005-002 - Replace the Nuts on the LH Side, ADDITIONAL WORK

	Work Zones and Access Panels				
	Zone		Access/Work location		
From	141	Access Panel 147AZ			
		Work location Rib 1			
То	540	Access Panel 540AB, Panel 540BZ			
		Work location	Rib 1		

Manpower Resources				
Manhours	5.00			
Minimum number of person	2			
Subtask elapsed time	2.50			
Skills	AIRFRAME			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### Material necessary to do the job

Suppl	Supplementary kit 571140A02S02					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
10	ASNA2532-7	7	NUT			
11	ASNA2531-7	2	NUT			
13	ASNA2532-8	16	NUT			
15	ASNA2531-6	2	NUT			
	NSA5372-716AX	27	WASHER			
	NSA5372-716BX	27	WASHER			
	NSA5372-716CX	27	WASHER			
	NSA5372-716DX	27	WASHER			
	NSA5372-716EX	27	WASHER			

Supp	Supplementary kit 571140A02S03						
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES			
	NSA5372-616AX	2	WASHER				
	NSA5372-616BX	2	WASHER				
	NSA5372-616CX	2	WASHER				
	NSA5372-616DX	2	WASHER				
	NSA5372-616EX	2	WASHER				
	NSA5372-816AX	16	WASHER				
	NSA5372-816BX	16	WASHER				
	NSA5372-816CX	16	WASHER				
	NSA5372-816DX	16	WASHER				
	NSA5372-816EX	16	WASHER				

Cons	Consumable CMLA01					
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES		
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required			
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required			

References				
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001			
Structural Repair Manual (SRM)	51-42-11 51-43-00			
Fig. A-FCCAA	Sheet 01			
Definition of the Washer Thickness for	Sheet 02			
the Original Taperlok	Sheet 03			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

References				
Fig. A-FCFAB	Sheet 01			
LH Side, Replacement of the Lower	Sheet 02			
Panel Fasteners for the ADDITIONAL	Sheet 03			
WORK	Sheet 04			
	Sheet 05			
	Sheet 06			
	Sheet 07			

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCFAB Sheet 01, Fig. A-FCFAB Sheet 02, Fig. A-FCFAB Sheet 05, Fig. A-FCFAB Sheet 06, Fig. A-FCFAB Sheet 07

The supplementary kit 538096A02S02 includes:

7	Nut	ASNA2532-7	Item 10
2	Nut	ASNA2531-7	Item 11
16	Nut	ASNA2532-8	Item 13
2	Nut	ASNA2531-6	Item 15
	with		
27	Washer	NSA5372-716AX	
	and/or		
27	Washer	NSA5372-716BX	
	and/or		
27	Washer	NSA5372-716CX	
	and/or		
27	Washer	NSA5372-716DX	
	and/or		
27	Washer	NSA5372-716EX	
	- The supplementary	kit 538096A02S03 in	cludes:

571140A02R03 and have not accomplished this Service Bulletin

The additional kit is valid for operators which have ordered Kit

yet.

NOTE:

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

I	2	Washer		NSA5372-616A	X
ı		and/or			
ı	2	Washer		NSA5372-616E	3X
1		and/or			
1	2	Washer		NSA5372-616C	X
1		and/or			
1	2	Washer		NSA5372-616E	)X
1		and/or			
1	2	Washer		NSA5372-616E	ΣX
ı		and			
ı	16	Washer		NSA5372-816A	λX
ı		and/or			
ı	16	Washer		NSA5372-816E	3X
I		and/or			
I	16	Washer		NSA5372-8160	X
I		and/or			
I	16	Washer		NSA5372-816D	)X
ı		and/or			
I	16	Washer		NSA5372-816E	EX
		NOTE:			cordance with the definition of the washer g. A-FCCAA Sheet 01.
		<u>NOTE</u> :	If neces		tion of the three washers is approved in this
		NOTE:	Torque 411lbf.i		en 3.80daN and 4.60daN (342lbf.in. and
		NOTE:	Inside t	he wing center bo	ox, apply on the nuts:
		Polysulfide Sea Fuel Tank Fillet		ABB1	As required
		Adhesion Prom For Polysulfide Sealant	oter- 06	PAG1	As required

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

# (2) Subtask 571140-833-006-002 - Replace the Nuts on the RH Side, ADDITIONAL WORK

	Work Zones and Access Panels					
	Zone Access/Work location					
From	142	Access	Panel 148AZ			
		Work location Rib 1				
То	640	Access Panel 640AB, Panel 640BZ				
		Work location	Rib 1			

Manpower Resources					
Manhours	5.00				
Minimum number of person	2				
Subtask elapsed time	2.50				
Skills	AIRFRAME				

### Material necessary to do the job

Supp	Supplementary kit 571140A02S02					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
10	ASNA2532-7	7	NUT			
11	ASNA2531-7	2	NUT			
13	ASNA2532-8	16	NUT			
15	ASNA2531-6	2	NUT			
	NSA5372-716AX	27	WASHER			
	NSA5372-716BX	27	WASHER			
	NSA5372-716CX	27	WASHER			
	NSA5372-716DX	27	WASHER			
	NSA5372-716EX	27	WASHER			

Suppl	Supplementary kit 571140A02S03					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
	NSA5372-616AX	2	WASHER			
	NSA5372-616BX	2	WASHER			
	NSA5372-616CX	2	WASHER			
	NSA5372-616DX	2	WASHER			
	NSA5372-616EX	2	WASHER			
	NSA5372-816AX	16	WASHER			
	NSA5372-816BX	16	WASHER			
	NSA5372-816CX	16	WASHER			
	NSA5372-816DX	16	WASHER			
	NSA5372-816EX	16	WASHER			

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Cons	Consumable CMLA01						
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES			
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required				
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required				

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Structural Repair Manual (SRM)	51-42-11 51-43-00	
Fig. A-FCCAA Definition of the Washer Thickness for the Original Taperlok	Sheet 01 Sheet 02 Sheet 03	
Fig. A-FCGAB RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK	<u>Sheet 01</u> <u>Sheet 02</u> <u>Sheet 03</u> <u>Sheet 04</u> <u>Sheet 05</u> <u>Sheet 06</u> <u>Sheet 07</u>	

NOTE: The nuts are removed during the inspection.

(a) Install the nuts.

In accordance with SRM 51-42-11 and SRM 51-43-00.

Refer to AMM Task 20-21-11-911-001.

Refer to Fig. A-FCGAB Sheet 01, Fig. A-FCGAB Sheet 02, Fig. A-FCGAB Sheet 05, Fig. A-FCGAB Sheet 06, Fig. A-FCGAB Sheet 07

- The supplementary kit 538096A02S02 includes:

7	Nut	ASNA2532-7	Item 10
2	Nut	ASNA2531-7	Item 11
16	Nut	ASNA2532-8	Item 13
2	Nut	ASNA2531-6	Item 15
	with		
27	Washer	NSA5372-716AX	
	and/or		
27	Washer	NSA5372-716BX	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

		and/or	
	27	Washer	NSA5372-716CX
		and/or	
	27	Washer	NSA5372-716DX
		and/or	
I	27	Washer	NSA5372-716EX
I		- The suppl	ementary kit 538096A02S03 includes:
		NOTE:	The additional kit is valid for operators which have ordered Kit 571140A02R03 and have not accomplished this Service Bulletin yet.
I	2	Washer	NSA5372-616AX
I		and/or	
I	2	Washer	NSA5372-616BX
I		and/or	
I	2	Washer	NSA5372-616CX
I		and/or	
I	2	Washer	NSA5372-616DX
I		and/or	
I	2	Washer	NSA5372-616EX
I		and	
I	16	Washer	NSA5372-816AX
I		and/or	
I	16	Washer	NSA5372-816BX
I		and/or	
I	16	Washer	NSA5372-816CX
I		and/or	
I	16	Washer	NSA5372-816DX
I		and/or	
I	16	Washer	NSA5372-816EX
		NOTE:	Install the washer in accordance with the definition of the washer

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

thickness given in the Fig. A-FCCAA Sheet 01.

NOTE: If necessary, the installation of the three washers is approved in this

condition.

NOTE: Torque the nuts between 3.80daN and 4.60daN (342lbf.in. and

411lbf.in.).

NOTE: Inside the wing center box, apply on the nuts:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1

As required

For Polysulfide

Sealant

# (3) Subtask 571140-833-007-002 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the LH Side, ADDITIONAL WORK

Work Zones and Access Panels			
	Zone Access/Work location		
From	141	Access	Panel 147AZ
		Work location	Rib 1
То	540	Access	Panel 540AB, Panel 540BZ
		Work location	Rib 1

Manpower Resources			
Manhours	6.00		
Minimum number of person	2		
Subtask elapsed time	3.00		
Skills	AIRFRAME NON DESTRUCTIVE TESTING		

#### Material necessary to do the job

Suppl	Supplementary kit 571140A02S02			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
60	EN6115T2-3	14	BOLT	
61	ASNA2536-2	17	NUT	
62	EN6115T2-2	3	BOLT	
65	NAS1149D0332K	8	WASHER	

Comp	Component COMPA04				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES	
11	ASNA2531-7	2	NUT		
34	ABS1418K8-19	4	SCREW		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
35	ASNA2532-8	7	NUT	
37	ABS1418K8-26	1	SCREW	
43	ABS1418K8-25	1	SCREW	
44	ASNA2531-8	2	NUIT	
73	ABS1418K9-15	2	SCREW	
74	ABS1418K9-16	8	SCREW	
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	9	WASHER	
	NSA5372-816BX	9	WASHER	
	NSA5372-816EX	9	WASHER	
	NSA5372-916AX	16	WASHER	
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

NOTE: The quantities given in the component table are for all the taperloks

replacement.

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

0	0				
	umable CMLA01				
ITEM	DESCRIPTION	REFERENCE TO	QTY PER A/C	SEE	
		CML MAT. No.		NOTES	
	Wash Primer - Structure	04CMA2	As required		
	Primer Polyurethane Paint -	04EAC2	As required		
	Corrosion Inhibiting				
	Top Coat Polyurethane -	04JAA3	As required		
	External Structure				
	Polysulfide Sealant-General	06AAA1	As required		
	Purpose Brushable				
	Polysulfide Sealant-Fuel	06ABB1	As required		
	Tank Fillet				
	Adhesion Promoter-For	06PAG1	As required		
	Polysulfide Sealant				

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Kit tool 571140T02R00				
ITEM	PART N°	KEYWORD	QTY	SEE NOTES
	98D57103002000	Test	1	

Ref	References			
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001			
Drawing	R57102001			
Non Destructive Test Manual (NTM)	51-10-01 PART 6			
Structural Repair Manual (SRM)	51-24-00 51-42-11 51-43-00			
Fig. A-FCDAA Definition of the Washer Thickness for the New Taperlok	Sheet 01			
Fig. A-FDAAA Removal/Installation of the Cooling Duct	Sheet 01			
Fig. A-FDBAA Removal/Installation of the Belly Fairing Structure	Sheet 01 Sheet 02 Sheet 03			
Fig. A-FCFAB LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK	Sheet 01 Sheet 02 Sheet 03 Sheet 04 Sheet 05 Sheet 06 Sheet 07			

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCFAB Sheet 01 to Fig. A-FCFAB Sheet 07

- (a) Depending on the result of the inspection, remove for access :
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1	Duct	Item (53)	Retain
1	Duct	Item (52)	Retain
	attached with		
1	Clamp	Item (63)	Retain
8	Screw	Item (64)	Retain

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

8		Washer	Item (65)	Discard	
		Remove the structure of the belly fairing.			
		Refer t	Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03		
1		Channel-Fo	rmed Item (51)	Retain	
		attache	ed with		
3		Rivet	Item (62)	Discard	
7		Rivet	Item (60)	Discard	
10		Bush	Item (61)	Discard	
		and/or			
1		Web 4 assy	Item (50)	Retain	
		attache	ed with		
7		Rivet	Item (60)	Discard	
7		Bush	Item (61)	Discard	
	(b)	In accordance with the result of the inspection, remove the taperlok(s) :			
		Refer to Fig. A-FCFAB Sheet 01 to Fig. A-FCFAB Sheet 04			
4		Screw	Item (7)	Discard	
1		Screw	Item (14)	Discard	
1		Screw	Item (12)	Discard	
2		Screw	Item (70)	Discard	
8		Screw	Item (71)	Discard	
6		Screw	Item (72)	Discard	
2		Screw	Item (77)	Discard	
2		Screw	Item (79)	Discard	
1		Screw	Item (81)	Discard	
		NOTE:	The nuts are removed during the inspecti	on.	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- (c) Do a rototest inspection of the holes for cracks, refer to NTM 51-10-01 PART 6.
  - 1 If cracks are found, contact AIRBUS before any further work.
  - 2 If no crack is found, do the following steps.
- (d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

NOTE: To prevent any accidental damage, we recommend to train to oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCFAB Sheet 01, Fig. A-FCFAB Sheet 02, Fig. A-FCFAB Sheet 05, Fig. A-FCFAB Sheet 06, Fig. A-FCFAB Sheet 07

4	Screw	ABS1418K8-19	Item 34
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		
7	Nut	ASNA2532-8	Item 35
	and if necessary		
7	Washer	NSA5372-816AX	
	and/or		
7	Washer	NSA5372-816EX	
	and/or		
7	Washer	NSA5372-816BX	
	and		
1	Screw	ABS1418K8-25	Item 43
1	Screw	ABS1418K8-26	Item 37
	with		
2	Nut	ASNA2531-8	Item 44
	and if necessary		
2	Washer	NSA5372-816AX	

DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 162

5

### SERVICE BULLETIN

	and/or		
2	Washer	NSA5372-816EX	
	and/or		
2	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K9-15	Item 73
8	Screw	ABS1418K9-16	Item 74
6	Screw	ABS1418K9-17	Item 75
	with		
16	Nut	ASNA2532-9	Item 76
	and if necess	sary	
16	Washer	NSA5372-916AX	
	and/or		
16	Washer	NSA5372-916EX	
	and/or		
16	Washer	NSA5372-916BX	
	and		
2	Screw	ABS1418K7-23	Item 80
	with		
2	Nut	ASNA2531-7	Item 11
	and if necess	sary	
2	Washer	NSA5372-716AX	
	and/or		
2	Washer	NSA5372-716EX	
	and/or		
2	Washer	NSA5372-716BX	
	NOTE:	Install the screw in accordanthe repair instruction R5710	nce with the installation principle given in 2001.
	NOTE:		sher in accordance with the definition of in the Fig. A-FCDAA Sheet 01.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

NOTE: Wet assembly, apply:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

NOTE: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

<u>NOTE</u>: Inside the wing center box, apply on the nuts :

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

(f) If removed, install:

1 The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

1	Channel-Formed	Item (51)	Retained at removal
	with		

7	Bolt	EN611512-3	Item 60
3	Bolt	EN6115T2-2	Item 62
10	Nut	ASNA2536-2	Item 61

and/or

1 Web 4 assy Item (50) Retained at

removal

attached with

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

7 Bolt EN6115T2-3 Item 60

7 Nut ASNA2536-2 Item 61

> NOTE: Apply to the interface of the structure and all the parts:

Polysulfide Sealant- 06AAA1

As required

Item 65

General Purpose

Brushable

Washer

8

2 The cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1	Duct	Item (53)	Retained at removal
1	Duct	Item (52)	Retained at removal
	with		
1	Clamp	Item (63)	Retained at removal
8	Screw	Item (64)	Retained at removal

### (4) Subtask 571140-833-008-002 - Replace the Taperlok with the Next Nominal Diameter Taperlok on the RH Side, ADDITIONAL WORK

NAS1149D0332K

	Work Zones and Access Panels				
	Zone Access/Work location				
From	142	Access	Panel 148AZ		
		Work location	Rib 1		
То	640	Access	Panel 640AB, Panel 640BZ		
		Work location	Rib 1		

5 SERVICE BULLETIN No.: A320-57-1140 DATE: Nov 21/06

### SERVICE BULLETIN

Manpower Resources

Manhours 6.00

Minimum number of person 2

Subtask elapsed time 3.00

Skills AIRFRAME
NON DESTRUCTIVE
TESTING

### Material necessary to do the job

Suppl	Supplementary kit 571140A02S02					
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES		
60	EN6115T2-3	14	BOLT			
61	ASNA2536-2	17	NUT			
62	EN6115T2-2	3	BOLT			
65	NAS1149D0332K	8	WASHER			

Comp	onent COMPA04			
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
11	ASNA2531-7	2	NUT	
34	ABS1418K8-19	4	SCREW	
35	ASNA2532-8	7	NUT	
37	ABS1418K8-26	1	SCREW	
43	ABS1418K8-25	1	SCREW	
44	ASNA2531-8	2	NUIT	
73	ABS1418K9-15	2	SCREW	
74	ABS1418K9-16	8	SCREW	
75	ABS1418K9-17	6	SCREW	
76	ASNA2532-9	16	NUT	
78	ABS1418K8-20	2	SCREW	
80	ABS1418K7-23	2	SCREW	
82	ABS1418K8-22	1	SCREW	
	NSA5372-716AX	2	WASHER	
	NSA5372-716BX	2	WASHER	
	NSA5372-716EX	2	WASHER	
	NSA5372-816AX	9	WASHER	
	NSA5372-816BX	9	WASHER	
	NSA5372-816EX	9	WASHER	
	NSA5372-916AX	16	WASHER	
	NSA5372-916BX	16	WASHER	
	NSA5372-916EX	16	WASHER	

<u>NOTE</u>: The quantities given in the component table are for all the taperloks replacement.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

NOTE: The above list of components is not an AIRBUS Kit, the required parts

shall be ordered as necessary through the given channel.

NOTE: The components listed above are only necessary if Repair Task. The

quantity of these items are to be ordered as required.

Consi	Consumable CMLA01				
ITEM	DESCRIPTION	REFERENCE TO CML MAT. No.	QTY PER A/C	SEE NOTES	
	Wash Primer - Structure	04CMA2	As required		
	Primer Polyurethane Paint - Corrosion Inhibiting	04EAC2	As required		
	Top Coat Polyurethane - External Structure	04JAA3	As required		
	Polysulfide Sealant-General Purpose Brushable	06AAA1	As required		
	Polysulfide Sealant-Fuel Tank Fillet	06ABB1	As required		
	Adhesion Promoter-For Polysulfide Sealant	06PAG1	As required		

Kit to	Kit tool 571140T02R00					
ITEM	PART N°	KEYWORD	QTY	SEE NOTES		
	98D57103002000	Test	1			

Ref	References			
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001			
Drawing	R57102001			
Non Destructive Test Manual (NTM)	51-10-01 PART 6			
Structural Repair Manual (SRM)	51-24-00			
	51-42-11			
	51-43-00			
Fig. A-FCDAA	Sheet 01			
Definition of the Washer Thickness for				
the New Taperlok				
Fig. A-FDAAA	Sheet 01			
Removal/Installation of the Cooling Duct				
Fig. A-FDBAA	Sheet 01			
Removal/Installation of the Belly Fairing	Sheet 02			
Structure	Sheet 03			
Fig. A-FCGAB	Sheet 01			
RH Side, Replacement of the Lower	Sheet 02			
Panel Fasteners for the ADDITIONAL	Sheet 03			
WORK	Sheet 04			
	Sheet 05			
	Sheet 06			
	Sheet 07			

In accordance with SRM 51-42-11, SRM 51-43-00 and SRM 51-24-00.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

Refer to AMM Task 20-21-11-911-001.

Refer to NTM 51-10-01 PART 6

Refer to Fig. A-FCGAB Sheet 01 to Fig. A-FCGAB Sheet 07

- (a) Depending on the result of the inspection, remove for access :
  - 1 Remove the cooling duct.

Refer to Fig. A-FDAAA Sheet 01

1		Duct		Item (54)	Retain
1		Du	et	Item (52)	Retain
			attached with		
1		Cla	mp	Item (63)	Retain
8		Scr	rew	Item (64)	Retain
8		Wa	sher	Item (65)	Discard
		<u>2</u>	Remove the structure of the belly fairing		
			Refer to Fig. A-FDBAA Sheet 01 to Fig.	A-FDBAA Sh	<u>eet 03</u>
1		Cha	annel-Formed	Item (171)	Retain
			attached with		
3		Riv	et	Item (62)	Discard
7		Riv	et	Item (60)	Discard
10		Bus	sh	Item (61)	Discard
			and/or		
1		We	b 4 assy	Item (170)	Retain
			attached with		
7		Riv	et	Item (60)	Discard
7		Bus	sh	Item (61)	Discard
	(b)	In a	accordance with the result of the inspectio	n, remove the	taperlok(s):

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

Refer to Fig. A-FCGAB Sheet 01 to Fig. A-FCGAB Sheet 04

### SERVICE BULLETIN

ew	Item (7)	Discard
ew	Item (14)	Discard
ew	Item (12)	Discard
ew	Item (70)	Discard
ew	Item (71)	Discard
ew	Item (72)	Discard
ew	Item (77)	Discard
ew	Item (79)	Discard
ew	Item (81)	Discard
	ew ew ew ew ew ew	ew Item (14) ew Item (12) ew Item (70) ew Item (71) ew Item (72) ew Item (77) ew Item (77)

NOTE: The nuts are removed during the inspection.

- (c) Do a rototest inspection of the holes for cracks refer to NTM 51-10-01 PART 6.
  - 1 If cracks are found, contact AIRBUS before any further work.
  - If no crack is found, do the following steps.
- (d) Oversize the hole to the next nominal diameter in accordance with the drilling procedure given in the Repair Instruction Drawing R57102001 and use the drilling tool SOA-TL-R57102001B.

NOTE: To prevent any accidental damage, we recommend to train to oversize the taperlok holes on the test specimen.

98D57103002000 Test specimen 1

(e) Depending on the removal, install:

Refer to Fig. A-FCGAB Sheet 01, Fig. A-FCGAB Sheet 02, Fig. A-FCGAB Sheet 05, Fig. A-FCGAB Sheet 06, Fig. A-FCGAB Sheet 07

4	Screw	ABS1418K8-19	Item 34
2	Screw	ABS1418K8-20	Item 78
1	Screw	ABS1418K8-22	Item 82
	with		
7	Nut	ASNA2532-8	Item 35
	and if necessary		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

7	Washer	NSA5372-816AX	
	and/or		
7	Washer	NSA5372-816EX	
	and/or		
7	Washer	NSA5372-816BX	
	and		
1	Screw	ABS1418K8-25	Item 43
1	Screw	ABS1418K8-26	Item 37
	with		
2	Nut	ASNA2531-8	Item 44
	and if necessary		
2	Washer	NSA5372-816AX	
	and/or		
2	Washer	NSA5372-816EX	
	and/or		
2	Washer	NSA5372-816BX	
	and		
2	Screw	ABS1418K9-15	Item 73
8	Screw	ABS1418K9-16	Item 74
6	Screw	ABS1418K9-17	Item 75
	with		
16	Nut	ASNA2532-9	Item 76
	and if necessary		
16	Washer	NSA5372-916AX	
	and/or		
16	Washer	NSA5372-916EX	
	and/or		
16	Washer	NSA5372-916BX	
	and		

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

2 Screw ABS1418K7-23 Item 80

with

2 Nut ASNA2531-7 Item 11

and if necessary

2 Washer NSA5372-716AX

and/or

2 Washer NSA5372-716EX

and/or

2 Washer NSA5372-716BX

NOTE: Install the screw in accordance with the installation principle given in

the repair instruction R57102001.

NOTE: If necessary, install the washer in accordance with the definition of

the washer thickness given in the Fig. A-FCDAA Sheet 01.

NOTE: Wet assembly, apply:

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

NOTE: Torque the nuts between 5.60daN and 6.70daN (493lbf.in. and

592lbf.in.).

NOTE: Outside the wing center box, apply on the screws :

Primer 04EAC2 As required

Polyurethane Paint

- Corrosion Inhibiting

Wash Primer - 04CMA2 As required

Structure

Top Coat 04JAA3 As required

Polyurethane -External Structure

<u>NOTE</u>: Inside the wing center box, apply on the nuts :

Polysulfide Sealant- 06ABB1 As required

Fuel Tank Fillet

Adhesion Promoter- 06PAG1 As required

For Polysulfide

Sealant

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

(f)	If removed,	install	:
-----	-------------	---------	---

1 The structure of the belly fairing

Refer to Fig. A-FDBAA Sheet 01 to Fig. A-FDBAA Sheet 03

1	Channel-Formed		Item (171)	Retained at removal
	with			
7	Bolt	EN6115T2-3	Item 60	
3	Bolt	EN6115T2-2	Item 62	
10	Nut	ASNA2536-2	Item 61	
	and/or			
1	Web 4 assy		Item (170)	Retained at removal
	attached with	1		
7	Bolt	EN6115T2-3	Item 60	
7	Nut	ASNA2536-2	Item 61	
	NOTE:	Apply to the interface o	f the structure	and all the parts:
	Polysulfide Sealant General Purpose Brushable	t- 06AAA1 As	s required	
	2 The cooling	duct.		
	Refer to Fig.	A-FDAAA Sheet 01		
1	Duct		Item (54)	Retained at removal
1	Duct		Item (52)	Retained at removal
	with			
1	Clamp		Item (63)	Retained at removal
8	Screw		Item (64)	Retained at
				removal

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL

### D. TEST

#### \*\*CONF 001

### (1) Subtask 571140-710-002-001 - Test

Manpower Resources	
Skills	NON SPECIFIC

	3-1
ŀ	References
Aircraft Maintenance Manual (AMM)	Task 20-28-00-720-005
	Task 20-28-00-869-002
	Task 28-11-00-280-002
	Task 28-21-00-710-006
	Task 57-17-11-400-001
	Task 57-27-11-400-001

NOTE:

This test procedure is to be accomplished after the installation of the parts removed for the access SUBTASK 571137-410-003 001 Install/Close Items Removed/Opened for Access on the LH Side, SUBTASK 571137-410-004 001 Install/Close Items Removed/Opened for Access on the RH Side, SUBTASK 571137-410-007 001 Install the Fuel Strainer, LH Side and SUBTASK 571137-410-008 001 Install the Fuel Strainer, RH Side.

### (a) Job Set-up:

- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.

### (b) Test:

- <u>1</u> Do the test procedure as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- <u>2</u> Do the test procedure as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.
- Do a fuel tanks leak checks (only leak test of the center tank or/and leak test of the wing tanks - without fuel - by the local blowing procedure), refer to AMM Task 28-11-00-280-002.

NOTE: Do this test on the taperlok bolts inspected by this Service Bulletin.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

4 For all the access panels and covers removed during the preparation procedure, do a check of the electrical bonding (external metal surfaces/parts (hinges or fixed)) refer to AMM Task 20-28-00-720-005.

NOTE:

For the maximum permitted resistance values : refer to the table AMM Task 20-28-00-869-002.

#### \*\*CONF 002

#### (1) Subtask 571140-710-002-001 - Test

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 20-28-00-720-005	
	Task 20-28-00-869-002	
	Task 28-11-00-280-002	
	Task 28-21-00-710-006	
	Task 57-17-11-400-001	
	Task 57-27-11-400-001	

NOTE:

This test procedure is to be accomplished after the installation of the parts removed for the access SUBTASK 571137-410-003 001 Install/Close Items Removed/Opened for Access on the LH Side, SUBTASK 571137-410-004 001 Install/Close Items Removed/Opened for Access on the RH Side, SUBTASK 571137-410-007 001 Install the Fuel Strainer, LH Side and SUBTASK 571137-410-008 001 Install the Fuel Strainer, RH Side.

### (a) Job Set-up:

- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- Remove the safety clips and tags and close the circuit breakers as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.

### (b) Test:

- <u>1</u> Do the test procedure as specified after the installation of the access covers 147AZ and 148AZ, refer to AMM Task 57-17-11-400-001.
- Do the test procedure as specified after the installation of the access panels 540AB and 640AB, refer to AMM Task 57-27-11-400-001.
- On a fuel tanks leak checks (only leak test of the center tank or/and leak test of the wing tanks without fuel by the local blowing procedure), refer to AMM Task 28-11-00-280-002.

NOTE: Do this test on the taperlok bolts inspected by this Service

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

Bulletin.

4 For all the access panels and covers removed during the preparation procedure, do a check of the electrical bonding (external metal surfaces/parts (hinges or fixed)) refer to AMM Task 20-28-00-720-005.

NOTE:

For the maximum permitted resistance values : refer to the table AMM Task 20-28-00-869-002.

### \*\*CONF ALL

### E. CLOSE-UP

### \*\*CONF 001

(1) Subtask 571140-410-003-001 - Install/Close Items Removed/Opened for Access on the LH Side

	Manpower Res	ources
Skills		NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-002 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 540BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 540AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 147AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

# (2) Subtask 571140-410-004-001 - Install/Close Items Removed/Opened for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-002 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 640BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 640AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 148AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels, 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.

### (3) Subtask 571140-410-007-001 - Install the Fuel Retainer, LH Side

Manpower Resources	
Skills	NON SPECIFIC

### Material necessary to do the job

Suppl	Supplementary kit 571140A01S02			
ITEM	NEW PART N°	QTY (UM)		SEE NOTES
69	NAS1149F0332P	2	WASHER	

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References		
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: The parts removed for the access must be installed before the

SUBTASK 571137-700-002 001 Testing.

NOTE: This step is only valid for aircraft on which Service Bulletin No.

A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for LH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly	Item (55)	Retained at removal
1	Strainer Assembly	Item (57)	Retained at removal
	with		
8	Bolt	Item (66)	Retained at removal
2	Bolt	Item (67)	Retained at removal
2	Bolt	Item (68)	Retained at removal

### (4) Subtask 571140-410-008-001 - Install the Fuel Retainer, RH Side

2

Washer

Manpower Resources	
Skills	NON SPECIFIC

NAS1149F0332P

Item 69

### Material necessary to do the job

Supplementary kit 571140A01S02				
ITEM	NEW PART N°	QTY (UM)	KEYWORD	SEE NOTES
69	NAS1149F0332P	2	WASHER	

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References		
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: The parts removed for the access must be installed before the

SUBTASK 571137-700-002 001 Testing.

NOTE: This step is only valid for aircraft on which Service Bulletin No.

A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for RH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly		Item (56)	Retained at removal
1	Strainer Assembly		Item (58)	Retained at removal
	with			
8	Bolt		Item (66)	Retained at removal
2	Bolt		Item (67)	Retained at removal
2	Bolt		Item (68)	Retained at removal
2	Washer	NAS1149F0332P	Item 69	

### (5) Subtask 571140-942-002-001 - Close-up

Manpower Resources	
Skills	NON SPECIFIC

	References
Aircraft Maintenance Manual (AMM)	Task 28-25-00-650-001
	Task 32-12-00-410-001

- (a) Refuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (b) Refuel the center tank, refer to AMM Task 28-25-00-650-001.
  - (c) Close the main landing gear doors, refer to AMM Task 32-12-00-410-001.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

- (d) Remove the access platform(s).
- (e) Put the aircraft back to its initial configuration.

### \*\*CONF 002

(1) Subtask 571140-410-003-001 - Install/Close Items Removed/Opened for Access on the LH Side

Manpower Resources	
Skills	NON SPECIFIC

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-002 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 6QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 540BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 540AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 147AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels 191LB and 147CB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.
- (2) Subtask 571140-410-004-001 Install/Close Items Removed/Opened for Access on the RH Side

Manpower Resources	
Skills	NON SPECIFIC

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

References		
Aircraft Maintenance Manual (AMM)	Task 28-21-42-400-001 Task 28-21-54-400-001 Task 53-35-11-400-001 Task 57-17-11-400-001 Task 57-27-11-400-001 Task 57-27-12-400-001	
Fig. A-FDCAA Removal/Installation of the Fuel Pump Strainer Covers	Sheet 01	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-002 001 Testing.

- (a) Make sure that the work areas are clean and clear of tools and other items of equipment.
- (b) Install the covers Item (80) and (81) of the fuel pump strainer FIN 8QM, refer to Fig. A-FDCAA Sheet 01 and AMM Task 28-21-54-400-001.
- (c) Install the fuel pump suction valve, refer to AMM Task 28-21-42-400-001.
- (d) Close the fuel surge access door 640BZ, refer to AMM Task 57-27-12-400-001.
- (e) Install the wing access panel 640AB, refer to AMM Task 57-27-11-400-001.
- (f) Install the access cover 148AZ, refer to AMM Task 57-17-11-400-001.
- (g) If removed, install the panels, 192LB and 148DB on the wing to fuselage, refer to AMM Task 53-35-11-400-001.

### (3) Subtask 571140-410-007-002 - Install the Fuel Retainer, LH Side

Manp	power Resources
Skills	NON SPECIFIC

### Material necessary to do the job

Suppl	ementary kit 571140A02S02	2		
ITEM	NEW PART N°	QTY (UM)		SEE NOTES
69	NAS1149F0332P	2	WASHER	

References		
Aircraft Maintenance Manual (AMM) Task 20-21-11-911-001		
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-002 001 Testing.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

NOTE: This step is only valid for aircraft on which Service Bulletin No. A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for LH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly		Item (55)	Retained at removal
1	Strainer Assembly		Item (57)	Retained at removal
	with			
8	Bolt		Item (66)	Retained at removal
2	Bolt		Item (67)	Retained at removal
2	Bolt		Item (68)	Retained at removal
2	Washer	NAS1149F0332P	Item 69	

### (4) Subtask 571140-410-008-002 - Install the Fuel Retainer, RH Side

	Manpower Resources
Skills	NON SPECIFIC

### Material necessary to do the job

Suppl	ementary kit 571140A02S02	2		
ITEM	NEW PART N°	QTY (UM)		SEE NOTES
69	NAS1149F0332P	2	WASHER	

References		
Aircraft Maintenance Manual (AMM)	Task 20-21-11-911-001	
Structural Repair Manual (SRM)	51-42-11	
Fig. A-FDDAA	Sheet 01	
Removal/Installation of the Fuel Strainer	Sheet 02	

NOTE: The parts removed for the access must be installed before the SUBTASK 571137-700-002 001 Testing.

NOTE: This step is only valid for aircraft on which Service Bulletin No.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

A320-28-1149 (or Modification No. 36387J2487) is accomplished.

(a) If removed, install the fuel retainer for RH side:

Refer to Fig. A-FDDAA Sheet 01 and Fig. A-FDDAA Sheet 02

In accordance with SRM 51-42-11.

Refer to AMM Task 20-21-11-911-001.

1	Strainer Assembly		Item (56)	Retained at removal
1	Strainer Assembly		Item (58)	Retained at removal
	with			
8	Bolt		Item (66)	Retained at removal
2	Bolt		Item (67)	Retained at removal
2	Bolt		Item (68)	Retained at removal
2	Washer	NAS1149F0332P	Item 69	

### (5) Subtask 571140-942-002-001 - Close-up

Manpower Resources	
Skills	NON SPECIFIC


Refe	erences
Aircraft Maintenance Manual (AMM)	Task 28-25-00-650-001
	Task 32-12-00-410-001

- (a) Refuel the LH and RH wing tanks, refer to AMM Task 28-25-00-650-001.
- (b) Refuel the center tank, refer to AMM Task 28-25-00-650-001.
  - (c) Close the main landing gear doors, refer to AMM Task 32-12-00-410-001.
  - (d) Remove the access platform(s).
  - (e) Put the aircraft back to its initial configuration.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL




N\_SB\_571140\_5\_BAAA\_01\_00

Figure A-FBAAA - Sheet 01 Inspection of the Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL



### NOTE:

- + FASTENER NOT AFFECTED.
- FASTENER TO BE REMOVED.


N\_SB\_571140\_5\_BAAA\_02\_01

Figure A-FBAAA - Sheet 02 Inspection of the Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL



### NOTE:

- + FASTENER NOT AFFECTED.
- FASTENER TO BE REMOVED.

N\_SB\_571140\_5\_BAAA\_03\_01

Figure A-FBAAA - Sheet 03 Inspection of the Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

#### \*\*CONF 001




Figure A-FFAAA - Sheet 01 Flow Chart

N\_SB\_571140\_5\_FAAA\_01\_04

DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140 5

#### SERVICE BUILLETIN

#### \*\*CONF 002




Figure A-FFAAB - Sheet 01 Flow Chart


N\_SB\_571140\_5\_FAAB\_01\_02

DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140 5

SERVICE BULLETIN

\*\*CONF ALL

### THREAD DAMAGE



### NOTE:

01 FOR MORE INFORMATION OF THE CRITERION MARKS REFER TO THE BOOKLET 06-0009 N\_SB\_571140\_5\_BCAA\_01\_00

Figure A-FBCAA - Sheet 01 Thread Damage

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN





Figure A-FCAAA - Sheet 01 LH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL



### NOTE:

+ FASTENERS NOT AFFECTED.


N\_SB\_571140\_5\_CAAA\_02\_02

Figure A-FCAAA - Sheet 02 LH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL



### NOTE:

+ FASTENERS NOT AFFECTED.

N\_SB\_571140\_5\_CAAA\_03\_02

Figure A-FCAAA - Sheet 03 LH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL





Figure A-FCAAA - Sheet 04 LH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL





HOLE	NEW ITEM		
•	10	OR	33 35
•	10	OR	38 35
$\ominus$	10	OR	34 35
$\oplus$	10	OR	32 35
•	13	OR	75 76
$\bigcirc$	13	OR	74 76

#### NOTE:

+ FASTENERS NOT AFFECTED.

FOR THE INSTALLATION OF THE FASTENERS, DO A CHECK OF THE WASHER THICKNESS, REFER TO FIG. A-FCCAA OR FIG. A-FCDAA.

IF YOU REPLACE ONLY THE NUT, TORQUE THE

NUT TO BETWEEN 3.80 daN AND 4.60 daN (342 lbf.in AND 411 lbf.in).

IF YOU REPLACE THE NUT AND THE SCREW,

TORQUE THE NUT TO BETWEEN 5.60 daN AND 6.70 daN

(493 lbf.in AND 592 lbf.in).

N\_SB\_571140\_5\_CAAA\_05\_01

Figure A-FCAAA - Sheet 05 LH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL





Figure A-FCAAA - Sheet 06 LH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov. 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL



### NOTE:

- 01 APPLY MATERIAL No 06ABB1 AND MATERIAL No 06PAG1 ON THE NUTS.
- 02 APPLY MATERIAL No 04EAC2, MATERIAL No 04CMA2 AND MATERIAL No 04JAA3 ON THE BOLTS.
- 03 WET ASSEMBLY, APPLY MATERIAL No 06ABB1.


N\_SB\_571140\_5\_CAAA\_07\_01

Figure A-FCAAA - Sheet 07 LH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL




N\_SB\_571140\_5\_CBAA\_01\_00

Figure A-FCBAA - Sheet 01 RH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL



### NOTE:

+ FASTENERS NOT AFFECTED.


N\_SB\_571140\_5\_CBAA\_02\_01

Figure A-FCBAA - Sheet 02 RH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL



### NOTE:

+ FASTENERS NOT AFFECTED.

N\_SB\_571140\_5\_CBAA\_03\_01

Figure A-FCBAA - Sheet 03 RH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL





Figure A-FCBAA - Sheet 04 RH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL



FOR THE INSTALLATION OF THE FASTENERS, DO A CHECK OF THE WASHER THICKNESS, REFER TO FIG. A–FCCAA OR FIG. A–FCDAA.

IF YOU REPLACE ONLY THE NUT, TORQUE THE

NUT TO BETWEEN 3.80 daN AND 4.60 daN (342 lbf.in AND 411 lbf.in).

IF YOU REPLACE THE NUT AND THE SCREW,

TORQUE THE NUT TO BETWEEN 5.60 daN AND 6.70 daN

(493 lbf.in AND 592 lbf.in).


N\_SB\_571140\_5\_CBAA\_05\_01

Figure A-FCBAA - Sheet 05 RH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL



N\_SB\_571140\_5\_CBAA\_06\_01

Figure A-FCBAA - Sheet 06 RH Side, Replacement of the Lower Panel Fasteners


TORQUE THE NUT TO BETWEEN 5.60 daN AND 6.70 daN

(493 lbf.in AND 592 lbf.in).

5 DATE: Nov. 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL



#### NOTE:

- 01 APPLY MATERIAL No 06AAB1 AND MATERIAL No 06PAG1 ON THE NUTS.
- 02 APPLY MATERIAL No 04EAC2, MATERIAL No 04CAA2 AND MATERIAL No 04JAA3 ON THE BOLTS.
- 03 WET ASSEMBLY, APPLY MATERIAL No 06ABB1.

N\_SB\_571140\_5\_CBAA\_07\_01


Figure A-FCBAA - Sheet 07 RH Side, Replacement of the Lower Panel Fasteners

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL

# DEFINITION OF THE WASHER THICKNESS FOR THE ORIGINAL TAPERLOK



#### NOTE:

D: TAPERLOK LENGTH PROTRUDING BEYOND THE PLATE.

R: THICKNESS OF WASHER REQUIRED.

N\_SB\_571140\_5\_CCAA\_01\_01

Figure A-FCCAA - Sheet 01
Definition of the Washer Thickness for the Original Taperlok

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

\*\*CONF ALL

DIAMETER CODE No	D MIN	D		R		WASHERS THICKNESSES CODES	EXAMPLE	REMARKS
		mm	in	mm	in	CODES		
		≥ 12.6	0.496	0.80	0.031	A		IF "D" < 10.06 mm (0.397 in)
	10.06 mm (0.397 in)	≥ 13	0.512	1.20	0.047	E		INSTALL ABS1418 NEXT LENGHT CODE
		≥ 13.4	0.528	1.60	0.063	В	IF "D" ≽ 13.80 mm (0.543 in) INSTALL THE WASHERS NSA5372-616AX + NSA5372-616EX	IF "D" < 12.28 mm (0.484 in) NO WASHER TO INSTALL
		≥ 13.8	0.543	2	0.079	A+E		
		≥ 14.2	0.560	2.40	0.094	С		
		≥ 14.6	0.575	2.80	0.110	E+B		
		≥ 15	0.590	3.20	0.126	D		
6		≥ 15.4	0.606	3.60	0.142	E+C		
		≥ 15.8	0.622	4	0.157	B+C		
		≥ 16.2	0.638	4.40	0.173	E+D		
		≥ 16.6	0.653	4.80	0.189	B+D		
		≥ 17	0.669	5.20	0.205	E+B+C		
		≥ 17.4	0.685	5.60	0.220	C+D		
		≥ 17.8	0.701	6	0.236	E+B+D		
		≥ 18.2	0.716	6.40	0.252	D+D		
		≥ 18.6	0.732	6.80	0.268	E+C+D		

N\_SB\_571140\_5\_CCAA\_02\_01

Figure A-FCCAA - Sheet 02 Definition of the Washer Thickness for the Original Taperlok

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL

### VALID FOR ASNA2531 AND ASNA2532 NUT

DIAMETER	D MIN	D		R		WASHERS	EVANDI FO	DEMARKS
CODE No	DIVIIN	mm	in	mm	in	THICKNESSES CODES	EXAMPLES	REMARKS
		≥ 13.5	0.531	0.80	0.031	Α		IF "D" < 11.25 mm (0.443 in) INSTALL ABS1418 NEXT LENGHT CODE
		≥ 13.9	0.547	1.20	0.047	E		
		≥ 14.3	0.563	1.60	0.063	В		
		≥ 14.8	0.583	2	0.079	A+E		
		≥ 15.1	0.594	2.40	0.094	С		
		≥ 15.5	0.610	2.80	0.110	E+B		
		≥ 15.9	0.626	3.20	0.126	D		
	11 05	≥ 16.3		3.60	0.142	E+C	IF "D" ≥ 15.50 mm (0.610 in)	
7	11.25 mm (0.443 in)	≥ 16.8		4	0.157	B+C	INSTALL THE WASHERS	IF "D" < 13.46 mm (0.530 in)
			0.673		0.173	E+D	NSA5372-716EX + NSA5372-716BX	NO WASHER TO INSTALL
			0.689		0.189	B+D		
		≥ 17.9			0.205	E+B+C		
		≥ 18.3			0.220	C+D		
		≥ 18.7		6	0.236	E+B+D		
		≥ 19.1			0.252	D+D		
		≥ 19.5			0.268	E+C+D		
		≥ 19.9			0.283	C+C+C		
		≥ 14.3			0.031	A		IF "D" < 12.07 mm (0.476 in) INSTALL ABS1418 NEXT LENGHT CODE
		≥ 14.8			0.047	E		
		≥ 15.1			0.063	В	IF "D" ≥ 16.30 mm (0.642 in)	
		≥ 15.5		2	0.079	A+E		
		≥ 15.9 ≥ 16.3			0.094	C E+B		IF "D" < 14.27 mm (0.562 in) NO WASHER TO INSTALL
		≥ 16.3 ≥ 16.8			0.110	D		
	12.07 mm (0.476 in)	≥ 10.6 ≥ 17.1			0.120	E+C		
8		≥ 17.1		4	0.142	B+C	INSTALL THE WASHERS	
	,	≥ 17.3 ≥ 17.9			0.137	E+D	NSA5372-816EX + NSA5372-816BX	
		≥ 17.3			0.170	B+D		
		≥ 18.7			0.205	E+B+C		
	- -		0.752	5.60	0.220	C+D		
		≥ 19.5		6	0.236	E+B+D		
		≥ 19.9			0.252	D+D		
		≥ 20.3			0.268	E+C+D		

#### NOTE:

IF NECESSARY, THE INSTALLATION OF THREE WASHERS IS APPROVED IN THIS CONDITION.

Figure A-FCCAA - Sheet 03
Definition of the Washer Thickness for the Original Taperlok

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 205


Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.


N\_SB\_571140\_5\_CCAA\_03\_01


SERVICE BULLETIN

### \*\*CONF ALL

### **DEFINITION OF THE WASHER THICKNESS** FOR THE NEW TAPERLOK







DIAMETER CODE No	D MIN	D		R		WASHERS THICKNESSES	EXAMPLES	REMARKS
		mm	in	mm	in	CODES		
		≥14.20	0.559	0.8	0.031	Α	IF "D" ≥ 14.20 mm (0.559 in) INSTALL THE WASHER NSA5372-716AX	BETWEEN 12.50 mm (0.493 in) AND 14.20 mm (0.559 in) NO WASHER TO INSTALL
7	12.50 mm (0.493 in)	≥14.60	0.574	1.2	0.047	E		
		≥15	0.590	1.6	0.063	В		
	13.52 mm (0.533 in)	≥15.30	0.602	0.8	0.031	Α	IF "D" ≥ 15.70 mm (0.618 in) INSTALL THE WASHER NSA5372-816EX	BETWEEN 13.52 mm (0.533 in) AND 15.30 mm (0.602 in) NO WASHER TO INSTALL
8		≥15.70	0.618	1.2	0.047	E		
		≥16.10	0.633	1.6	0.063	В		
9	15.42 mm (0.608 in)	≥17.30	0.681	0.8	0.031	Α	IF "D" ≥ 18.10 mm (0.712 in) INSTALL THE WASHER	BETWEEN 15.42 mm (0.608 in) AND 17.29 mm (0.680 in)
		≥17.70	0.696	1.2	0.047	E		
		≥18.10	0.712	1.6	0.063	В	NSA5372-916BX	NO WASHER TO INSTALL

D: TAPERLOK LENGTH PROTRUDING BEYOND THE PLATE.
R: THICKNESS OF WASHER REQUIRED.

LT: LENGTH OF THE REPAIR TAPERLOK.

TH: TOTAL THICKNESS.

BEFORE INSTALLATION OF THE NEW TAPERLOK, YOU MUST CALCULATE THE "D" VALUE: D = LT - TH.

TABLE ONLY VALID FOR THE OPTIONAL ABS1418 TAPERLOK.

IF THE LENGTH OF THE ABS1418 TAPERLOK IS CORRECTLY MEASURED,

THE INSTALLATION OF THE WASHER IS NOT REQUIRED.

IF THE LENGTH OF THE ABS1418 IS LESS THAN "D MIN" INSTALL THE NEXT LENGTH CODE OF FASTENER.

Figure A-FCDAA - Sheet 01 Definition of the Washer Thickness for the New Taperlok

DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140


REVISION No.: 03 - Apr 19/19 Page: 206

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

N\_SB\_571140\_5\_CDAA\_01\_01

SERVICE BULLETIN

### \*\*CONF ALL




N\_SB\_571140\_5\_DAAA\_01\_01


Figure A-FDAAA - Sheet 01 Removal/Installation of the Cooling Duct


5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL








N\_SB\_571140\_5\_DBAA\_01\_01


Figure A-FDBAA - Sheet 01
Removal/Installation of the Belly Fairing Structure

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL






HOLE	OLD ITEM	NEW ITEM
•	(60) (61)	60 61
-	(62) (61)	62 61

#### NOTE:

APPLY MAT. No. 06AAA1 TO THE INTERFACES OF THE PARTS




N\_SB\_571140\_5\_DBAA\_02\_00

Figure A-FDBAA - Sheet 02 Removal/Installation of the Belly Fairing Structure

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF ALL



01 DEPENDING ON AIRCRAFT CONFIGURATION


N\_SB\_571140\_5\_DBAA\_03\_00


Figure A-FDBAA - Sheet 03 Removal/Installation of the Belly Fairing Structure

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL






N\_SB\_571140\_5\_DCAA\_01\_01


Figure A-FDCAA - Sheet 01
Removal/Installation of the Fuel Pump Strainer Covers

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL







N\_SB\_571140\_5\_DDAA\_01\_01

Figure A-FDDAA - Sheet 01
Removal/Installation of the Fuel Strainer

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF ALL





Figure A-FDDAA - Sheet 02 Removal/Installation of the Fuel Strainer

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 001




N\_SB\_571140\_5\_CEAA\_01\_00

Figure A-FCEAA - Sheet 01
Inspection of the Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 001



#### NOTE:

- + FASTENER NOT AFFECTED.
- FASTENER TO BE REMOVED.


N\_SB\_571140\_5\_CEAA\_02\_01

Figure A-FCEAA - Sheet 02
Inspection of the Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 001



#### NOTE:

- + FASTENER NOT AFFECTED.
- FASTENER TO BE REMOVED.


N\_SB\_571140\_5\_CEAA\_03\_01

Figure A-FCEAA - Sheet 03
Inspection of the Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 002




N\_SB\_571140\_5\_CEAB\_01\_00

Figure A-FCEAB - Sheet 01
Inspection of the Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 002



#### NOTE:

- + FASTENER NOT AFFECTED.
- FASTENER TO BE REMOVED.


N\_SB\_571140\_5\_CEAB\_02\_01

Figure A-FCEAB - Sheet 02 Inspection of the Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 002



#### NOTE:

- + FASTENER NOT AFFECTED.
- FASTENER TO BE REMOVED.

N\_SB\_571140\_5\_CEAB\_03\_01

Figure A-FCEAB - Sheet 03
Inspection of the Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

#### \*\*CONF 001




Figure A-FFBAA - Sheet 01
Flow Chart for the ADDITIONAL WORK

N\_SB\_571140\_5\_FBAA\_01\_04

OR COMPLIANCE TIMES GIVEN IN THIS SERVICE BULLETIN.

5 DATE: Nov. 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BUILLETIN

#### \*\*CONF 002




Figure A-FFBAB - Sheet 01 Flow Chart for the ADDITIONAL WORK

N\_SB\_571140\_5\_FBAB\_01\_04

DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140 5

SERVICE BULLETIN





Figure A-FCFAA - Sheet 01 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 001



### NOTE:

+ FASTENERS NOT AFFECTED.


N\_SB\_571140\_5\_CFAA\_02\_01

Figure A-FCFAA - Sheet 02 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 001



	ı
HOLE	OLD ITEM
•	(10) OR (3) (10)
•	(13) OR (72) (13)
$\ominus$	(13) OR (71) (13)



#### NOTE:

+ FASTENERS NOT AFFECTED.

N\_SB\_571140\_5\_CFAA\_03\_01

Figure A-FCFAA - Sheet 03 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 001





Figure A-FCFAA - Sheet 04 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 001



#### NOTE:

+ FASTENERS NOT AFFECTED.

FOR THE INSTALLATION OF THE FASTENERS, DO A CHECK OF THE WASHER THICKNESS, REFER TO FIG. A–FCCAA OR FIG. A–FCDAA.

IF YOU REPLACE ONLY THE NUT, TORQUE THE

NUT TO BETWEEN 3.80 daN AND 4.60 daN (342 lbf.in AND 411 lbf.in).

IF YOU REPLACE THE NUT AND THE SCREW,

TORQUE THE NUT TO BETWEEN 5.60 daN AND 6.70 daN

(493 lbf.in AND 592 lbf.in).

N\_SB\_571140\_5\_CFAA\_05\_01

Figure A-FCFAA - Sheet 05 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 001





Figure A-FCFAA - Sheet 06 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 001



### NOTE:

- 01 APPLY MATERIAL No 06ABB1 AND MATERIAL No 06PAG1 ON THE NUTS.
- 02 APPLY MATERIAL No 04EAC2, MATERIAL No 04CMA2 AND MATERIAL No 04JAA3 ON THE BOLTS.
- 03 WET ASSEMBLY, APPLY MATERIAL No 06ABB1.

N\_SB\_571140\_5\_CFAA\_07\_01

Figure A-FCFAA - Sheet 07 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN





Figure A-FCFAB - Sheet 01 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

### \*\*CONF 002



### NOTE:

+ FASTENERS NOT AFFECTED.


N\_SB\_571140\_5\_CFAB\_02\_01

Figure A-FCFAB - Sheet 02 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 002





HOLE	OLD ITEM		
•	(13) OR (72)		
•	(13) OR (71) (13)		

#### NOTE:

+ FASTENERS NOT AFFECTED.

N\_SB\_571140\_5\_CFAB\_03\_01

Figure A-FCFAB - Sheet 03 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 002





Figure A-FCFAB - Sheet 04 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 002



#### NOTE:

+ FASTENERS NOT AFFECTED.

FOR THE INSTALLATION OF THE FASTENERS, DO A CHECK OF THE WASHER THICKNESS, REFER TO FIG. A-FCCAA OR FIG. A-FCDAA.

IF YOU REPLACE ONLY THE NUT, TORQUE THE

NUT TO BETWEEN 3.80 daN AND 4.60 daN (342 lbf.in AND 411 lbf.in).

IF YOU REPLACE THE NUT AND THE SCREW,

TORQUE THE NUT TO BETWEEN 5.60 daN AND 6.70 daN

(493 lbf.in AND 592 lbf.in).

N\_SB\_571140\_5\_CFAB\_05\_01

Figure A-FCFAB - Sheet 05 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 002





Figure A-FCFAB - Sheet 06 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN

### \*\*CONF 002



### NOTE:

- 01 APPLY MATERIAL No 06ABB1 AND MATERIAL No 06PAG1 ON THE NUTS.
- 02 APPLY MATERIAL No 04EAC2, MATERIAL No 04CMA2 AND MATERIAL No 04JAA3 ON THE BOLTS.
- 03 WET ASSEMBLY, APPLY MATERIAL No 06ABB1.

N\_SB\_571140\_5\_CFAB\_07\_01

Figure A-FCFAB - Sheet 07 LH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN





Figure A-FCGAA - Sheet 01 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

#### \*\*CONF 001



### NOTE:

+ FASTENERS NOT AFFECTED.


N\_SB\_571140\_5\_CGAA\_02\_01

Figure A-FCGAA - Sheet 02 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 001



#### NOTE:

+ FASTENERS NOT AFFECTED.

N\_SB\_571140\_5\_CGAA\_03\_01

Figure A-FCGAA - Sheet 03 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 001





Figure A-FCGAA - Sheet 04
RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 001



#### NOTE:

+ FASTENERS NOT AFFECTED.

FOR THE INSTALLATION OF THE FASTENERS, DO A CHECK OF THE WASHER THICKNESS, REFER TO FIG. A–FCCAA OR FIG. A–FCDAA.

IF YOU REPLACE ONLY THE NUT, TORQUE THE

NUT TO BETWEEN 3.80 daN AND 4.60 daN (342 lbf.in AND 411 lbf.in).

IF YOU REPLACE THE NUT AND THE SCREW,

TORQUE THE NUT TO BETWEEN 5.60 daN AND 6.70 daN

(493 lbf.in AND 592 lbf.in).

N\_SB\_571140\_5\_CGAA\_05\_01

Figure A-FCGAA - Sheet 05 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 001





Figure A-FCGAA - Sheet 06 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

#### \*\*CONF 001



#### NOTE:

- 01 APPLY MATERIAL No 06AAB1 AND MATERIAL No 06PAG1 ON THE NUTS.
- 02 APPLY MATERIAL No 04EAC2, MATERIAL No 04CAA2 AND MATERIAL No 04JAA3 ON THE BOLTS.
- 03 WET ASSEMBLY, APPLY MATERIAL No 06ABB1.

N\_SB\_571140\_5\_CGAA\_07\_01

Figure A-FCGAA - Sheet 07 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN





Figure A-FCGAB - Sheet 01 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

#### \*\*CONF 002



### NOTE:

+ FASTENERS NOT AFFECTED.


N\_SB\_571140\_5\_CGAB\_02\_01

Figure A-FCGAB - Sheet 02 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

#### \*\*CONF 002





HOLE	OLD ITEM		
•	(13) OR (72)		
	(13) OR (71)		

#### NOTE:

+ FASTENERS NOT AFFECTED.

N\_SB\_571140\_5\_CGAB\_03\_01

Figure A-FCGAB - Sheet 03 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 002





Figure A-FCGAB - Sheet 04
RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 002



#### NOTE:

+ FASTENERS NOT AFFECTED.

FOR THE INSTALLATION OF THE FASTENERS, DO A CHECK OF THE WASHER THICKNESS, REFER TO FIG. A–FCCAA OR FIG. A–FCDAA.

IF YOU REPLACE ONLY THE NUT, TORQUE THE

NUT TO BETWEEN 3.80 daN AND 4.60 daN (342 lbf.in AND 411 lbf.in).

IF YOU REPLACE THE NUT AND THE SCREW,

TORQUE THE NUT TO BETWEEN 5.60 daN AND 6.70 daN (493 lbf.in AND 592 lbf.in).

Figure A-FCGAB - Sheet 05 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

N\_SB\_571140\_5\_CGAB\_05\_01

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 002





Figure A-FCGAB - Sheet 06 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN

#### \*\*CONF 002



#### NOTE:

- 01 APPLY MATERIAL No 06ABB1 AND MATERIAL No 06PAG1 ON THE NUTS.
- 02 APPLY MATERIAL No 04EAC2, MATERIAL No 04CMA2 AND MATERIAL No 04JAA3 ON THE BOLTS.
- 03 WET ASSEMBLY, APPLY MATERIAL No 06ABB1.

N\_SB\_571140\_5\_CGAB\_07\_01

Figure A-FCGAB - Sheet 07 RH Side, Replacement of the Lower Panel Fasteners for the ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN

This Page Intentionally Left Blank

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

# SERVICE BULLETIN APPENDIX 01 - Weight Variant (WV) correspondence table

### \*\*CONF ALL

### (1) Weight Variant (WV) correspondence table

SERIES	AIRCRAFT MODEL	WEIGHT VARIANT (WV)	ASSOCIATED MODIFICATION	ASSOCIATED SERVICE BULLETIN
A320-200	A320-211	000		
	A320-212	001	20966	SB A320-00-1002
	A320-231	002	21601	
		003	22269	SB A320-00-1006
		004	21532	
		005	21711	
		006	22436	
		007	23264	SB A320-00-1013
		008	23900	SB A320-00-1030
		009	23900 , 22269	SB A320-00-1006 OR SB A320-00-1030
		010	23900 , 23264	SB A320-00-1013 OR SB A320-00-1030
		011	30307	SB A320-00-1077
		012	30479	SB A320-00-1069 OR SB A320-00-1227
		013	31132	SB A320-00-1060
		014	31385	SB A320-00-1063

SERIES	AIRCRAFT MODEL	WEIGHT VARIANT (WV)	ASSOCIATED MODIFICATION	ASSOCIATED SERVICE BULLETIN
A320-200	A320-214	000		
	A320-232	002	21601	
	A320-233	003	22269	SB A320-00-1006
		007	23264	SB A320-00-1013
		800	23900	SB A320-00-1030
		009	23900 , 22269	SB A320-00-1006 OR SB A320-00-1030
		010	23900 , 23264	SB A320-00-1013 OR SB A320-00-1030
		011	30307	SB A320-00-1077
		012	30479	SB A320-00-1069
		013	31132	SB A320-00-1060
		014	31385	SB A320-00-1063
		015	34047	SB A320-00-1126
		016	34094	SB A320-00-1143

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

SERVICE BULLETIN
APPENDIX 01 - Weight Variant (WV) correspondence table

This Page Intentionally Left Blank

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

#### SERVICE BULLETIN APPENDIX 02 - Elapsed Time Assumption

### \*\*CONF ALL

The following chart is only a proposal. Operators may determine that another way to do the work is more suitable for them.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN APPENDIX 02 - Elapsed Time Assumption


\*\*CONF ALL

MH: MANHOURS

PER: NUMBER OF PERSONS ET/S: ELAPSED TIME PER STEP

### ELAPSED TIME ASSUMPTION SERVICE BULLETIN No A320-57-1140





#### NOTE:

01) THIS CHART IS ONLY A PROPOSAL.
OPERATORS MAY DETERMINE THAT ANOTHER WAY
TO DO THE WORK IS MORE SUITABLE FOR THEM

02 IF A VSB IS INVOLVED, THE ASSOCIATED MANHOURS ARE NOT REFLECTED IN THIS GANTT CHART

Figure A-FABAA - Sheet 01 Elapsed Time Assumption Inspection Task

N\_SB\_571140\_5\_ABAA\_01\_00

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN APPENDIX 02 - Elapsed Time Assumption


\*\*CONF ALL

MH: MANHOURS

PER: NUMBER OF PERSONS ET/S: ELAPSED TIME PER STEP

### **ELAPSED TIME ASSUMPTION SERVICE BULLETIN No A320-57-1140**





### NOTE:

OT THIS CHART IS ONLY A PROPOSAL
OPERATORS MAY DETERMINE THAT ANOTHER WAY
TO DO THE WORK IS MORE SUITABLE FOR THEM

02 IF A VSB IS INVOLVED, THE ASSOCIATED MANHOURS ARE NOT REFLECTED IN THIS GANTT CHART

Figure A-FACAA - Sheet 01 Elapsed Time Assumption Repair Task

DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 3

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

N\_SB\_571140\_5\_ACAA\_01\_00

SERVICE BULLETIN APPENDIX 02 - Elapsed Time Assumption

This Page Intentionally Left Blank

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

# SERVICE BULLETIN APPENDIX 03 - Elapsed Time Assumption (ADDITIONAL WORK)

### \*\*CONF ALL

The following chart is only a proposal. Operators may determine that another way to do the work is more suitable for them.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

# SERVICE BULLETIN APPENDIX 03 - Elapsed Time Assumption (ADDITIONAL WORK)


\*\*CONF 001

MH: MANHOURS

PER: NUMBER OF PERSONS ET/S: ELAPSED TIME PER STEP

### ELAPSED TIME ASSUMPTION SERVICE BULLETIN No A320-57-1140





#### NOTE:

01 THIS CHART IS ONLY A PROPOSAL.
OPERATORS MAY DETERMINE THAT ANOTHER WAY
TO DO THE WORK IS MORE SUITABLE FOR THEM

02 IF A VSB IS INVOLVED, THE ASSOCIATED MANHOURS ARE NOT REFLECTED IN THIS GANTT CHART

Figure A-FADAA - Sheet 01
Elapsed Time Assumption Inspection Task for ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 2

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

N\_SB\_571140\_5\_ADAA\_01\_00

# SERVICE BULLETIN APPENDIX 03 - Elapsed Time Assumption (ADDITIONAL WORK)

#### \*\*CONF 002




Figure A-FADAB - Sheet 01
Elapsed Time Assumption Inspection Task for ADDITIONAL WORK

5 DATE: Nov. 21/06 SERVICE BULLETIN No.: A320-57-1140

# SERVICE BULLETIN APPENDIX 03 - Elapsed Time Assumption (ADDITIONAL WORK)


\*\*CONF 001

MH: MANHOURS

PER: NUMBER OF PERSONS ET/S: ELAPSED TIME PER STEP

### ELAPSED TIME ASSUMPTION SERVICE BULLETIN No A320-57-1140





### NOTE:

O1 THIS CHART IS ONLY A PROPOSAL
OPERATORS MAY DETERMINE THAT ANOTHER WAY
TO DO THE WORK IS MORE SUITABLE FOR THEM

02 IF A VSB IS INVOLVED, THE ASSOCIATED MANHOURS ARE NOT REFLECTED IN THIS GANTT CHART

N\_SB\_571140\_5\_AEAA\_01\_00

Figure A-FAEAA - Sheet 01
Elapsed Time Assumption Repair Task for ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 4

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

# SERVICE BULLETIN APPENDIX 03 - Elapsed Time Assumption (ADDITIONAL WORK)


\*\*CONF 002

MH: MANHOURS

PER: NUMBER OF PERSONS ET/S: ELAPSED TIME PER STEP

### ELAPSED TIME ASSUMPTION SERVICE BULLETIN No A320-57-1140





### NOTE:

O1 THIS CHART IS ONLY A PROPOSAL
OPERATORS MAY DETERMINE THAT ANOTHER WAY
TO DO THE WORK IS MORE SUITABLE FOR THEM

02 IF A VSB IS INVOLVED, THE ASSOCIATED MANHOURS ARE NOT REFLECTED IN THIS GANTT CHART

N\_SB\_571140\_5\_AEAB\_01\_00

Figure A-FAEAB - Sheet 01
Elapsed Time Assumption Repair Task for ADDITIONAL WORK

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

REVISION No.: 03 - Apr 19/19 Page: 5

Printed in FRANCE © AIRBUS S.A.S. 2007. All rights reserved.

### SERVICE BULLETIN APPENDIX 04 - Inspection Report

### \*\*CONF ALL

The results of the inspection, including no findings, replacement or actions to be done, must be uploaded in accordance with ISI 00.00.00179 using the on-line reporting application.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

### SERVICE BULLETIN APPENDIX 04 - Inspection Report

### \*\*CONF ALL

INSPECTION REPORT							
SERVICE B	ULLETIN No: A320	-57-1140					
	A/C MSN :			UPLOAD THE COMPLETED INSPECTION REPORT SHEET IN ACCORDANCE WITH ISI 00.00.00179			
FLIG	HT CYCLES :						
FLIC	GHT HOURS :						
DATE OF I	NSPECTION :						
		S NO D					
INSPECTIO	ON METHOD : D	ETAILED NSPECTION					
	CENTER WING BOX						
		DOES T	HE GAGE FIT AND	MOVE?			
		YES		□ NO			
SIDE	THREAD NOT DAMAGED	THREAD DAMAGED	THREAD MARKS FOUND	THREAD NOT DAMAGED	THREAD DAMAGED		
LH							
RH							
OUTER WING BOX							
			HE GAGE FIT AND				
		YES		□ NO			
SIDE	THREAD DAMAGED	THREAD NOT DAMAGED	THREAD MARKS FOUND	THREAD DAMAGED	THREAD NOT DAMAGED		
LH							
RH							
PLEASE PRECISE OTHER FINDINGS:							

N\_SB\_571140\_5\_AAAA\_01\_01

Figure A-FAAAA - Sheet 01 Inspection Report

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN Service Bulletin REPORTING

TITLE: WINGS - GENERAL - ONE TIME INSPECTION OF TAPERLOK BOLT AT WING TO FUSELAGE JUNCTION.

MODIFICATION No.: None

#### **SB Reporting status**

This Service Bulletin will only be incorporated into affected customized Maintenance and Flight Operations Products if it is duly reported to Airbus.

#### **General information**

The SB Reporting policy is published in ISI 00.00.00135. This document provides information regarding: the SB Reporting means and benefits, the update of customized Maintenance Products and customized Flight Operations Products.

If this Service Bulletin has an operational impact, refer to paragraph "Flight Operations Products" for further information on the update of affected Flight Operations Products.

#### SB Reporting procedure

Standard practice to report SB is to use the online reporting application on AirbusWorld.

Refer to ISI 00.00.00179:

- For complete information on reporting means to Airbus. Question 2 "What are the standard practices for SB reporting?"
- If this SB requires previous or simultaneous accomplishment of other SBs, Question 3 "What about the reporting of prerequisite Service Bulletin?"

NOTE: ISI 00.00.00179 covers all the frequently asked questions about SB Reporting. It is revised on a regular basis.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140

## SERVICE BULLETIN QUALITY PERCEPTION FORM

Use this form to tell us what is your perception of the quality of this Service Bulletin. The reported data that you provide us will be used to analyse areas of difficulties and to take corrective action to further improve the quality of our Service Bulletins.

We thank you for the time you have taken in completing this form.

(Please rate on a scale of 1 to 4, with 4 being the highest score)

- Quality rating of this SB	4	3	2	1
- Quality rating of the Accomplishment Instructions	4	3	2	1
- Quality rating of the Illustrations	4	3	2	1
- Is this SB easy to understand ?	Y / N			

If you have had difficulties in the accomplishment of this SB please quote below the area(s) and give a short description of the issue.

	Planning		Material		Instructions		
Χ	Effectivity	Χ	Kit content	Χ	Preparation		
Χ	Reason	Χ	List of Materials Operator Supplied	Χ	Mod/Inspection		
Χ	Manpower	Χ	Industry support	Χ	Test		
Χ	References	Χ	Re-identification	Χ	Close-Up		
Χ	Publication	Χ	Tooling	Χ	Illustrations		
<u>Co</u>	mments:						
Operator:					Date:		
Name/Title:							
Please return this form to:							
AIRBUS CUSTOMER SERVICES DIRECTORATE							

Attn: SEM4 Service Bulletins Management

FAX: (33) 5 61 93 42 51

1 Rond Point Maurice Bellonte 31707 BLAGNAC CEDEX FRANCE

Or via your Resident Customer Support Office.

5 DATE: Nov 21/06 SERVICE BULLETIN No.: A320-57-1140